

# Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541  
Tel : 64817221

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120

Vehicle No : SLS 4109 C  
Make/Model : Toyota C-HR  
Year : 2017

*Not Authored*

*Runway BY party*

*4 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate cost of repair

1 pc	Rear o/s door assy	<i>By</i> \$1,218.50	✓
1 pc	Rear o/s door protector	<i>Mr</i> \$376.10	✓
1 pc	Rear o/s door frame black sticker	<i>Mr</i> \$134.50	✓
1 pc	Rear o/s door inner trim board	<i>Mr</i> \$455.70	X
1 pc	Rear o/s door glass regulator	\$185.10	?
1 pc	Rear o/s door glass regulator motor	\$485.70	?
1 pc	Rear o/s door inner lock	<i>R</i> \$305.10	X
1 pc	Rear o/s door rubber	\$185.90	?
1 pc	Front o/s door protector	<i>CM</i> \$397.10	✓
1 pc	Front o/s door frame black sticker	<i>Mr</i> \$134.50	X
1 pc	Rear o/s fender arch garnish	<i>Not by</i> \$255.10	✓
1 pc	Rear lower bumper	<i>Cur</i> \$685.70	✓
1 pc	O/S locker panel garnish	<i>Not</i> \$655.70	✓
1 pc	Rear o/s shock absorber	\$497.80	?
1 pc	Rear o/s lower arm	\$497.80	?
1 pc	Rear o/s kunckle arm	\$847.60	?
1 pc	Rear o/s kunckle bearing	\$205.10	?
1 pc	Rear o/s trailing arm	\$255.60	?
1 pc	Rear o/s hub assy	\$455.60	?
		\$8,234.20	
		Less 25 %	\$2,058.55
			\$6,175.65

## S Nett

1 pc Rear n/s tyre rim  
20 pcs Clip

*Not* \$450.00 ✓  
\$2.50 *Mr* \$50.00 ✓  
\$500.00

balance c/f \$6,675.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLS 4109 C

balance b/f \$6,675.65

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 4001

To putty and spray paint

\$800.00 4001

Check & reconnect wiring.

\$45.00 201

To respray anti-rust proofing treatment

\$120.00 301

Remove/refit rear tail-gate mechanism to new door.

\$150.00 601

Remove/renew rear o/s undercarriages.

\$450.00 ?

Check and realign wheel alignment.

\$60.00 ✓

Total

\$9,100.65