

TP AIG (IN)

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

type.

Vehicle Insured : SBV 9933 J
Accident Date : 01-Dec-2019

No. : 30900

Date : 03-Dec-2019

Our Ref : 190723 (AIG) / QUEK

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

83443.04

Not Withheld
Reserve B4pam

6day

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT (2019) SMN3599S

- 1 pc rear bumper
- 1 pc o/s rear bumper side retainer
- 10 pcs rear bumper clips @ S\$ 3.50
- 1 pc rear bumper lower garnish -centre
- 1 pc o/s rear bumper lower side garnish
- 1 pc o/s rear bumper inner shield
- 1 pc o/s taillamp
- 1 pc o/s taillamp panel
- 1 pc o/s rear fender
- 1 pc o/s rear fender lower inner grille
- 1 pc rear end panel
- 1 pc o/s rear rim
- 1 pc o/s rear shock absorber
- 1 pc o/s rear wheel bearing
- 1 pc rear axle

B1/cm 492.70 ✓
Cm 15.00 ✓
Rn 35.00 ✓
n, 68.30 ✓
Cm 48.70 ✓
Tn 33.10 ✓
m/cm 223.90 ✓
Bn 75.30 ✓
Bu 559.30 ✓
Cm 26.00 ✓
Bn 314.00 ✓
Sn 418.40 X
Sn 212.90 X
Rn 287.50 X
Sn 911.00 X

3,721.10
Less 20% : -744.22

2,976.88

- 1 pc rear bumper "L" Plate
- 1 pc rear bumper "L" plate bracket
- 1 pc o/s rear fender top glass sealant
- 1 pc o/s rear fender top glass damping seal
- 1 pc o/s rear tyre

Sn 80.00 sn X
Ri 30.00 sn ✓
Rn 40.00 sn 30sn
Rn 20.00 sn ✓
Sn 280.00 sn X

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : SBV 9933 J

Our Ref : 190723

Page : 2

No. : 30900

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	800	900.00
To focus taillamps. To check rear wiring and lighting operation.	20	50.00
To remove and refit rear windscreen glass and conduct water leak test	✓	120.00
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	100	120.00
To dismantle and check rear under-carriage. To replace affected portions.	NN	240.00 X
To conduct rear wheel alignment test.	60	100.00
To putty and respray on affected portions.	75	900.00
Total :		S\$ 5,856.88

Singapore Dollars Five Thousand Eight Hundred and Fifty Six and Cents Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1891.30
-20%

1513.04 s/Parts
80.00 SN
+ 1850.00 Labour

3443.04 ✓ ok