

W. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司
160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30900

Date : 03-Dec-2019

PAGE : 1

Vehicle Insured : SBV 9933 J
Accident Date : 01-Dec-2019

Our Ref : 190723 (AIG) / QUEK

BUKIT BATOK DRIVING CENTRE LTD
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT (2019) SMN3599S

- 1 pc rear bumper
- 1 pc o/s rear bumper side retainer
- 10 pcs rear bumper clips
- 1 pc rear bumper lower garnish
- 1 pc o/s rear bumper lower side
- 1 pc o/s rear bumper inner shield
- 1 pc o/s taillamp
- 1 pc o/s taillamp panel
- 1 pc o/s rear fender
- 1 pc o/s rear fender lower inner
- 1 pc grille
- 1 pc rear end panel
- 1 pc o/s rear rim
- 1 pc o/s rear shock absorber
- 1 pc o/s rear wheel bearing
- 1 pc rear axle

BT/CM 492.70 ✓
CM 15.00 ✓
@ S\$ 3.50 35.00 ✓
1 68.30 ✓
CM 48.70 ✓
T 33.10 ✓
NN 223.90 7 ✓
NN 75.30 7 ✓
Bu 559.30 ✓
CM 26.00 ✓
R 314.00 ✓
Bu 418.40 X
NN 212.90 7 ✓
NN 287.50 7 ✓
NN 911.00 7 ✓
3,721.10
Less 20% : -744.22

2,976.88

- 1 pc rear bumper "L" Plate
- 1 pc rear bumper "L" plate bracket
- 1 pc o/s rear fender top glass
- 1 pc sealant
- 1 pc o/s rear fender top glass
- 1 pc damping seal
- 1 pc o/s rear tyre

R 80.00 sn ✓
1 30.00 sn ✓
R 40.00 sn 30sn ✓
R 20.00 sn ✓
NN X 280.00 sn 7

Con't Page 2 ...

W. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SBV 9933 J
Our Ref : 190723

Page : 2
No. : 30900

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800
900.00

To focus taillamps. To check rear
wiring and lighting operation.

50.00 201

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

1001
120.00

To dismantle and check rear under-
carriage. To replace affected
portions.

x NN 240.00 ?

To conduct rear wheel alignment
test.

100.00 601

To putty and respray on affected
portions.

900.00 7501

Total : S\$ 5,856.88
=====

Singapore Dollars Five Thousand Eight Hundred
and Fifty Six and Cents Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1891.30
-20%

1513.04 s/Parts
80.00 SW
+ 1850.00 Labour

3443.04