

PAIG (N)



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhinh.com.sg

No. : 30900

Vehicle Insured : SBV 9933 J
Accident Date : 01-Dec-2019

Date : 03-Dec-2019

Our Ref : 190723 (AIG) / QUEK

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

Not Notified
Resurvey before painting

6 days

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT (2019) SMN3599S

1 pc rear bumper	BT/CM 492.70	✓
1 pc o/s rear bumper side retainer	CM 15.00	✓
10 pcs rear bumper clips	@ S\$ 3.50 35.00	✓
1 pc rear bumper lower garnish	BT 68.30	✓
-centre		
1 pc o/s rear bumper lower side	CM 48.70	✓
garnish		
1 pc o/s rear bumper inner shield	T 33.10	✓
1 pc o/s taillamp	223.90	?
1 pc o/s taillamp panel	75.30	?
1 pc o/s rear fender	Bu 559.30	✓
1 pc o/s rear fender lower inner	CM 26.00	✓
grille		
1 pc rear end panel	B 314.00	✓
1 pc o/s rear rim	sn 418.40	X
1 pc o/s rear shock absorber	212.90	?
1 pc o/s rear wheel bearing	287.50	?
1 pc rear axle	911.00	?

3,721.10
Less 20% : -744.22
2,976.88

1 pc rear bumper "L" Plate	sn 80.00	sn X
1 pc rear bumper "L" plate bracket	BT 30.00	sn ✓
1 pc o/s rear fender top glass	BT 40.00	sn 30.00
sealant		
1 pc o/s rear fender top glass	BT 20.00	sn ✓
damping seal		
1 pc o/s rear tyre	280.00	sn ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SBV 9933 J
Our Ref : 190723

Page : 2
No. : 30900

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800
900.00

To focus taillamps. To check rear
wiring and lighting operation.

50.00 200

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

100
120.00

To dismantle and check rear under-
carriage. To replace affected
portions.

240.00 ?

To conduct rear wheel alignment
test.

100.00 600

To putty and respray on affected
portions.

900.00 750

Total : S\$ 5,856.88
=====

Singapore Dollars Five Thousand Eight Hundred
and Fifty Six and Cents Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.