

ASS. RAC. BY:

REF: CS/LPC 19021308/UT f303

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Gerald Poh

of

LPC

Date/Time: 3.12.19 14.30p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 4770D

Insured:

at Workshop m/s Kan Fook Sing

Tel:

67479660

of NO 61 De fu Lane 12

Policy No: Z119/VC 00/105076

Claim No: 19/19/19/VC 00/022707

Sum Insured:

Excess: \$1000.00

Make of Veh:

D.O.A. 27.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

R.O.D. Endorsement:

Date/Time: 3.12.19 2.42p.m.

Person Contacted:

Alice

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XD 4770D-X

5/12-16:30 Seek mandate for approval menmen

5/12-17.46- Chew Beng Kee authorize repair.

5/12-9:28am Inform workshop via email authorize repair excess 1k

ASS. REF. BY:

REF:

Lpc CS/LPC1902/308/UTf3

ASSIGNMENT

From:

Date:

5.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 4770D

at Workshop m/s Ken Fnt Sing

of NO 61 Bfu Lane 12

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: \$1000-00

(Client's Record)

Make of Veh: Before 12p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

25k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA (REV) REP. / 24 HRS

385

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

XD 4770D

Yr Regn:

7 11

Type: M.Car / M.Cycle / Bns / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make:

HIND FSIETKA

C.C. 12913

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

277219

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHDFSIETKXX12137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goldencrown

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

27/11/19

D.O.I.

5/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19.12.2019

see 18-7-2019 LRA 4693

13/1/20

confirmed 1/5 @ 4000 with MR Tan.
(Red: 13/10/15; 31%)

RECEIVED 14 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Pop. Form:

Lump Sum / F.B. / F.C.

4000

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Wheel end (\$

Survey Fee:

290

Transportation

S + RS: 34

Photos

Other:

11

TOTAL

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2019 Sendback Est	03 Dec 2019 14:22 S\$1,330.00	03 Dec 2019 14:30 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CHIP ENG SENG CONTRACTORS (1988) PTE LTD, Co. Reg. No.: 198802355C		
Vehicle Reg. No.:	XD4770D	Date of Loss:	27/11/2019 10:00 - :59 [100 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 19/19/19/VC00/022707	Policy/Cover Note No.:	Z/19/VC00/105076 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2019]		
Driver/Custodian:	MUHAMMAD NA'EEM BIN IBRAHIM (31 / Male), NRIC: S8847061C, Tel: +6591193815 Email: NOEMAIL		
Adj Asg. Remarks:	SURVEY & REVERT. PARTS PRICING ARE NOT AVAILABLE YET		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 6 December 2019 9:28 AM
To: 'mttan@kanfs.net'
Cc: SUR
Subject: XD 4770D / OD / LPC / DOA: 27/11/2019
Attachments: estimate.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle XD 4770D (Excess \$1,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

XD4770D (19/19/19/VC00/022707)
OD
Nov 27 2019 10:00AM
[CHIP ENG SENG CONTRACTORS (1988) PTE LTD]
Kan Fook Sing Motor Workshop

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 05/12/2019 17:46 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4763.30) - XD4770D - Claim Handler: Gerald Poh

Approved:4763.30.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 05 Dec 2019

Preliminary Advice

Vehicle No	: XD4770D	Accident Date	: 27/11/2019
Make	: HINO FS1ETKA	Policy No.	: Z/19/VC00/105076
Assignment Date	: 03/12/2019	Excess	: S\$1,000.00
Date of Inspection	: 05/12/2019	Est. Duration of Repair	: 3.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,819.73
Revised Amount	:S\$	4,763.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,763.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,693.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,307.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 05 Dec 2019

Preliminary Advice

Vehicle No	: XD4770D	Accident Date	: 27/11/2019
Make	: HINO FS1ETKA	Policy No.	: Z/19/VC00/105076
Assignment Date	: 03/12/2019	Excess	: S\$1,000.00
Date of Inspection	: 05/12/2019	Est. Duration of Repair	: 3.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,810.15
Revised Amount	:S\$	4,734.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,734.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,693.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,307.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Front Bumper Top Grille, pending part price

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum


**RECYCLE
RIGHT**

Care for our environment


**National
Environment
Agency**

© National Environment Agency 2018

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Newly Resprayed In Original Pearl White. Tip Top.



Will Trade Or Swap With Other Car.

Direct Owner StarAd


**Lake View
Credit Pte Ltd**

> Low prices guaranteed
> Specialist in Japanese cars
> Easy loan application
> All terms are clearly stated

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category ▾

Sort by Date Posted ▾

10 vehicles

hino fs1

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	hino fs1		Any	Any	Any	Any	Any	Any
	Hino FS1ELKM Tipper (COE till 11/2022)		\$43,800	\$14,820 /yr	19-Nov-2007	12,913 cc	-	Truck
	Fuel Type: Diesel Hino 700 Series Tipper Truck. Suitable For Most Of The Heavy Duty Work. Fuel Efficiency, Wear/Tear Replaced, 100% Loan Available, High Trade In. Call Us To View This Magnificent Vehicle.							
	ARWIN (1994) Pte Ltd Posted: 04-Dec-2019 Tags: 2007 Hino FS1ELKM, 2007 hino fs1elkm, Hino FS1ELKM, hino fs1elkm, Hino, FS1ELKM, fs1elkm, Used Hino							
	Hino FS1ETKA		\$58,800	\$29,240 /yr	09-Dec-2011	12,913 cc	-	Truck
	Fuel Type: Diesel Rare 20FT Hook Lift! Excellent Engine Condition! Hook Lift Warranty! 100% Loan Available. Easy Approval. High-Value Trade In For Your Vehicle. Done Up With Full Servicing And Doll Up With New Paintwork To Serve Her New Owner. 100% Bank/In House Loan Available With...							
	Bell Auto Pte Ltd Posted: 03-Dec-2019 Tags: 2011 Hino FS1ETKA, 2011 hino fs1etka, Hino FS1ETKA, hino fs1etka, Hino, FS1ETKA, fs1etka, Used Hino							
	Hino FS1ETLA		\$80,800	\$22,270 /yr	22-Jul-2013	12,913 cc	-	Truck
	Fuel Type: Diesel Excellent Engine Condition. 6 Months Warranty. 100% Loan Available. Easy Approval. High-Value Trade In For Your Vehicle. Package With Full Servicing And New Paintwork To Serve Her New Owner. 100% Bank/In House Loan Available With Low Interest! No Hidden Costs!...							
	Bell Auto Pte Ltd Posted: 28-Nov-2019 Tags: 2013 Hino FS1ETLA, 2013 hino fs1etla, Hino FS1ETLA, hino fs1etla, Hino, FS1ETLA, fs1etla, Used Hino							
	HINO FS1EKLD		\$80,800	\$22,380 /yr	16-Jul-2013	12,913 cc	-	Truck
	Fuel Type: Diesel 10 Wheeler Hooklift Garbage Wagon With Tarping Cover System. New Paintwork Done. Trade In Welcome. Loan And Insurance Support Available.							
	Posted: 28-Nov-2019 Tags: 2013 HINO FS1EKLD, 2013 hino fs1ekld, HINO FS1EKLD, hino fs1ekld, HINO, FS1EKLD, fs1ekld, Used HINO							

Car Buying

Car Selling

Car Ownership

Buying a pre

Unsure i

Car Aftermarket

On The Move

Lifestyle

Got, S

Compare

**FS1ETKA (COE till
1028)**
\$96,800**\$11,680 /yr****18-Mar-2008****12,913 cc****-****Truck**

> Back to OneMctoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	355C
Vehicle Details	
Vehicle No.:	XD4770D
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	HINO
Vehicle Model:	FS1ETKA
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	E13CUN15943
Chassis No.:	JHDFS1ETKXXX12137
Maximum Power Output:	-
Open Market Value:	\$90,576.00
Original Registration Date:	19 Jul 2011
First Registration Date:	19 Jul 2011
Transfer Count:	0
Actual ARF Paid:	\$4,529.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,006.00
COE Rebate Amount:	\$4,693.00
Total Rebate Amount:	\$4,693.00

The information contained herein is correct as at 05 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2019 13:47
Date Of Accident	27/11/2019 10:30
Exact Location Of Accident	BRADDELL ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD4770D
Insured/Policyholder	
Name Of Registered Owner	CHIP ENG SENG CONTRACTORS (1988) PTE LTD
Co Reg No	198802355C
Email Address	SWEECHIN.KOH@CHIPENGSENG.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68010089

Vehicle Particulars

Manufacturer	HINO
Model	FS1ETKA-12.9 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19/VC00/105076
Cover Note Number	01/11/2019 TO 31/10/2020

Driver

Name of Driver	MUHAMMAD NA'EEM BIN IBRAHIM
NRIC No	S8847061C
Date Of Birth	26/11/1988
Occupation	OUTDOOR
Date Of Driving Pass	14/07/2010
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91193815
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address APT BLK 433B SENGKANG WEST WAY #03-539 (S) 792433

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR717C

Vehicle Make/Model/Colour SUBARU

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TONG PECK FONG (TANG BIFANG)

NRIC/Passport Number S7718483Z

Contact Number 97929098

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

SKETCH PLAN



A: XD 4770D

B: SJR 717C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/11/2019 at around 10:30hr, I drove my lorry XD4770D from Buddell road turning to cte. Upon reaching at the merging lane, car SJR717C came out from side road squeeze through on my left & resulting her car hit my left hand glazed against my lorry front left portion. Nobody was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

not filled
2/3 + 4000
3/4
14155 + 1000
the above

LONPAC INSURANCE BHD

DATE : 04-12-2019

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : XD4770D

ACCIDENT DATE : 27-11-2019 10:30

THIRD PARTY REF. : SJR717C

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE XD4770D HINO FS1ETKA-12.9 D (M)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP LH <i>one</i>	1750.94 ✓
2	1	FRONT HEADLAMP BRACKET LH <i>17X</i>	250.00 X
3	1	FRONT BUMPER <i>Dis</i>	1808.45 ✓
4	1	FRONT BUMPER TOP GRILLE <i>7w/one</i>	258.00 ✓
5	1	FRONT BUMPER TOP PANEL LH <i>Dis</i>	135.59 ✓
6	1	FRONT BUMPER BRACKET <i>17X</i>	191.52 X
			4,136.50
ADD 10 %			413.65
TOTAL (A)			4,550.15

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 <i>20</i>
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	580.00 <i>300</i>
3	1	SPRAYPAINTING CHARGES	650.00 <i>350</i>
TOTAL (D)			1,260.00

ESTIMATE TOTAL

5,810.15

3952.98
4348.27
5018.27
4014

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星噴漆工廠

KAN FOOK SING MOTOR WORKSHOP

81 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 5858 2125, 5858 4381

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg No: 201889147
GST Reg No: M010000011

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105076	Date of Loss:	27/11/2019
Vehicle Reg. No.:	XD4770D	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHIP ENG SENG CONTRACTORS (1988) PTE LTD		
Driver:	MUHAMMAD NA'EEM BIN IBRAHIM		
Make/Model:	HINO FS1ETKA, 12.9 D (M)	Vehicle Reg. Date:	19/07/2011
Vehicle Colour:	WHITE		
Engine No:	E13CUN15943	Chassis No:	JHDFS1ETKXXX12137
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER WITH ATTACH.		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

*Not Authorized
n/bk
5/12/19
Excess \$1000*

1/5
3 dy.
thru to Attorney.*

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	680.00
Paintwork Labour	650.00
Towing	0.00
Calculated Gross Total (S\$)	1,330.00
- Excess (S\$)	1,000.00
(S\$)	330.00
+ GST 7.00% (S\$)	23.10
Nett Amount (S\$)	353.10

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 03 Dec 2019)**Parts:** N/A HINO FS1ETKA 12.9 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kan Fook Sing Motor Workshop/XD4770D/03/12/2019 14:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH <i>CHG ✓</i> CHECK PRICE	0.00	0.00	-
2	1		*FRONT HEADLAMP LOWER BRACKET LH <i>✓ X</i> CHECK PRICE	0.00	0.00	-
3	1		*FRONT BUMPER <i>Dis -</i> CHECK PRICE	0.00	0.00	-
4	1		*FRONT BUMPER TOP GRILLE <i>?</i> CHECK PRICE	0.00	0.00	-
5	1		*FRONT BUMPER BRACKET LH <i>✓ X</i> CHECK PRICE	0.00	0.00	-
6	1		*FRONT BUMPER TOP PANEL LH <i>Dis -</i> CHECK PRICE	0.00	0.00	-
Sub Total (\$\$)						0.00
+ Margin on L,N Items 15.00% (\$\$)						0.00
Total Parts (\$\$)						0.00

Kan Fook Sing Motor Workshop/XD4770D/03/12/2019 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	300 650.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	20 30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	350 650.00
Gross Labour Cost (S\$)			1,330.00

Kan Fook Sing Motor Workshop/XD4770D/03/12/2019 14:22 Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Dec 2019)

Parts: N/A HINO FS1ETKA 12.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/XD4770D/05/12/2019 12:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH	0.00	0.00	1,750.94 F
2	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	X*250.00 F
3	1		*FRONT BUMPER	0.00	0.00	1,808.45 F
4	1		*FRONT BUMPER BRACKET LH	0.00	0.00	X*155.59 F
Sub Total (S\$)						3,964.98
+ Margin on L,N Items 15.00% (S\$)						594.75
Total Parts (S\$)						4,559.73

F=Franchise part.

Kan Fook Sing Motor Workshop/XD4770D/05/12/2019 12:13, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New 350	650.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New 20	30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New 300	580.00
Gross Labour Cost (S\$)			1,260.00

Kan Fook Sing Motor Workshop/XD4770D/05/12/2019 12:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2019 Sendback Est.	05 Dec 2019 12:13 \$55,819.73	03 Dec 2019 14:30 Edit Adj Rpt	\$54,000.00 Edit Estimates	\$54,000.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	13 Jan 2020 16:19	13 Jan 2020 16:20 \$5452.63	13 Jan 2020 16:20			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CHIP ENG SENG CONTRACTORS (1988) PTE LTD, Co. Reg. No.: 198802355C								
Vehicle Reg. No.:	XD4770D	Date of Loss:	27/11/2019 10:00 - :59 [100 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 19/19/19/VC00/022707	Policy/Cover Note No.:	Z/19/VC00/105076 (Comprehensive)						
		Excess:	\$51,000.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560								
Handling Insurer:	Lompac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/12/2019]								
Driver/Custodian:	MUHAMMAD NA'EEM BIN IBRAHIM (31 / Male) , NRIC: S8847061C, Tel: +6591193815 Email: NOEMAIL								
Adj Asp. Remarks:	SURVEY & REVERT. PARTS PRICING ARE NOT AVAILABLE YET								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• LONPAC_HQ (05/12/2019): Alert - Adj Mandate Approved (\$54763.30) - XD4770D - Claim Handler: Gerald Poh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

XD4770D (19/19/19/VC00/022707)
 OD
 Nov 27 2019 10:00AM
 [CHIP ENG SENG CONTRACTORS (1988) PTE LTD]
 Kan Fook Sing Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports

1 per page 1

☒

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
1	05/12/19 12:13	Repairer Estimates		Load HTM	
2	13/01/20 16:20	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/19 11:41	Adjuster Immediate Advice		Load HTM	
2	05/12/19 16:39	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page 3

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/12/19 15:14	Chassis Number		Load JPG	☒
2	05/12/19 15:14	Odometer Reading		Load JPG	☒
3	05/12/19 15:14	General View		Load JPG	☒
4	05/12/19 15:14	General View		Load JPG	☒
5	05/12/19 15:14	General View		Load JPG	☒
6	05/12/19 15:14	General View		Load JPG	☒
7	05/12/19 15:14	General View		Load JPG	☒
8	05/12/19 15:14	General View		Load JPG	☒
9	05/12/19 15:14	General View		Load JPG	☒
10	05/12/19 15:14	General View		Load JPG	☒
11	05/12/19 15:14	General View		Load JPG	☒
12	05/12/19 15:14	General View		Load JPG	☒
13	05/12/19 15:14	General View		Load JPG	☒
14	05/12/19 15:14	General View		Load JPG	☒
15	05/12/19 15:14	General View		Load JPG	☒
16	05/12/19 15:14	General View		Load JPG	☒
17	05/12/19 15:14	General View		Load JPG	☒
18	05/12/19 15:14	General View		Load JPG	☒
19	05/12/19 15:14	General View		Load JPG	☒
20	05/12/19 15:14	General View		Load JPG	☒
21	05/12/19 15:14	General View		Load JPG	☒
22	05/12/19 15:14	General View		Load JPG	☒
23	05/12/19 15:14	General View		Load JPG	☒
24	05/12/19 15:14	General View		Load JPG	☒
25	05/12/19 15:14	General View		Load JPG	☒
26	05/12/19 15:14	General View		Load JPG	☒
27	05/12/19 15:14	General View		Load JPG	☒
28	05/12/19 15:14	General View		Load JPG	☒
29	05/12/19 15:14	General View		Load JPG	☒
30	05/12/19 15:14	General View		Load JPG	☒
31	05/12/19 15:14	General View		Load JPG	☒
32	13/01/20 08:29	After Repair Photo		Load JPG	☒
33	13/01/20 08:29	After Repair Photo		Load JPG	☒
34	13/01/20 08:29	After Repair Photo		Load JPG	☒
35	13/01/20 08:29	After Repair Photo		Load JPG	☒

Documentation

1 per page 1

☒

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)		Thumbnail	Print
----	--------------	-------------------------------------	--	-----------	-------

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	28/11/19 10:17	E-filed GIA report	 Load PDF	
2	13/01/20 10:44	Repairer's Bill	 Load PDF	
3	13/01/20 10:44	Signed DV	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/19 16:42	estimate	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	06/12/19 19:39	Accident Statement	 Load HTM	
2	06/12/19 19:41	Accident Statement	 Load HTM	
3	06/12/19 19:43	Accident Statement	 Load HTM	
4	06/12/19 19:45	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	27/11/19 14:05	Accident Photo	 Load JPG	☒
2	27/11/19 14:05	Accident Photo	 Load JPG	☒
3	27/11/19 14:05	Accident Photo	 Load JPG	☒
4	27/11/19 14:05	Accident Photo	 Load JPG	☒
5	27/11/19 14:05	Accident Photo	 Load JPG	☒
6	27/11/19 14:05	Accident Photo	 Load JPG	☒
7	27/11/19 14:05	Accident Photo	 Load JPG	☒
8	27/11/19 14:05	Accident Photo	 Load JPG	☒
9	27/11/19 14:05	Accident Photo	 Load JPG	☒
10	27/11/19 14:05	Accident Photo	 Load JPG	☒
11	27/11/19 14:05	Accident Photo	 Load JPG	☒
12	27/11/19 14:05	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	27/11/19 14:12	Accident Sketch Plan	 Load TIF	
2	27/11/19 14:12	Accident Sketch Plan	 Load TIF	
3	27/11/19 14:12	Driving License	 Load TIF	
4	27/11/19 14:12	certificate of insurance	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19021308/UTF3E2

Date: 15/01/2020

REFERENCE

Insured/Claimant: CHIP ENG SENG CONTRACTORS
(1988) PTE LTD

Policy No: Z/19/VC00/105076

Date of Loss: 27/11/2019

Nature of
Claim: OD

Claim
No: 19/19/19/VC00/022707

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD4770D

Make & Model: HINO FS1ETKA, 12.9 D (M)
Reg. Date: 19/07/2011 (Man. Year: 2011)

Colour: White

Engine Capacity: 12913 cc

Market Value/New Car Price: S\$25,000.00

Price:

Sum Insured (S\$): Market Value/New Car Price

Engine No: E13CUN15943

Chassis No: JHDFS1ETKXXX12137

Odometer: 277219 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Golden Crown 6 mm

Rear Left Side: Golden Crown 6/6/6/6 mm

Front Right Side: Golden Crown 6 mm

Rear Right Side: Golden Crown 6/6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,012.36	4,348.28	664.08	13.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	610.00	320.00	290.00	47.54
Paintwork Labour	650.00	350.00	300.00	46.15
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,272.36	5,018.28	1,254.08	19.99
Approved Total (Overridden) (S\$)		4,000.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	5,272.36	3,000.00	2,272.36	43.10
+ GST 7.00/7.00% (S\$)	369.06	210.00	159.06	43.10
Nett Amount (S\$)	5,641.42	3,210.00	2,431.42	43.10

INSPECTION

Date of Assignment: 03/12/2019 Present Location:

Kan Fook Sing Motor Workshop
(Defu)

Date Inspected: 05/12/2019 Inspected At:

Kan Fook Sing Motor Workshop
(Defu)
No. 61 Defu Lane 12
Singapore 539147

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jan 2020)	
Parts:	N/A	HINO FS1ETKA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD4770D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH (WCP)	Cracked	1,750.94 F	*1,750.94 F
2	1		*FRONT HEADLAMP LOWER BRACKET LH (WCP)	Not Necessary	250.00 F	*- F
3	1		*FRONT BUMPER (WCP)	Distorted	1,808.45 F	*1,808.45 F
4	1		*FRONT BUMPER BRACKET LH (WCP)	Not Necessary	155.59 F	*- F
Supplementary #1						
5	1		*FRONT BUMPER TOP PANEL LH (WCP)	Distorted	135.59 F	*135.59 F
6	1		*FRONT BUMPER TOP GRILLE (WCP)	Twisted / Cracked	258.00 F	*258.00 F
					Sub Total (S\$)	4,358.57 3,952.98
					+ Margin on L,N Items 15.00/10.00% (S\$)	653.79 395.30
					Total Parts (S\$)	5,012.36 4,348.28

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	650.00	350.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	30.00	20.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	580.00	300.00
Gross Labour Cost (S\$)			1,260.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >