

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

29-Nov-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8735 E

1 pc	End panel inner garnish
1 pc	Boot lid lock
1 pc	End panel
1 pc	Bootlid striker
1 pc	Bootlid emblem
1 pc	Bootlid CRDi
1 pc	Boot lid rubber weatherstrip
1 pc	Rear bumper
1 pc	Rear bumper lower cover
1 pc	Rear bumper inner sponge
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00
1 pc	Rear bumper reinforcement
2 pcs	Rear bumper stay o/s & n/s @ \$53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00

\$	74.00	? XSVL
\$	99.00	? XSVL
\$	250.00	? XSVL
\$	21.00	? XSVL
\$	27.00	/ NEL
\$	29.00	/ NEL
\$	96.00	/ TN
\$	696.00	/ CRL
\$	206.00	/ DEF
\$	114.00	? / CRK
\$	58.00	? / BT
\$	607.00	? / DEF
\$	108.00	? / BT
\$	36.00	? XSVL
\$	36.00	? XSVL

1,941
Less 10%
\$ 2,457.00
\$ 245.70

1,746.90 \$ 2,211.30

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 set	Bootlid lower garnish clips
1 set	End panel inner garnish clips
1 set	Bootlid stickers
1 pc	Rear bumper top protector
1 pc	Rear no. plate with casing

\$	28.00	/ NEL
\$	200.00	XSVL
\$	30.00	? XNN
\$	30.00	? XNN
\$	30.00	/ NEL
\$	80.00	/ NEL
\$	50.00	
\$	40	DD

178

Khanchana

- Finalized.

- Naz.

11/12/19

29-Nov-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8735 E

To labour charge for dismantle and renew the accident damaged parts. To heatweld, cut-off the the end panel, floorboard panel, rear o/s fender, n/s & o/s taillamp panel, including knock-out, straighten, repair, reshape and adjust of the same, etc

\$ ~~1,000.00~~ 400
360

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel

\$ ~~1,000.00~~ 400

To apply rustproofing on the repaired and replaced panels

\$ ~~120.00~~ 40
\$ 4,779.30

800

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK

29/11/19 1700

LLS

3 DAYS

CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2,124.90

2,179.92

PARTS	\$1,941.00
LESS 10%	\$1,746.90
S/NETT	\$ 178.00
LABOUR	\$ 800.00
TOTAL	\$2,724.90
LESS LLS 20%	\$2,179.92
LLS TOTAL	\$2,150.00

/ 3 REPAIR DAYS.

FINALIZED LUMP SUM REPAIR \$2,150.00 / 3 DAYS

NAZ LKK
11/12/19.