

areas



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L		NAME : Mr Yap Wee Leong Alvin		WIP : 15340	
78 SHENTON WAY		ADDRESS : 259A Punggol Field		EXCESS :	
#07-16 CHARTIS BUILDING		#17-23		DATE: 30-Nov-19	
SINGAPORE 079120		Singapore 821259			
ATTN. : MOTOR CLAIMS		TEL : 98334539			
FAX :					
VEH NO :	SKF1028C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6KF2W7AJ0137046	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	CX5	DATE REG.:	14-Dec-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	REAR BUMPER <i>de</i>	1	MKBYB-50-22XBBB		\$ 1,278.90
2	RETAINER LHS <i>X</i>	1	MKB8A-50-2J1B		\$ 23.70
3	BRACKET CENTER <i>X</i>	1	MKD53-50-251		\$ 5.40
4	STAY LHS <i>X</i>	1	MKB7W-52-B32A		\$ 25.40
5	STAY RHS <i>X</i>	1	MKB7W-52-B22A		\$ 25.40
6	REFLECTOR LHS <i>X</i>	1	MK123-51-5M0C		\$ 210.90
7	REAR REINFORCEMENT <i>X</i>	1	MKD53-50-260D		\$ 520.00
8	FASTENER, REAR BUMPER <i>rec</i>	16	MB45A-56-146A		\$ 48.00
9	GROMMET, REAR BUMPER <i>rec</i>	4	MBHN1-50-0Z1A		\$ 10.80
10	RUBBER SEAL, REAR BUMPER <i>X</i>	6	MKB8A-50-2G2		\$ 98.40
11	RETAINER SIDE, SENSOR <i>rec</i>	1	MK156-67-UC5 51		\$ 15.50
12	SENSOR SIDE, ULTRASONIC <i>rec</i>	1	MKD47-67-UC1 51		\$ 203.60
13	PAD PROTECTOR, SENSOR <i>rec</i>	3	MG001-67-061		\$ 23.40
14	BRACKET LHS, MODULE LANE CHANGE <i>(NEC) X</i>	1	MKB8C-67-ZP1A		\$ 20.90
15	MONITOR, BLIND SPOT <i>(NEC) ca (LH) 1pc / RV-?</i>		MKB8C-67-Y30F		\$ 3,427.00
16	PANEL LOWER LHS, REAR FENDER <i>X</i>	1	MKBYW-71-40X		\$ 294.40
17	GARNISH LHS, REAR FENDER <i>de</i>	1	MKB7W-51-W60F		\$ 186.40
18	BRACKET SIDE LHS, GARNISH <i>X</i>	1	MKB8A-51-U30		\$ 10.10
19	EXTRACTOR VENT LHS <i>X</i>	1	MKB7W-51-920		\$ 48.00
TOTAL PARTS					\$ 6,476.20
LESS 10%					\$ 647.62
TOTAL PARTS COST					\$ 5,828.58
Labour Description					
1	TO REPLACE REAR BUMPER, PANEL LOWER LHS. TO REPAIR REAR FENDER LH, REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			630	\$ 2,835.00

2		TO RESPRAY REAR BUMPER, PANEL LOWER LHS, REAR FENDER LH, REAR END PANEL.	600	\$ 2,400.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	NETT	\$ 180.00
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	\$ 945.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	NETT 20	\$ 100.00
			TOTAL LABOUR	\$ - \$ 7,660.00
			TOTAL PARTS	\$ - \$ 5,828.58
			TOTAL	\$ - \$ 13,488.58
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Rasul
Hp 900 100 68
3 days
06/12/19 @ 1545
EXCESS: TBA
REVERT
Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: