



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Yap Wee Leong Alvin ADDRESS : 259A Punggol Field #17-23 Singapore 821259 TEL : 98334539		WIP : 15340 EXCESS : \$ 300.00 DATE: 30-Nov-19	
VEH NO :	SKF1028C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6KF2W7AJ0137046	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	CX5	DATE REG.:	14-Dec-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MKBYB-50-22XBBB	\$ 1,278.90	\$ 1,278.90
2	RETAINER LHS	1	MKB8A-50-2J1B		\$ 23.70
3	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
4	STAY LHS	1	MKB7W-52-B32A		\$ 25.40
5	STAY RHS	1	MKB7W-52-B22A		\$ 25.40
6	REFLECTOR LHS	1	MK123-51-5M0C		\$ 210.90
7	REAR REINFORCEMENT	1	MKD53-50-260D		\$ 520.00
8	FASTENER, REAR BUMPER	16	MB45A-56-146A	\$ 48.00	\$ 48.00
9	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
10	RUBBER SEAL, REAR BUMPER	6	MKB8A-50-2G2		\$ 98.40
11	RETAINER SIDE, SENSOR	1	MK156-67-UC5 51	\$ 15.50	\$ 15.50
12	SENSOR SIDE, ULTRASONIC	1	MKD47-67-UC1 51	\$ 203.60	\$ 203.60
13	PAD PROTECTOR, SENSOR	3	MG001-67-061	\$ 23.40	\$ 23.40
14	BRACKET LHS, MODULE LANE CHANGE	1	MKB8C-67-ZP1A	\$ 20.90	\$ 20.90
15	MONITOR, BLIND SPOT	1	MKB8C-67-Y30F	\$ 1,713.50	\$ 3,427.00
16	PANEL LOWER LHS, REAR FENDER	1	MKBYW-71-40X	\$ 294.40	\$ 294.40
17	GARNISH LHS, REAR FENDER	1	MKB7W-51-W60F	\$ 186.40	\$ 186.40
18	BRACKET SIDE LHS, GARNISH	1	MKB8A-51-U30		\$ 10.10
19	EXTRACTOR VENT LHS	1	MKB7W-51-920	\$ 48.00	\$ 48.00
TOTAL PARTS				\$ 3,843.40	\$ 6,476.20
LESS 10%				\$ 384.34	\$ 647.62
TOTAL PARTS COST				\$ 3,459.06	\$ 5,828.58
Labour Description					
1	TO REPLACE REAR BUMPER, PANEL LOWER LHS. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.			\$ 630.00	\$ 2,835.00
2	TO RESPRAY REAR BUMPER, PANEL LOWER LHS.			\$ 600.00	\$ 2,400.00

3	MZ-BR-REVS2	TO TRANSFER REVERSE SENSORS.	\$ 180.00	\$ 180.00
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 945.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 1,730.00 \$ 7,660.00
			TOTAL PARTS	\$ 3,459.06 \$ 5,828.58
			TOTAL	\$ 5,189.06 \$ 13,488.58
			LESS EXCESS	\$ 300.00 \$ -
			TOTAL AFTER EXCESS	\$ 4,889.06
			GST 7%	\$ 342.23 \$ -
			GRAND TOTAL	\$ 5,231.29 \$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)