

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

THAM SOUK FUN
BLK 505 WOODLANDS DRIVE 14
#06-68
S 730505

TP ALG.
Asher
KMH D841CMJU560989

Date :05.12.2019
Vehicle No :SLT 3449 Y
Make/Model :HYUNDAI ELANTRA
Accident date :29.11.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear bootlid <i>Dented.</i>	1	\$ 1977.8 1620
2	Rear bootlid hinges @ \$103.70 <i>new</i>	2	\$ 207.4 X
3	Rear bootlid upper lock <i>Damaged</i>	1	\$ 139.3 ✓
4	Rear bootlid lower lock <i>new</i>	1	\$ 138.8 X
5	Rear bootlid cable <i>new</i>	1	\$ 75.7 X
6	Rear bootlid weather strip <i>lit</i>	1	\$ 101.8 ✓
7	Rear bootlid insulation <i>new</i>	1	\$ 161.5 X
8	Rear bootlid reflector @ \$341.00 <i>new</i>	2	\$ 682 X
9	Rear bootlid centre emblem	1	\$ 52.8 ✓
10	Rear bootlid S emblem <i>new</i>	1	\$ 22 ✓
11	Rear bootlid Elantra emblem	1	\$ 63.8 ✓
12	Rear lamp @ \$431.20 <i>cracked</i>	2	\$ 862.4 ✓
13	Rear end panel <i>Dented.</i>	1	\$ 499.4 ✓
14	Rear end panel top garnish <i>Damaged</i>	1	\$ 76.8 ✓
15	Rear bumper <i>Distorted</i>	1	\$ 505.8 ✓
16	Rear bumper side holder @ \$30.80 <i>new</i>	2	\$ 61.6 ✓
17	Rear bumper reinforcement <i>Bent</i>	1	\$ 324.3 ✓
18	Rear bumper bracket @ \$60.90 <i>new</i>	2	\$ 121.8 X
19	Rear bumper lower bracket @ \$16.50 <i>Damaged</i>	4	\$ 66 ✓
20	Rear bumper lower lip <i>cracked</i>	1	\$ 308 ✓
21	Rear bumper reflector @ \$63.80 <i>cracked</i>	2	\$ 127.6 ✓
22	Rear bumper clips (1 set) <i>new</i>	1	\$ 66 30
23	Rear exhaust pipe <i>new</i>	1	\$ 647.2 X
24	Rear exhaust pipe mounting <i>new</i>	1	\$ 33 X
25	Rear spare tyre top board <i>new</i>	1	\$ 240.9 X
26	Rear bootlid centre lock sensor <i>cracked</i>	1	\$ 115.5 ✓
27	Rear end panel lower LH side cover <i>Damaged</i>	1	\$ 54.5 ✓
28	Rear fender inner garnish @ \$228.70 <i>form</i>	2	\$ 457.4 X
29	Rear number plate lamp @ \$35.90 <i>new</i>	2	\$ 71.8 X
			\$ 8262.9
Less 20% Disc			\$ 1652.58
Total			\$ 6610.32

5489

4391.20

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

THAM SOUK FUN

BLK 505 WOODLANDS DRIVE 14

#06-68

S 730505

Date

:05.12.2019

Vehicle No

:SLT 3449 Y

Make/Model

:HYUNDAI ELANTRA

Accident date

:29.11.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

- 1 Rear bumper reverse sensor (1 set) *Damaged*
- 2 Rear camera *not rec*

200

\$ ~~380~~ 200

\$ 800 x.

Total

\$ 1180

Labour Cost

- 1 To supply rear end panel inner sealant
- 2 Remove & reinstall exhaust pipe
- 3 Remove & reinstall reverse sensor
- 4 Remove & reinstall bootlid inner garnish
- 5 Remove, replace & repair consistent to the accident
- 6 Respray painting
- 7 Tuff kote

2130

\$ 200 60

\$ 200 x

\$ 200 50.

\$ 200 60

\$ 1800 90

\$ 1400 800

\$ 100 60.

Total

\$ 4100

Grand Total

\$ 11890.32

total: 6721.20

4/s: 5.3k

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: