

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021312/KKA3N2

**Date:** 22/05/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800134825  
**Claimant**  
**Vehicle No :** SMQ4566P **Insured Vehicle No :** SGC7623H  
Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 4864273589SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ4566P**  
Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2C68462  
Reg. Date: 18/11/2019 (Man. Year: 2018) Chassis No: ZYX102163942  
Colour: Metallic Yellow Odometer: 4246 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17  
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm  
Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,023.23	3,357.14	666.09	16.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,120.00	1,460.00	56.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,603.23</b>	<b>4,477.14</b>	<b>2,126.09</b>	<b>32.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,550.00</b>		
<b>(S\$)</b>	6,603.23	3,550.00	3,053.23	46.24
<b>+ GST 7.00/7.00% (S\$)</b>	462.23	248.50	213.73	46.24
<b>Nett Amount (S\$)</b>	<b>7,065.46</b>	<b>3,798.50</b>	<b>3,266.96</b>	<b>46.24</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		321.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,121.50</b>		

#### INSPECTION

Date of Assignment: 02/12/2019  
Date Inspected: 03/12/2019 Inspected At: Hui Yang Motor Pte Ltd (HQ)  
176 Sin Ming Drive #04-02, Sin Ming  
AutoCare  
Singapore 575721  
Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cut	585.52 FL	*585.52 FL
2	1		*REAR LH TAILLAMP LOWER BRACKET	Cracked	171.45 FL	*171.45 FL
3	1		*REAR BUMPER	Buckled	972.45 FL	*972.45 FL
4	1		*REAR BUMPER LH SIDE RETAINER	Distorted	141.50 FL	*141.50 FL
5	1		*REAR BUMPER LH REFLECTOR	Cracked	180.50 FL	*180.50 FL
6	1		*REAR BUMPER LH REFLECTOR GARNISH	Dented	281.90 FL	*281.90 FL
7	1		*REAR BUMPER LH INNER SIDE SHIELD	Distorted	281.50 FL	*281.50 FL
8	1		*REAR BUMPER DIFFUSER	Bent	687.75 FL	*687.75 FL
9	10		*REAR BUMPER DIFFUSER CLIP	Necessary	50.00 FL	*50.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	482.50 FL	*482.50 FL
11	1		*REAR END PANEL	Repair	781.45 FL	*- FL
12	1		*REAR LH FENDER PROTECTOR	Distorted	374.45 FL	*374.45 FL
13	1		*SET REAR PARKING SENSOR	Cut	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,270.97</b>	<b>4,409.52</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,247.74	1,052.38
<b>Total Parts (\$\$)</b>	<b>4,023.23</b>	<b>3,357.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TUFFKOTE	New	80.00	0.00
2	WIRING	New	100.00	20.00
3	SPRAY PAINTING	New	1,200.00	600.00
4	LABOUR CHARGES	New	1,200.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,580.00</b>	<b>1,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >