

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

ALL
Veh in
03/12/19
LKK

29/11/2019

Owner: SKYWAY MOTOR PTE LTD

*Not Authorized
L/Sup @?*

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMO4566P

3dots

1pc	rear LH taillamp	<i>Wt</i>	\$ 585.52	✓
1pc	rear LH taillamp lower bracket		\$ 171.45	?
1pc	rear bumper	<i>Bu</i>	\$ 972.45	✓
1pc	rear bumper LH side retainer	<i>Dir</i>	\$ 141.50	✓
1pc	rear bumper LH reflector	<i>CM</i>	\$ 180.50	✓
1pc	rear bumper LH reflector garnish	<i>nd</i>	\$ 281.90	✓
1pc	rear bumper LH inner side shield		\$ 281.50	?
1pc	rear bumper diffuser	<i>B</i>	\$ 687.75	✓
10pcs	rear bumper diffuser clip @\$5.00	<i>nn</i>	\$ 50.00	✓
1pc	rear bumper reinforcement		\$ 482.50	?
1pc	rear end panel		\$ 781.45	?
1pc	rear LH fender protector	<i>Dir</i>	\$ 374.45	✓
			\$ 4,990.97	
	less 25%		\$ 1,247.74	
			\$ 3,743.23	
1set	rear parking sensor	s.nett	\$ 280.00	?
	tuffkote	<i>nn</i>	\$ 80.00	X
	wiring		\$ 100.00	2cl
	spray painting		\$ 1,200.00	?
	labour charges		\$ 1,200.00	?
	Total		\$ 6,603.23	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

