

LKK

7117
Veh in
03/12/19
LKK

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

29/11/2019
Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMQ4566P

- 1pc rear LH taillamp
- 1pc rear LH taillamp lower bracket
- 1pc rear bumper
- 1pc rear bumper LH side retainer
- 1pc rear bumper LH reflector
- 1pc rear bumper LH reflector garnish
- 1pc rear bumper LH inner side shield
- 1pc rear bumper diffuser
- 10pcs rear bumper diffuser clip @\$5.00
- 1pc rear bumper reinforcement
- 1pc rear end panel
- 1pc rear LH fender protector

Not Authorized
11/11/19 @ 3550h
4dots

<i>Cr</i>	\$	585.52	✓
<i>CM</i>		171.45	✓
<i>Bu</i>	\$	972.45	✓
<i>DIY</i>	\$	141.50	—
<i>CM</i>	\$	180.50	—
<i>DIY</i>	\$	281.90	—
<i>DIY</i>	\$	281.50	✓
<i>B</i>	\$	687.75	✓
<i>nr</i>	\$	50.00	✓
<i>B</i>	\$	482.50	✓
<i>R</i>	\$	781.45	X
<i>DIY</i>	\$	374.45	✓

	\$	4,990.97
less 25%	\$	1,247.74
	\$	<u>3,743.23</u>

- 1set rear parking sensor
- tuffkote
- wiring
- spray painting
- labour charges
- Total

<i>Cr</i>	s.nett	\$	280.00	<i>Down</i>
<i>nr</i>	\$	80.00		X
	\$	100.00		<i>201</i>
	\$	1,200.00		<i>500</i>
	\$	1,200.00		<i>500</i>
	\$	<u>6,603.23</u>		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

