

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 2/12/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP6681T

Chassis No: JM6BN22A8H0159130

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT: 01/12/2019

YOUR INSURED VEHICLE NUMBER :SLN 7133M

MILEAGE : 63566 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/L door mirror / CRU.	1PC	\$480.00	\$480.00
2	F/L door / PH	1PC	\$1,480.00	\$1,480.00
LIST TOTAL S\$:				\$1,960.00
10% DISCOUNT S\$:				\$196.00
				\$1,764.00

LABOUR CHARGES

1	To labour charge for removing F/L door out to facilitate repairs and replacement of parts	\$600.00	400.
2	To respray F/L door and F/L door mirror	\$900.00	350.
3	Transfer F/L door mechanism	\$100.00	80.
LABOUR TOTAL S\$:		\$1,600.00	
TOTAL S\$:		\$3,364.00	
7% GST		\$235.48	
GRAND TOTAL S\$:		\$3,599.48	

Repair day - 3 days

Sun Pm (4th)
03/12/2019

Lump Sum Repair

After spray photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: