

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

P = 1,425.5

L = 830

2,255.5

20%

1,804.4

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 2/12/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP6681T

Chassis No: JM6BN22A8H0159130

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT: 01/12/2019

YOUR INSURED VEHICLE NUMBER :SLN 7133M

MILEAGE : 63566 km

415 = \$1,800
3 days

PARTS DESCRIPTION

- 1 F/L door mirror / ~~FR~~ CRU.
- 2 F/L door / pn

QTY	UNIT PRICE	LIST PRICE
1PC	\$480.00	\$480.00 396.9
1PC	\$1,480.00	\$1,480.00 1,385
LIST TOTAL S\$:		\$1,960.00 1,781.9
10% DISCOUNT S\$:		\$196.00 -20%
w		\$1,764.00 1,425.5

1,960.00

392.00

1,568.00

LABOUR CHARGES

- 1 To labour charge for removing F/L door out to facilitate repairs and replacement of parts
- 2 To respray F/L door and F/L door mirror
- 3 Transfer F/L door mechanism

\$600.00 400.

\$900.00 350.

\$100.00 80.

LABOUR TOTAL S\$:

\$1,600.00

TOTAL S\$:

\$3,364.00

7% GST

\$235.48

GRAND TOTAL S\$:

\$3,599.48

830.00

2,398.00

Repair day - 3 days

Sun Pin (411)

03/12/2019

Lump Sum Repair

After spray photo

Lump sum
3 days

Oi Sun Pin (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Friday, 28 February, 2020 11:23 AM
To: Oi Sun Pin (LKK Auto)
Subject: Re: Final Bill: SLP6681T

Follow Up Flag: Follow up
Flag Status: Flagged

Sun Pin
Ok confirm lump sum \$1,800.00/3 days

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Fri, Feb 28, 2020 at 9:47 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Hi Mr Sim,

Kindly refer the finalize amount is \$1,800. Repair day 3 days. (L/S, before gst).

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 2/12/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP6681T
Chassis No: JM6BN22A8H0159130
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT: 01/12/2019
YOUR INSURED VEHICLE NUMBER :SLN 7133M
MILEAGE : 63566 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/L door mirror / CRU.	1PC	\$480.00	\$480.00
2	F/L door / pn	1PC	\$1,480.00	\$1,480.00
LIST TOTAL S\$:				\$1,960.00
10% DISCOUNT S\$:				\$196.00
				\$1,764.00

LABOUR CHARGES

1	To labour charge for removing F/L door out to facilitate repairs and replacement of parts	\$600.00	400
2	To respray F/L door and F/L door mirror	\$900.00	350
3	Transfer F/L door mechanism	\$100.00	80
LABOUR TOTAL S\$:		\$1,600.00	
TOTAL S\$:		\$3,364.00	
7% GST		\$235.48	
GRAND TOTAL S\$:		\$3,599.48	

Repair day - 3 days

Lump Sum Repair
After spray photo

Sur Pm (411)
03/12/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: