

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LCRF PTE LTD
CARROS CENTER

60 JALAN LAM HUAT #04-01 S(737869)

Main +65 62524991

P = 1,425.5

L = 830

2,255.5

20%

1,804.4

Lis = \$1,800
3 days

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 2/12/2019

Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP6681T

Chassis No: JM6BN22A8H0159130

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT: 01/12/2019

YOUR INSURED VEHICLE NUMBER :SLN 7133M

MILEAGE : 63566 km

PARTS DESCRIPTION

- 1 F/L door mirror / ~~CR4~~ CR4
- 2 F/L door / ~~PR~~ PR

QTY	UNIT PRICE	LIST PRICE
-----	------------	------------

1PC	\$480.00	\$480.00 396.9
-----	----------	----------------

1PC	\$1,480.00	\$1,480.00 1,385
-----	------------	------------------

LIST TOTAL S\$: \$1,960.00 1,781.9

10% DISCOUNT S\$: \$196.00 -20%

\$1,764.00 1,425.5

1,960.00

392.00

1,568.00

LABOUR CHARGES

- 1 To labour charge for removing F/L door out to facilitate repairs and replacement of parts

\$600.00 400.

- 2 To respray F/L door and F/L door mirror

\$900.00 350.

- 3 Transfer F/L door mechanism

\$100.00 80.

LABOUR TOTAL S\$: \$1,600.00

TOTAL S\$: \$3,364.00

7% GST \$235.48

GRAND TOTAL S\$: \$3,599.48

830.00

2,398.00

Repair day - 3 days

Sun Pm (4th)

03/12/2019

Lump Sum Repair

After spray photo

Lump sum
3 days