

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

TIDAL CAPITAL PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Authorised
1/18/19 @ 7
Permanently After Pain
6 days

Date: 3/12/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA VELLFIRE / SLB 7997 A		
1 pc	front bumper	Bu 2843.40 ✓
1 pc	front bumper side grille	~ 564.30 X
1 pc	front bumper side grille chrome trim	321.50 ?
1 pc	front bumper fog lamp	~ 453.80 X
1 pc	front bumper side retainer	~ 78.30 ✓
1 pc	front bumper side park sensor	~ 348.40 ✓
1 pc	front top grille chrome	684.60 ?
1 pc	front fender	Bu 968.20 ✓
1 pc	front fender dust cover	~ 196.40 X
1 pc	front fender blind spots mirror	~ 369.60 X
1 pc	front head lamp assy	~ 2533.30 ✓
1 pc	front head lamp lower bracket	78.50 ?
1 pc	front head lamp apron panel	~ 159.80 X
1 pc	front side mirror assy	~ 854.70 X
1 pc	alloy rim	~ 968.50 X
1 pc	front lower arm	585.20 ?
1 pc	front shock absorber	674.30 ?
1 pc	front shock absorber top mount	257.20 ?
1 pc	front steering tie rod	~ 263.30 X
1 pc	front steering tie rod end	~ 227.50 X
1 pc	front steering anti roll bar linkage	~ 85.40 X
1 pc	front knuckle	568.90 ?
1 pc	front wheel bearing hub	468.40 ?
1 pc	drive shaft LH	~ 985.70 X
sub-total		15,539.20
less 25%		3884.80
sub-total		11654.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	balance brought forward	11,654.40	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	860.00	500/
	To check wiring system.	60.00	20/
	To apply rust proofing on affected areas.	100.00	30/
	To apply waterproof sealant on affected areas.	100.00	nn X
	To remove and install front undercarriage parts to enable repair.	220.00	?
	To install reverse sensors & reverse camera.	80.00	50/
	To perform 4 wheels computerised alignment.	85.00	60/
	To apply putty and spray painting on affected areas.	850.00	700/
	Total	14,009.40	