

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

TIDAL CAPITAL PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Date: 3/12/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA VELLFIRE / SLB 7997 A		
1 pc	front bumper \$1,380.00	Bu 2843.40 ✓
1 pc	front bumper side grille	~ 564.30 X
1 pc	front bumper side grille chrome trim \$145.00	mtg cra 321.50 ✓
1 pc	front bumper fog lamp	~ 453.80 X
1 pc	front bumper side retainer	~ 78.30 ✓
1 pc	front bumper side park sensor	~ 348.40 ✓
1 pc	front top grille chrome \$490.00	mtg cra 684.60 ✓
1 pc	front fender 789.20	Bu 968.20 ✓
1 pc	front fender dust cover	~ 196.40 X
1 pc	front fender blind spots mirror	~ 369.60 X
1 pc	front head lamp assy \$2322.90	~ 2533.30 ✓
1 pc	front head lamp lower bracket	SVC 78.50 X
1 pc	front head lamp apron panel	~ 159.80 X
1 pc	front side mirror assy	~ 854.70 X
1 pc	alloy rim	~ 968.50 X
1 pc	front lower arm	SVC 585.20 X
1 pc	front shock absorber	SVC 674.30 X
1 pc	front shock absorber top mount	SVC 257.20 X
1 pc	front steering tie rod	~ 263.30 X
1 pc	front steering tie rod end	~ 227.50 X
1 pc	front steering anti roll bar linkage	~ 85.40 X
1 pc	front knuckle 522	Bt 568.90 ✓
1 pc	front wheel bearing hub \$181.75	Nec 468.40 ✓
1 pc	drive shaft LH	~ 985.70 X
sub-total		15,539.20
less 25%		3884.80
sub-total		11654.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1318/1cp
Not Authen
11Rm @ 500dp
Purvey After Rain
6days

balance brought forward	11,654.40	
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	860.00	500
To check wiring system.	60.00	200
To apply rust proofing on affected areas.	100.00	300
To apply waterproof sealant on affected areas.	100.00	X
To remove and install front undercarriage parts to enable repair.	220.00	✓ \$60.00
To install reverse sensors & reverse camera.	80.00	500
To perform 4 wheels computerised alignment.	85.00	600
To apply putty and spray painting on affected areas.	850.00	7000
Total	14,009.40	