

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Email: sg_motor_enterprise@yahoo.com.sg

To : LKK

Attn : Bryan Ang

VEHICLE NO : JRQ 5443

ACCIDENT DATE: 22 November 2019

	Description	Qty	Quotation \$
1	Handle Bar H/H	1	185.00 X
front 2	Left Side Signal broken	1	75.00 ✓
3	Handle Cover H/H	1	78.00 X
4	Front Side Left Fairing rep	1	185.00 X
5	Front Footrest Bar Left 1st	1	105.00 ✓
6	Left Side Mirror broken	1	80.00 ✓
7	Front Fork H/H	1 set	480.00 X
8	Front Rim cut / distribute	1	320.00 ✓
9	Pillion Footrest Left broken	1	80.00 ✓
10	Pillion Footrest Bracket broken H/S	1 set	135.00 ✓ 67.50
11	Pillion Handle Bar cut	1	95.00 ✓
12	Left Side Fairing rep	1	80.00 X
13	Rear Mudguard cut / 1st	1	185.00 ✓
14	Front Disc H/H	1	230.00 X
15	Side Signal H/H	1	150.00 X
16	Exhaust Cover H/H	1	180.00 X
17	Balancer Left cut	1	75.00 ✓
18	Rear Left Signal Lamp broken	1	85.00 ✓
19	Front Head Lamp Cover cut	1	135.00 ✓
	Sub-Total		2,938.00
	Less 10%		293.80
	Sub-Total		2,644.20

VEHICLE NO : JRQ 5443

Honda AFS

Nett Items

1	Rear number plate	15.00 ✓
2	Towing fee	60.00 X
3	Remove & replace new parts, align & etc	350.00 180/-
4	Remove & replace fork assy, brake disc & rim	150.00 NH
5	Replace body new sticker and spray painting	80.00 ✓
Sub-Total		655.00

Nett Total 3,299.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

1447.25
L/S 1150/-

S9 MOTOR TRADING PTE LTD

:LG

03/12/19 @ 1200hr
H/A Andrew
L/S H/W 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto