

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 06 Dec 2019

Preliminary Advice

Vehicle No	: SLN8420C	Accident Date	: 29/11/2019
Make	: MAZDA 6	Policy No.	: 2100509485
Assignment Date	: 03/12/2019	Excess	: S\$0.00
Date of Inspection	: 06/12/2019	Est. Duration of Repair	: 4.00
Inspection At	: TRANS EUROKARS PTE LTD (UBI) 5 UBI CLOSE SINGAPORE 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,087.06
Revised Amount	:S\$	7,483.50
Check Items (Estimated)	:S\$	2,450.97
Total	:S\$	9,934.47
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	60,203.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,797.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :