

Your password will expire in 9 days. [Click here to change it.](#)

- ARRANGE FOR SURVEY / SLN8420C

From: AIG SGP, Claims-Survey
To: Admin A, assignments
Cc: Fong, Andy-SY, Fan, Winnie-LW
Sent: 12/3/2019 11:38:04 AM
Attachments:  0214_191203085848_001.pdf

Hi LKK,

Kindly assist to survey.

Thanks & regards
Jennifer Chan

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Tuesday, 3 December, 2019 8:59 AM
To: AIG SGP, Claims-Survey
Cc: vion.lim@eurokars.com.sg; jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg
Subject: [EXTERNAL] ARRANGE FOR SURVEY / SLN8420C

This message is from an external sender; be cautious with links and attachments.

Dear AIG,

Please arrange on 06 Dec @ 3PM.

Kindly confirm.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd
5 Ubi Close, Singapore 408605
T: 6395 8899 H: 9127 7928
ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacan@mazda.com.sg <transeurokars@eurokars.com.sg>
Sent: 03 December 2019 08:59
To: Ronald Yap <ronald.yap@eurokars.com.sg>
Subject: Attached Image

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 9 December 2019 1:22 PM
To: ronald.yap@eurokars.com.sg
Cc: SUR
Subject: RE: SLN8420C / DOA 29/11/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLN 8420C (Excess \$0.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

- Before paint photos for new replacement parts required.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ronald.yap@eurokars.com.sg <ronald.yap@eurokars.com.sg>
Sent: Wednesday, 4 December 2019 10:32 AM
To: Hunchung.Gan@aig.com
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLN8420C / DOA 29/11/2019

Hi Hun Chung,

Please see attached.

Thank You,

*Ronald Yap
Insurance Claims*

Trans Eurokars Pte Ltd
5 Ubi Close, Singapore 408605

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/11/2019 14:33
Date Of Accident	29/11/2019 17:10
Exact Location Of Accident	PATERSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN8420C
Insured/Policyholder	
Name Of Registered Owner	MR NGOH KOH FUI FRANK
NRIC No	S6938804C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91050461
Alternative Phone No	OFFICE-91050461

Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 4-DOOR SEDAN (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MR NGOH KOH FUI FRANK
NRIC No	S6938804C
Date Of Birth	01/11/1969
Occupation	INDOOR
Date Of Driving Pass	30/11/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91050461
Fax Number	
Contact Number	
Email Address	NOEMAIL

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Ngoh Koh Fui-Frank
 Period of Insurance : 19 May 2019 To 18 May 2020
 Engine No. : PE20893279
 Chassis No. : JM6GL1071H0118381

Vehicle No. : SLN8420C
 Policy No. : 2100509485-02
 Endorsement No. :
 Issued Date : 14 May 2019

ABOUT THE COVER

Make/Model : MAZDA 6 2.0 SKYACTIV
 Engine Capacity/Tonnage : 1,998.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ngoh Koh Fui Frank - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurokars Pte Ltd Add: 27A Tanjong Penjuru, Singapore 609042 63310608

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599190

ARF (AP) PTE LTD - MAZDA
 7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX

SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP

Best Rate
GSM
Claims Examining
Asia Pacific
78 Shenton Way
Singapore 079120
Tel: 65 419 1970
Fax: 65 419 1970
aig.com

ASSIGNMENT

TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN: MOTOR CLAIMS FAX:		NAME: Mr Ngoh Koh Fui Frank ADDRESS: 542 Bukit Batok Street 52 #08-549 Singapore 650542 TEL: 91050461		WIP: 15618 EXCESS: DATE: 30-Nov-19	
VEH NO:	SLN8420C	DATE IN:		CONTACT PERSON:	Ronald 63957875
CHASSIS NO:	JM6GL1071H0118381	MILEAGE:		TYPE OF CLAIM:	OWN DAMAGED CLAIM
MODEL:	MAZDA6	DATE REG.:	19-May-17	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER <i>de</i>	1		
2	BRACKET CENTER <i>nee</i>	1		\$ 1,266.60
3	RETAINER LHS <i>nee</i>	1		\$ 5.40
4	TOWING COVER LHS <i>crn</i>	1		\$ 41.00
5	TOWING COVER RHS <i>M13</i>	1		\$ 24.90
6	REAR REINFORCEMENT <i>? bt</i>	1		\$ 24.90
7	RETAINER CENTER, SENSOR <i>nee</i>	1		\$ 538.30
8	SENSOR CENTER, ULTRASONIC <i>?</i>	2		\$ 36.40
9	TAPE PROTECTOR, SENSOR <i>nee</i>	2		\$ 361.80
10	GROMMET, REAR BUMPER <i>nee</i>	4		\$ 34.40
11	GROMMET, REAR BUMPER <i>nee</i>	2		\$ 6.00
12	FASTENER, REAR BUMPER <i>nee</i>	4		\$ 12.00
13	REFLECTOR LHS <i>?</i>	6		\$ 18.00
14	REAR END PANEL <i>?</i>	1		\$ 53.00
15	TRIM END PANEL <i>?</i>	1		\$ 700.10
16	FASTENER, TRIM <i>X</i>	1		\$ 122.30
17	BOOTLID <i>bt</i>	6		\$ 18.00
18	WEATHERSTRIP, BOOTLID <i>X</i>	1		\$ 1,115.00
19	ORNAMENT, MAZDA <i>nee</i>	1		\$ 135.60
20	ORNAMENT, 6 <i>nee</i>	1		\$ 28.90
21	MASCOT, REAR <i>nee</i>	1		\$ 16.50
22	ORNAMENT, SKYACTIVE <i>nee</i>	1		\$ 49.20
23	CHROME FINISHER CENTER <i>crn</i>	1		\$ 74.70
24	CHROME FINISHER LHS <i>?</i>	1		\$ 302.00
25	CAP CENTER, FINISHER <i>?</i>	1		\$ 133.40
26	CAP SIDE, FINISHER <i>?</i>	1		\$ 15.20
27	GROMMET, BOOTLID <i>nee</i>	2		\$ 30.40
28	LAMP LHS, BOOTLID <i>?</i>	2		\$ 6.60
29	TAILLAMP LHS <i>crn</i>	1		\$ 768.80
30	FASTENER, TAILLAMP <i>nee</i>	1		\$ 1,592.30
		1		\$ 4.10

ASSIGNMENT

	REAR, TAILLAMP	new /	1	MGHP9-51-146		\$ 3.50
	FRONT, TAILLAMP	new /	1	MGJ6A-51-14Y		\$ 15.70
	GASKET LHS, BOOTLID	new /	1	MG45F-51-3J8		\$ 52.50
	GASKET RHS, BOOTLID	new /	1	MG45F-51-3H8A		\$ 52.50
	GASKET LHS, TAILLAMP	new /	1	MGJA1-51-163		\$ 27.70
36	GASKET RHS, TAILLAMP	new /	1	MGJA1-51-153		\$ 27.70
37	GUARD STONE LHS	X	1	MGHP9-50-4R2A		\$ 17.40
38	LAMP, NUMBER PLATE	X	2	MGHK1-51-270B		\$ 80.60
TOTAL PARTS						\$ 7,813.40
LESS 10%						\$ 781.34
TOTAL PARTS COST						\$ 7,032.06

Labour Description

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID TO REPAIR REAR FLOOR PANEL, REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	945	\$ 3,280.00
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID AND REAR FENDER LH.	1200	\$ 3,600.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	NETT	\$ 180.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X NETT	\$ 180.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE	X NETT	\$ 70.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	\$ 945.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 20.00

TOTAL LABOUR	\$ -	\$ 10,055.00
TOTAL PARTS	\$ -	\$ 7,032.06
TOTAL	\$ -	\$ 17,087.06
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

RKS:

IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Rasul

Hp 20010068

4 days

06/12/19 @ 1440

EXCESS: TBA

REVERT

Resurvey before
paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Ngoh Koh Fui Frank ADDRESS : 542 Bukit Batok Street 52 #08-549 Singapore 650542 TEL : 91050461		WIP : 15618 EXCESS : DATE: 30-Nov-19	
VEH NO :	SLN8420C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071H0118381	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA6	DATE REG.:	19-May-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO		QTY		REVISED	PRICES
1	REAR BUMPER <i>de</i>	1	MGJS1-50-221ABB	✓	\$ 1,266.60
2	BRACKET CENTER <i>neu</i>	1	MKD53-50-251	✓	\$ 5.40
3	RETAINER LHS <i>neu</i>	1	MGJR9-50-2J1	✓	\$ 41.00
4	TOWING COVER LHS <i>neu</i>	1	MG4YL-50-EL1 64	✓	\$ 24.90
5	TOWING COVER RHS <i>neu</i>	1	MG4YL-50-EK1 64	✓	\$ 24.90
6	REAR REINFORCEMENT <i>bt</i>	1	MGHK1-50-260	✓	\$ 538.30
7	RETAINER CENTER, SENSOR <i>neu</i>	2	MKD45-67-UC5A64	✓	\$ 36.40
8	SENSOR CENTER, ULTRASONIC <i>NN</i>	2	MGMK6-67-UC1 64	✓	\$ 361.80
9	TAPE PROTECTOR, SENSOR <i>neu</i>	4	MG51D-50-EM1A	✓	\$ 34.40
10	GROMMET, REAR BUMPER <i>neu</i>	2	M9991-00-501	✓	\$ 6.00
11	GROMMET, REAR BUMPER <i>neu</i>	4	MH260-50-841	✓	\$ 12.00
12	FASTENER, REAR BUMPER <i>neu</i>	6	MB45A-56-146A	✓	\$ 18.00
13	REFLECTOR LHS <i>NN</i>	1	MD350-51-5L0E	✓	\$ 53.00
14	REAR END PANEL <i>NN</i>	1	MGHY1-70-75Z	✓	\$ 700.10
15	TRIM END PANEL <i>NN</i>	1	MGHK1-68-89XA	✓	\$ 122.30
16	FASTENER, TRIM <i>X</i>	6	MGJ21-68-885B02	✓	\$ 18.00
17	BOOTLID <i>bt</i>	1	MGJY0-52-61X	✓	\$ 1,115.00
18	WEATHERSTRIP, BOOTLID <i>NN</i>	1	MGHK1-56-951A	✓	\$ 135.60
19	ORNAMENT, MAZDA <i>neu</i>	1	MGHK1-51-711	✓	\$ 28.90
20	ORNAMENT, 6 <i>neu</i>	1	MGHK1-51-721	✓	\$ 16.50
21	MASCOT, REAR <i>neu</i>	1	MGHK1-51-730	✓	\$ 49.20
22	ORNAMENT, SKYACTIVE <i>neu</i>	1	MGHK1-51-771	✓	\$ 74.70
23	CHROME FINISHER CENTER <i>neu</i>	1	MGHK1-50-810C	✓	\$ 302.00
24	CHROME FINISHER LHS <i>NN</i>	1	MGHK1-50-8F0C	✓	\$ 133.40
25	CAP CENTER, FINISHER <i>NN</i>	1	MGHK2-50-819A	✓	\$ 15.20
26	CAP SIDE, FINISHER <i>NN</i>	2	MGHK1-50-819A	✓	\$ 30.40
27	GROMMET, BOOTLID <i>neu</i>	2	MGA7B-51-146	✓	\$ 6.60
28	LAMP LHS, BOOTLID <i>NN</i>	1	MG45F-51-3G0B	✓	\$ 768.80
29	TAILLAMP LHS <i>neu</i>	1	MGJA1-51-160B	✓	\$ 1,592.30
30	FASTENER, TAILLAMP <i>neu</i>	1	MKD53-51-146B	✓	\$ 4.10

31	FASTENER, TAILLAMP	nee /	1	MGHP9-51-146		\$ 3.50
32	FASTENER, TAILLAMP	nee /	1	MGJ6A-51-14Y		\$ 15.70
33	GASKET LHS, BOOTLID	nee /	1	MG45F-51-3J8		\$ 52.50
34	GASKET RHS, BOOTLID	nee /	1	MG45F-51-3H8A		\$ 52.50
35	GASKET LHS, TAILLAMP	nee /	1	MGJA1-51-163		\$ 27.70
36	GASKET RHS, TAILLAMP	nee /	1	MGJA1-51-153		\$ 27.70
37	GUARD STONE LHS	9. X	1	MGHP9-50-4R2A		\$ 17.40
38	LAMP, NUMBER PLATE	X LNN	2	MGHK1-51-270B		\$ 80.60
TOTAL PARTS						\$ 7,813.40
LESS 10%						\$ 781.34
TOTAL PARTS COST						\$ 7,032.06

Labour Description					
1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. TO REPAIR REAR FLOOR PANEL, REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	945 + 315	\$ 3,780.00	
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID AND REAR FENDER LH.	1200 + 600	\$ 3,600.00	
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	NETT	\$ 180.00	
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	X NETT	\$ 180.00	
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	X NETT	\$ 70.00	
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	\$ 945.00	
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00	
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00	
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00	
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00	
11	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 20	100.00

TOTAL LABOUR	\$ -	\$ 10,055.00
TOTAL PARTS	\$ -	\$ 7,032.06
TOTAL	\$ -	\$ 17,087.06
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Rasul

Hp 20010068

4 days + 1 day
= 5

06/12/19 @ 1440

EXCESS: TBA

REVERT

Resurvey before
paint



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Ngoh Koh Fui Frank ADDRESS : 542 Bukit Batok Street 52 #08-549 Singapore 650542 TEL : 91050461		WIP : 15618 EXCESS : DATE: 30-Nov-19	
VEH NO :	SLN8420C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071H0118381	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA6	DATE REG.:	19-May-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJ51-50-221ABB	\$ 1,266.60	\$ 1,266.60
2	BRACKET CENTER	1	MKD53-50-251	\$ 5.40	\$ 5.40
3	RETAINER LHS	1	MGJR9-50-2J1	\$ 41.00	\$ 41.00
4	TOWING COVER LHS	1	MG4YL-50-EL1 64	\$ 24.90	\$ 24.90
5	TOWING COVER RHS	1	MG4YL-50-EK1 64	\$ 24.90	\$ 24.90
6	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 538.30	\$ 538.30
7	RETAINER CENTER, SENSOR	2	MKD45-67-UC5A64	\$ 36.40	\$ 36.40
8	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 64		\$ 361.80
9	TAPE PROTECTOR, SENSOR	4	MG51D-50-EM1A	\$ 34.40	\$ 34.40
10	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
11	GROMMET, REAR BUMPER	4	MH260-50-841	\$ 12.00	\$ 12.00
12	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 18.00	\$ 18.00
13	REFLECTOR LHS	1	MD350-51-5L0E		\$ 53.00
14	REAR END PANEL	1	MGHY1-70-75Z		\$ 700.10
15	TRIM END PANEL	1	MGHK1-68-89XA		\$ 122.30
16	FASTENER, TRIM	6	MGJ21-68-885B02		\$ 18.00
17	BOOTLID	1	MGJY0-52-61X	\$ 1,115.00	\$ 1,115.00
18	WEATHERSTRIP, BOOTLID	1	MGHK1-56-951A		\$ 135.60
19	ORNAMENT, MAZDA	1	MGHK1-51-711	\$ 28.90	\$ 28.90
20	ORNAMENT, G	1	MGHK1-51-721	\$ 16.50	\$ 16.50
21	MASCOT, REAR	1	MGHK1-51-730	\$ 49.20	\$ 49.20
22	ORNAMENT, SKYACTIVE	1	MGHK1-51-771	\$ 74.70	\$ 74.70
23	CHROME FINISHER CENTER	1	MGHK1-50-810C	\$ 302.00	\$ 302.00
24	CHROME FINISHER LHS	1	MGHK1-50-8F0C		\$ 133.40
25	CAP CENTER, FINISHER	1	MGHK2-50-819A		\$ 15.20
26	CAP SIDE, FINISHER	2	MGHK1-50-819A		\$ 30.40
27	GROMMET, BOOTLID	2	MGA7B-51-146	\$ 6.60	\$ 6.60
28	LAMP LHS, BOOTLID	1	MG45F-51-3G0B		\$ 768.80
29	TAILLAMP LHS	1	MGJA1-51-160B	\$ 1,592.30	\$ 1,592.30
30	FASTENER, TAILLAMP	1	MKD53-51-146B	\$ 4.10	\$ 4.10
31	FASTENER, TAILLAMP	1	MGHP9-51-146	\$ 3.50	\$ 3.50

32	FASTENER, TAILLAMP	1	MGJ6A-51-14Y	\$ 15.70	\$ 15.70
33	GASKET LHS, BOOTLID	1	MG45F-51-3J8	\$ 52.50	\$ 52.50
34	GASKET RHS, BOOTLID	1	MG45F-51-3H8A	\$ 52.50	\$ 52.50
35	GASKET LHS, TAILLAMP	1	MGJA1-51-163	\$ 27.70	\$ 27.70
36	GASKET RHS, TAILLAMP	1	MGJA1-51-153	\$ 27.70	\$ 27.70
37	GUARD STONE LHS	1	MGHP9-50-4R2A		\$ 17.40
38	LAMP, NUMBER PLATE	2	MGHK1-51-270B		\$ 80.60
TOTAL PARTS				\$ 5,376.80	\$ 7,813.40
LESS 10%				\$ 537.68	\$ 781.34
TOTAL PARTS COST				\$ 4,839.12	\$ 7,032.06

Labour Description					
1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID.TO REPAIR REAR END PANEL AND AREAS AFFECTED BY THE ACCIDENT.	\$ 1,260.00	\$ 3,780.00	
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	\$ 1,800.00	\$ 3,600.00	
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 180.00	\$ 180.00	
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 180.00	
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00	
6	MZ-BR-TRIM52	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 945.00	
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00	
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00	
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00	
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00	
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00	
TOTAL LABOUR			\$ 3,560.00	\$ 10,055.00	
TOTAL PARTS			\$ 4,839.12	\$ 7,032.06	
TOTAL			\$ 8,399.12	\$ 17,087.06	
LESS EXCESS			\$ -	\$ -	
TOTAL AFTER EXCESS			\$ 8,399.12		
GST 7%			\$ 587.94	\$ -	
GRAND TOTAL			\$ 8,987.06	\$ -	

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)