

CC6/CT#19021329 / Ak63

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JN1M C2E26Z0005022

LUMILUX DESIGN PTE LTD
50 SERANGOON NORTH AVE 4
#08-18 FIRST CENTRE
S 555856

TP China
Khanchna

Date :06.12.2019
Vehicle No :GBE 1765 U
Make/Model :NISSAN NV350
Accident date :02.12.2019

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Rear windscreen <i>lt</i>	1	\$ 980.1 ✓
2	Rear tailgate <i>Distorted.</i>	1	\$ 1998.4 1742
3	Rear tailgate hinges @ \$59.60 <i>Not new</i>	2	\$ 119.2 X
4	Rear tailgate upper lock <i>Dangd</i>	1	\$ 355.4 ✓
5	Rear tailgate lower lock <i>NE new</i>	1	\$ 60.5 X
6	Rear tailgate side upper lock @ \$82.30	2	\$ 164.6 X
7	Rear tailgate side lower lock @ \$82.30	2	\$ 164.6 +
8	Rear tailgate shock absorber @ \$237.50	2	\$ 475 +
9	Rear tailgate inner board <i>Debond</i>	1	\$ 217.8 ✓
10	Rear tailgate weather strip <i>lt</i>	1	\$ 37.7 ✓
11	Rear tailgate centre Nissan emblem <i>new</i>	1	\$ 87.9 ✓
12	Rear tailgate handle <i>curled.</i>	1	\$ 589.3 511.40
13	Rear tailgate NV350 emblem	1	\$ 121 ✓
14	Rear tailgate 70km sticker <i>new</i>	1	\$ 33 - 15 (SN)
15	Rear tailgate 8 pax sticker	1	\$ 33 - 15 (SN)
16	Rear number plate lamp @ \$107.60 <i>NE new</i>	2	\$ 215.2 X
17	Rear end panel <i>Dented</i>	1	\$ 291.1 ✓
18	Rear end panel top number plate	1	\$ 100.2 X
19	Rear step panel <i>Best.</i>	1	\$ 178.9 ✓
20	Rear bumper <i>Debond</i>	1	\$ 733.9 667.
21	Rear bumper side holder @ \$24.40 <i>new</i>	2	\$ 48.8 ✓
22	Rear bumper clips (1 set) <i>new</i>	1	\$ 66 - 30
23	Rear lamp @ \$247.30 <i>curled</i>	2	\$ 494.6 ✓
24	Rear tailgate centre lock <i>Dangd</i>	1	\$ 196.4 ✓
			\$ 7762.6
	Less 10% Disc		\$ 776.26
	Total		\$ 6986.34

5880.10

5292.09

SN: 30

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LUMILUX DESIGN PTE LTD

50 SERANGOON NORTH AVE 4

#08-18 FIRST CENTRE

S 555856

Date

:06.12.2019

Vehicle No

:GBE 1765 U

Make/Model

:NISSAN NV350

Accident date

:02.12.2019

No	DESCRIPTION	Qty	Amount (S\$)
Special Nett Items			
1	Rear number plate <i>new</i>		\$ 50 <i>x</i>
2	Rear bumper reverse sensor (1 set) <i>myd</i>	<i>200</i>	\$ 380 <i>200</i>
	Total		\$ 430
Labour Cost			
1	To supply rear windscreen sealant		\$ 50 <i>✓</i>
2	Remove & reinstall rear windscreen	<i>2080</i>	\$ 150 <i>120</i>
3	Remove & reinstall reverse sensor		\$ 150 <i>50</i>
4	Remove & reinstall exhaust pipe		\$ 150 <i>x</i>
5	Remove, replace & repair consistent to the accident		\$ 1600 <i>800</i>
6	Respray painting		\$ 1400 <i>1000</i>
7	Tuff kote		\$ 150 <i>60</i>
	Total		\$ 3650
	Grand Total		\$ 11066.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7602.09
4/s: 6K
06 days

Ask For a 6000\$