

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 04 Dec 2019

Preliminary Advice

Vehicle No	: SLH7205X	Accident Date	: 25/11/2019
Make	: MAZDA 3	Policy No.	: 21004906312 - 03
Assignment Date	: 03/12/2019	Excess	: S\$0.00
Date of Inspection	: 03/12/2019	Est. Duration of Repair	: 5 days
Inspection At	: Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,148.11
Revised Amount	:S\$	8,639.78
Check Items (Estimated)	:S\$	1,356.30
Total	:S\$	9,996.08

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	48,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,298.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :