

# BEST Solution Autocare Pte Ltd

LKK Auto Consultancy, 53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Business Reg. No.: 201626438D

6744 0777

6744 2377

## Estimate Quotation

|              |               |
|--------------|---------------|
| Quotation No | Dec 005/2019  |
| Date         | 3/12/2019     |
| Vehicle No   | SLL7417E      |
| Make / Model | Toyota Estima |

To: M/s AIG Asia Pacific Insurance Pte Ltd  
Address: 78 Shenton Way #07-16 Singapore 079120

| Qty   | DESCRIPTION                                                | UNIT      | Amount                       |
|-------|------------------------------------------------------------|-----------|------------------------------|
|       | <b>Items</b>                                               |           |                              |
| 1 pc  | n/s front door <i>Beated</i>                               |           | \$ 1,415.00 ✓                |
| 1 pc  | n/s front door outer handle <i>new</i>                     |           | \$ 417.00 +                  |
| 2 set | n/s front door hinge <i>new</i>                            | \$ 80.00  | \$ 160.00 +                  |
| 1 pc  | n/s front door w/strip <i>new</i>                          |           | \$ 225.00 +                  |
| 1 pc  | n/s sliding door <i>Beated</i>                             |           | \$ 1,485.00 ✓                |
| 1 pc  | n/s sliding door w/strip <i>new</i>                        |           | \$ 234.00 +                  |
| 1 pc  | n/s side panel lower garnish <i>tot. Not new</i>           |           | \$ 690.00 +                  |
| 1 pc  | n/s sliding door power window motor & regulator <i>new</i> |           | \$ 988.00 +                  |
| 1 pc  | n/s sliding door outer handle <i>new</i>                   |           | \$ 210.00 +                  |
| 1 pc  | n/s rear fender <i>Repis</i>                               |           | \$ 985.00 +                  |
| 1 pc  | n/s rear sport rim <i>lot</i>                              |           | \$ 750.00 <del>400/saw</del> |
| 1 pc  | n/s rear fender glass sealant <i>new</i>                   |           | \$ 80.00 +                   |
| 2 pcs | n/s sliding door hinge <i>new</i>                          | \$ 225.00 | \$ 450.00 +                  |
| 1 pc  | n/s sliding door auto door motor <i>new</i>                |           | \$ 3,385.00 +                |
| 1 pc  | n/s sliding door rail <i>new</i>                           |           | \$ 255.00 +                  |
| 1 pc  | n/s sliding door roller <i>Beated</i>                      |           | \$ 267.00 +                  |
| 1 pc  | n/s sliding door lock actuator <i>Damaged</i>              |           | \$ 583.00 +                  |
| 1 pc  | n/s front door lower garnish <i>lot</i>                    | 5848      | \$ 987.00 465                |
| 1set  | n/s front door lower garnish clip <i>new</i>               | 4386      | \$ 40.00                     |
| 1 pc  | n/s rear sliding door lower garnish <i>lot</i>             | S.N: 500  | \$ 987.00 485                |
| 1 set | n/s rear sliding door lower garnish clip <i>new</i>        |           | \$ 40.00                     |
| 1 pc  | n/s rear fender lower garnish <i>lot</i>                   |           | \$ 297.00                    |
| 1 set | n/s rear fender lower garnish clip <i>new</i>              |           | \$ 40.00                     |
| 1 pc  | n/s rear bumper retainer <i>new</i>                        |           | \$ 98.00 56                  |
| 1 pc  | n/s sliding door sensor <i>Damaged</i>                     |           | \$ 675.00 ✓                  |
| 1 pc  | n/s rear shock absorber <i>new</i>                         |           | \$ 275.00 +                  |
|       | <del>Rear Bumpers</del>                                    |           |                              |
|       | <b>Labour Charge</b>                                       |           |                              |
| 1     | to dismantle damaged parts, panel beat, repair             |           | \$ 1,200.00 900              |
| 2     | to putty and spray painting on affected area               |           | \$ 1,000.00 900              |
| 3     | anti rust                                                  |           | \$ 50.00                     |
| 4     | transfer door <i>ittings</i>                               |           | \$ 300.00 160                |
| 5     | remove & refix rear fender glass                           |           | \$ 250.00 +                  |
| 6     | wiring check                                               |           | \$ 50.00 30                  |
| 7     | remove & refix fuel tank                                   |           | \$ 120.00 +                  |
| 8     | rear wheel alignment                                       |           | \$ 120.00 80                 |
|       | <i>Supplementary: 51375</i>                                |           |                              |
|       | <b>Subtotal:</b>                                           |           | \$ 19,108.00                 |

Total: 751975

H/s GIC

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

# BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

## Supplementary Quotation

|              |               |
|--------------|---------------|
| Quotation No | Dec 006/2019  |
| Date         | 4/12/2019     |
| Vehicle No   | SLL7417E      |
| Make / Model | Toyota Estima |

To: M/s AIG Asia Pacific Insurance Pte Ltd

Address: 78 Shenton Way #07-16 Singapore 079120

| Qty       | DESCRIPTION                               | UNIT | Amount      |
|-----------|-------------------------------------------|------|-------------|
|           | Items                                     |      |             |
| 1 pc      | rear bumper <i>torn</i>                   |      | \$ 685.00 ✓ |
| 1 pc      | n/s rear wheel hub bearing <i>NSE new</i> |      | \$ 783.00 ✗ |
| Subtotal: |                                           |      | \$ 1,468.00 |

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

685

513.75