



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19021337/Kga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Date : 29-06-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 8989B	Veh. Inspected	SLE 8940R	
Policy No.	VA1GA417802	Coverage (\$)	0.00	
Claim No.	S9M028Z2	Excess (\$)	0.00	
Assign From		Assign Date	03/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707040119	Colour	METALLIC BLUE	
Odometer	79613	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DAVANTI	9 mm	
L/H Front Tyre	185/60 R15	DAVANTI	9 mm	
R/H Rear Tyre	185/60 R15	DAVANTI	9 mm	
L/H Rear Tyre	185/60 R15	DAVANTI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2019	Inspection Date	04/12/2019	
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		