

Supreme Auto Service Pte Ltd

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

CYCLOPS CARS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Date: 4/12/2019

*Not Authorized
1/12/19
4-5 days*

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA SIENTA / SLE 8940 R	
1 pc	rear boot lid	<i>Bz</i> 1,259.30 ✓
1 pc	rear boot lid lock	<i>net</i> 183.40 ✓
1 pc	rear boot emblem logo	<i>net</i> 67.40 ✓
1 pc	rear boot inner trim	<i>sun</i> 548.30 X
1 pc	rear boot weatherstrip	<i>sun</i> 353.90 X
1 pc	rear bumper	528.90 ✓
1 pc	rear bumper sponge	183.20 ✓
2 pcs	rear bumper side retainer @ 48.50	<i>sun</i> 97.00 X
1 pc	rear bumper reflector	<i>sun</i> 93.80 ✓
1 pc	rear bumper bottom Top	<i>net/hr</i> 461.20 ✓
1 pc	rear windscreen glass moulding	<i>net</i> 176.90 ✓
1 pc	rear end panel garnish	318.40 ✓
1 pc	rear key lock sensor receiver	377.60 ✓
1 pc	rear end bumper panel	<i>net</i> 470.50 X
	Sub-total	5,119.80
	Less 25%	1,279.95
	Sub-total	3,839.85
1 set	reverse sensor s.nett	<i>net</i> 250.00 ✓
1 set	windscreen sealant s.nett	<i>net</i> 80.00 40sn
1 set	windscreen seal s.nett	<i>net</i> 80.00 30sn
	Sub-total	4,249.85
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		

balance brought forward		4,249.85	
To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.		800.00	?
To check wiring system.		50.00	15/
To apply rust proofing on affected areas.		80.00	?
To apply waterproof sealant on affected areas.		80.00	?
To spray painting on affected areas.		800.00	600
To install reverse sensors & reverse camera.		50.00	✓
To remove carpet, trimming and seats to enable repair.		60.00	?
To remove rear windscreen glass to enable repair.		120.00	✓
To transfer ^{boot lid} door accessories	\$80		
	601-		
	total	6,289.85	