

Supreme Auto Service Pte Ltd

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

CYCLOPS CARS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 4/12/2019

*Not Authorized
1/12/19
4-5 days*

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA SIENTA / SLE 8940 R		
1 pc	rear boot lid	1125.10
1 pc	rear boot lid lock	1,259.30 ✓
1 pc	rear boot emblem logo	183.40 ✓
1 pc	rear boot inner trim	67.40 ✓
1 pc	rear boot weatherstrip	548.30 X
1 pc	rear bumper	353.90 X
1 pc	rear bumper sponge	497.60
2 pcs	rear bumper side retainer	528.00 ✓ MTG CRA
1 pc	rear bumper reflector	183.20 X SVC
1 pc	rear bumper bottom Top	97.00 X
1 pc	rear windscreen glass moulding	93.80 ✓
1 pc	rear end panel garnish	401.20 ✓
1 pc	rear key lock sensor receiver	176.90 ✓ MTG CRA
1 pc	rear end panel panel	318.40 ✓ CRA
		377.00 X
		470.50 X
	Sub-total	5,119.80
	Less 25%	1,279.95
	Sub-total	3,839.85
1 set	reverse sensor	s.nett 200.00
1 set	windscreen sealant	s.nett 250.00 ✓ SHORTED
1 set	windscreen seal	s.nett 80.00 40sn
		80.00 30sn
	Sub-total	4,249.85
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		

balance brought forward		4,249.85	
To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.	500.00	800.00	✓
To check wiring system.		50.00	15/
To apply rust proofing on affected areas.	30.00	80.00	✓
To apply waterproof sealant on affected areas.		80.00	✗ NN
To spray painting on affected areas.		800.00	600
To install reverse sensors & reverse camera.		50.00	✓
To remove carpet, trimming and seats to enable repair.		60.00	✗ NN
To remove rear windscreen glass to enable repair.		120.00	✓
To transfer ^{boot lid} door accessories \$80	601-		
total		6,289.85	