Surveyor K	onneth		ASSIGN	1902134 MENT					
From (Person): O	ong Bun		of	C11		T	ote/Time	3.12.19	15.40p.n
Estimated Cost _				Bit					
To leave t Vehicle	No. S	J 92	A/INV/M	V/C8		Insured:	64	6490	×   932886A
at Workshop m/s of 160 Sin 1	ו וזוקווו	# pL	- 02			Tel:	6761	-8000	13288664
Policy No: Dm	VSN 3031	301900	0		Claim No:	SNMIAD	170571	8102	
Smn Imaued					Excess				
Make of Veh:						1	A,O,0	30-11-2	11
CA / REV / REDate/Time 3-12.		HRS	"wp" rson Contac	1	Danny	Ve	H.O.D. En	OUT	
	tion/lestruction/ SLJ 4216 F SLJ 5440	5 - X		rate					
18/2	1/ Ly	8 810	od en	ei/ 6	cenfr	m u	Red 8	7212.6	83, 47%

MINN

Kenner	ASSIGNMENT
From: 4.12. 2019	Veh No: SCJ 8216R Yr Regn. 06 12
Eslimated Cost:	Type: Mcar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: SLJ 9216R	Make: Me C180 Kays CC 1587
at Workshop m/s MBM Westport	Sp.Reading 97737 T/Radio: Insured / Std / NI / NA
11 160 sin Ming Dave +06-02	Sp.Reading 97737 T/Radio; Insured / Std / NL / NA
Insured:	Eng/No:
Policy No.	C/No: WDO .204045.2 A 72024
Claims No.	Gen. Cond: 26od Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inovier / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh	Modi: Nil / S/Rim / STO A/Rim or
	Tyre Size: F: 225/45R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU FIR / SUMI /
repair at the time of inspection.	TOYO / YOKO Dr
Bal. or Market Value. & 4//C	Front D Rear D
IDAC Accident Rport: Consistent? Yes or No	R/Bail. 0 mm R/Bail 0 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. d mm L/Bal. d mm
Est. Repairs: 06 days Res.: Yes or No	D.O.A. 30/1/19 D.O.I. 4/12/19
Lum Sum: % 3 Val.: Yes or No	Survey held at
(hpi)	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: I	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	
Ontoffino, File Pass to? : Preli. Report	Days Of Repair:
1 1 /	
1) 20 2 MN4Y : Final Report	Resurvey No. of Trip. 2 Survey Folk
Dotoffinu, Filo Roboni to?	dd Fee:   Site Insp (\$ )8+Rs_B
3	Interview (\$ ) Floatin
1000 10	Tech, trive (3. ) value.
Lung Small (2 8/00	: Meet and 15
Lung Sum / 1 / 12 8/00	220

## ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	Adji	Rpt	Adj Submitted	Ins Auth'e	d Sh	rtus	
Main	03 Dec 2019		03 Dec 2019 15:40 Assign					Ne	w Assignm Cancel Case	ent
	Main	Re	ference		Claim D	etails	Docu	ments	$\neg$	Show All
	UBFOLDER DET	AILS					1	Created	d by insure	er]
Insured: Main Clair	nant:	ra								
Vehicle Re	TERROR STATE	SLJ92	ED NG YONG ME	NG, ID	: 5740238	-				
Claim Typ		12000000	PERSONAL PROPERTY.	1000	Date of		20/11/2019-1/			
	g. No. (Insured):		NM19D205718	C02		Cover Note No.:	DMCV5N30363019000			0
	gvo. (inauteo);	01349			Excess	io. (Claimant):	744257747			
Repairer:		MBM W 6262 88	heelpower Pte	Ltd (HQ)			S\$0.00 2, Sin Ming AutoCity, 575722 Sin Ming - Tel:			ting - Tet:
Handling 1	Insurer:	China 1 Sen]	aiping Insuranc	ce (Sing	apore) Pt	e. Ltd. (HQ) - Te	Tel: 6389 6111 [Handled by Chong Boon			ng Boon
Claimant's	Insurer:	NTUC I	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Au	to Consultants I	Pte Ltd (	HQ) - Tel:	6256-3561 [1	Final Rpt de	je 12/1	2/20191	
ASSOCIA	TED MAIL REC									
	no mail for this ca						View	IIA. v	Compose	Case Mail
E ALL ASS		S Type Task G	roup Subject	t Han	_	ew All Search	Tasks Completed	Create N	ew Task Created O	Complete n Done

### Nivitha (LKK Auto)

From:

Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent:

Tuesday, 3 December 2019 3:35 PM

To:

Danny Ong ; assignments

Cc:

Chong Boon Sen

Subject:

RE: OUR REF: SNM19D205718/GY5490X/CBS- Liability Status - Accident involving

SLJ9216R & GY5490X (CNT) on 30/11/2019

#### WITHOUT PREJUDICE

Dear Danny,

We refer to your email dated 03.12.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

### Tan Kah Leong

Assistant Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sq.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited, if you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]

Sent: Tuesday, December 3, 2019 3:18 PM

To: Tan Kah Leong < Kah Leong. Tan@sg.cntaiping.com > Cc: Chong Boon Sen < boonsen.chong@sg.cntaiping.com >

Subject: RE: OUR REF: SNM19D205718/GY5490X/CBS- Liability Status - Accident involving

SLJ9216R & GY5490X (CNT) on 30/11/2019


Dear Kah Leong

Kindly arrange "Kenneth Kong - LKK" to conduct the survey

Please note that vehicle is in our premises now. Thanks

Best regards,

'Danny Ong / Claims Advisor



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg MBM Wheelpower Pte Ltd 160 Sin Ming Drive • #06-02 Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: Tan Kah Leong < Kah Leong Tan@sg.cntaiping.com>

Sent: Tuesday, 3 December 2019 3:05 PM To: danny.ong@mbmwheelpower.com.sg

Cc: Chong Boon Sen < boonsen.chong@sg.entaiping.com>

Subject: RE: OUR REF: SNM19D205718/GY5490X/CBS- Liability Status - Accident involving

SLJ9216R & GY5490X (CNT) on 30/11/2019

#### Without Prejudice

Dear Danny,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

#### Tan Kah Leong

Assistant Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, December 3, 2019 2:46 PM

To: danny.ong@mbmwheelpower.com.sg; Chong Boon Sen <br/>
boonsen.chong@sg.cntaiping.com>; Chee So

Chow <sochow.chee@sg.cntaiping.com>; Tan Kah Leong <Kahl.eong.Tan@sg.cntaiping.com>

Subject: OUR REF: SNM19D205718/GY5490X/CBS- Liability Status - Accident involving SLJ9216R &

GY5490X (CNT) on 30/11/2019

Importance: High

Dear Kah Leong.

Please assist to conduct PRS for SLJ9216R

Note: officer in charge - Boon Sen 63896171.

\*\*\* kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Danny Ong [mailto:danny.ong@mbmwheelpower.com.sg]

Sent: Monday, December 02, 2019 3:51 PM

To: Claims Dept of CTI

Cc: ervx.tan@mbmwheelpower.com.sg; eric.woo@mbmwheelpower.com.sg

Subject: Liability Status - Accident involving SLJ9216R & GY5490X (CNT) on 30/11/2019

Importance: High

Dear All

Appreciate if you can advise us on the liability status first for the below loss and arrange a pre-survey.

Kindly refer to the attached GIA report & estimate.

Please note that vehicle is in our premises now.

## \*Kindly provide us with the list of surveyor film\*

Our Client's Vehicle Number:	SLJ9216R
UOI Vehicle Number:	GY5490X
Date/Time of Loss:	30/11/2019 1725 hrs

## Please contact Danny 93288668 for the survey arrangement

Best regards,

Danny Ong | Claims Advisor



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02
 Sin Ming AutoCity • Singapore 575722
 www.mbmwheelpower.com.sg

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	3811	
Vehicle No.:	SLJ9216R	
Vehicle to be Exported:	No	
Intended Deregistration Date:	02 Dec 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	C 180 KOMPRESSOR	
Primary Colour:	Silver	
Manufacturing Year:	2012	
Engine No.:	27191031355592	
Chassis No.:	WDD2040452A720249	
Maximum Power Output:	115.0 kW (154 bhp)	
Open Market Value:	\$30,327.00	
Original Registration Date:	12 Jun 2012	
First Registration Date:	12 Jun 2012	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$30,327.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	11 Jun 2022	
PARF Rebate Amount: Intended COE Rebate Details	\$18,196.00	
COE Expiry Date:	11 Jun 2022	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$64,201.00	
COE Rebate Amount:	\$16,210.00	
Total Rebate Amount:	\$34,406.00	

The information contained herein is correct as at 02 Dec 2019

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	02/12/2019 12:35
Date Of Accident	30/11/2019 17:25
Exact Location Of Accident	CTE + CITY (BEF BRADDELL EXIT)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLJ9216R
Insured/Policyholder	
Name Of Registered Owner	EDWARD NG YONG MENG
NRIC No	S7402381I
Email Address	EDWARDNG@SPH.COM.SG
Mobile Phone No	(LOCAL) +65-97964140
Alternative Phone No	OFFICE-97964140
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C180-1.8 KOMPRESSOR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112227714
Cover Note Number	

# Driver

Name of Driver EDWARD NG YONG MENG

 NRIC No
 \$74023811

 Date Of Birth
 14/01/1974

 Occupation
 OUTDOOR

 Date Of Driving Pass
 06/12/1996

Driving Experience 22 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97964140

Fax Number

Contact Number OFFICE-97964140

EMail Address EDWARDNG@SPH.COM.SG

BLK 241 BISHAN STREET 22 Address

#12-244

570241 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

ambulance?

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

YES Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

2

YES

Number of Passengers (Including Driver)

Passenger 1

NAME:

: KAYLA NG

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE SIZE TOO BIG

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GY5490X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver BALAIYA NAIDU LOGANATHAN

NRIC/Passport Number F8305544T Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### **DETAILS OF INJURED PERSON 1**

Name

EDWARD NG YONG MENG

Approximate Age

Injuries Sustain

**NECK INJURY** 

Injured person in which vehicle?

SLJ9216R

Were seat belts worn?

YES

Was this injured conveyed to hospital by

NO

ambulance?

Address Postcode

Page 3 of 18

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy fiability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of "...
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)


Dute & Time:

\_\_\_

Reporting Centre Personnel's Signature

NRIC/FIN No.:

02 DEC 2019



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1 11 12 1 1 TO 1 1 1 Cds 1
I was travelling along CTE tawards City, approaching Braddell road exit. With the intentions to exit, while
Braddell read exit. With the intensions to exit, while
Checking for traffic to safety filter there was a
sudden heavy impact from the rear. As a result of
the impact, my car was progetted toward geriral
therking for traffic to safety filter there was a sudden heavy impact from the rear. As a result of the impact, my car was projetted toward servial metres. For toward of I was able to avoid the
car infront.
*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Orlver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Marne:

NRIC/FIN No.:

02 DEC 2019

-- GIAPA Sheld P . 35





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 4 Report No. T/20191203/7008

#### REPORT OF A TRAFFIC ACCIDENT

Date/Tin 03/12/20	ne Report M 119 14:01	Made:	Vide Report No.: A/20191130/0001	Station Diary No.:
Informa	nt's Partice	ilars		<b>产品的</b>
	Informant: D NG YON	G MENG	Address: APT BLK 241 BISHAN STREI 570241	ET 22 #12-244 SINGAPORE
ID Type NRIC N	/ ID No.: D / S740238	811	Contact No.: Home/Office:	Mobile: 97964140
National SINGAP	ity: ORE CITIZ	EN	Email: edwardng@sph.com.sg	
Sex: Male	Age: 45	Date of Birth: 14/01/1974	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupat Manage	ion: ment execu	itive	Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 30/11/2019 17:25	Type of Location: Straight Road
Location: CENTRAL EX	(PRESSWAY	Road Surface:		Road Speed Limit:
				in Km/h
Clear Traffic Flow: One Way		Traffic Control: Not Controlled		90 Km/h Fraffic Volume: Moderate

Vehicle No	Type:	Make	Model	Color	Goodition	No of Passenger
GY5490X	Lorry	MITSUBISHI	unknown	White	Slightly Damaged	2
SLJ9216R	Car	MERCEDES BENZ	C 180 KOMPRESS OR	Silver	Seriously Damaged	2

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GY5490X		Not available		





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 4 Report No. T/20191203/7008

#### CONTINUATION OF REPORT

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SLJ9216R	NTUC Income Insurance Co-Operative Limited	5112227714	29/08/2019	28/08/2020	

Details of Perso	n Involved	No. of Street, or other party of the	1500	1	500 H	<b>建</b> 原体系型公司
Any Pedestrian II	nvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Peo	destrian	Cross	ing: NA
Driver				OF STATE	EHECS.	<b>一种企业工作</b>
Name	BALAIYA NAIDU LO	GANATHA	NN.	ID No	-	F8305544T
Related Vehicle	GY5490X (Lorry)			Contact No.		93757985
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: 07/12/2023
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	
Driver	E STATE OF THE STA	A.R. BE		R PROPERTY.	5	
Name	EDWARD NG YON	G MENG		ID No	-	S7402381I
Related Vehicle	SLJ9216R (Car)			Conta	ct No.	97964140
Hospital/Clinic	TAN TOCK SENG HOSPITAL			Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL
Date Treatment	30/11/2019		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	04	Degree of	Injury	Sligh	

#### Brief Details.

I was travelling along CTE towards the City, approaching the Braddell road exit. With the intentions to exit at Braddell, amidst checking the traffic to safely filter to exit, there was a heavy impact from the rear. As a result my car was forcefully pushed several metres, fortunately I was able to avoid the vehicle in front.

My car SLJ9216R was impacted (head to rear) by a Mitsubishi lorry GY5490X, driven by a Balaiya Naidu Loganathan, driver licence F8305544T

Mitsubishi lorry was accelerating to filter as his vehicle was obstructed by an on-coming vehicle, failing o make the allowance he collided head to rear to my vehicle, as per attached video. During the impact, I was forcefully thrown forward and back towards the head rest, and suffered a neck and shoulder pain injury. After the incident I have visited both a GP and TTSH A&E for medical review.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 4 Report No. T/20191203/7008

CONTINUATION OF REPORT





Police Station Of Origin: Traffic Police 10 Ubl Avenue 3 SINGAPORE 408865 Tel No: 65470000 4 of 4 Report No. T/20191203/7008

CONTINUATION OF REPORT

Sketch Plan

NP168

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/12/2019 14:01
Officer In Charge Of Case: TP / TPHQ / WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp	

## MBM WHEELPOWER PTE LTD

Your Ref: GY5490X

Our Ref:

**SLJ9216R** 

To:

CC

Fax

**CHINA TAIPING** 

Not Nothanier

Renny After Painy Date:

11 Ly 88100h From:
Fax:
Conta

6 day, Make

3/12/2019

Danny

64525333

Contact:

93288668

Make / Model:

MERCEDES C180

Chassis No.:

WDD2040452A720249

mbm wheelpower

Engine No.:

27191031355592

Year of Make:

2012

Accident Date:

30 November 2019

ESTIMATE FOR VEHICLE NO. :

SLJ9216R

DESCRIPTION	QTY	List Price
BOOT LID 1550	1	\$ 1,730.80
BOOT LID WEATHERSTRIP	1	\$ n.y 5001n 185.00
BOOT LID INNER TRIM BOARD	1	\$ 247.00
BOOT LID INNER TRIM BOARD CLIPS	8	\$ 48.00
BOOT LID HANDLE	1	\$ 78.00
BOOT LID HINGE BRACKET RH	1	\$ 776.00
BOOT LID HINGE BRACKET LH	1	\$ 176.00
BOOT LID LOCK 285. a	1	\$ 318.50
BOOT LID HANDLE RELEASE	1	\$ 168.40
BOOT LID HANDLE STRIP	1	\$ 211.60
BOOT LID "MERCEDES" LOGO	1	\$ 20.00
BOOT LID "KOCOMPRESSOR" EMBLEM	1	\$ 12 90.00
BOOT LID "C180: EMBLEM	1	s 1 80.00
REAR BUMPER 1460	1	\$ 4 1,638.00
REAR BUMPER TOW COVER	1	\$ 60.00
REAR BUMPER CENTER CHROME 185	. 1	\$ 210.00
REAR BUMPER RH CHROME // 0	1	\$ 165.00
REAR BUMPER LH CHROME //0	1	\$ 165.00
REAR BUMPER RH BRACKET - TO FENDER	1	\$ 75 45.00
REAR BUMPER LOWER END COVER	1	\$ \$\frac{1}{2} 67.00
REAR BUMPER CENTER CARRIER	1	\$ CM 150.00
REAR BUMPER RH CARRIER	1	\$ 07/122.00
REAR BUMPER LH CARRIER	1	\$ 7 122.00

27			
	. 0		252
END PANEL	1084.00	1	\$ <b>3</b> 1,309.00 -
END PANEL TOP	GARNISH	1	\$ カラ ~146.40
END PANEL TOP	GARNISH CLIPS	8	\$ Ma - 48.00
BUMPER RIVETS	S	10	\$ Ma - 60.00
DISTANCE SENS	SOR @ \$250 EACH	41	\$ 1,000.00
TAIL LAMP RH	673.	1	\$ Bn 774.00 -
REAR RH FENDI	ER	1	\$ Λ 1,920.00 λ
		Total:	\$ 11,570.70
		LESS 10%	\$ (1,157.07)
		Parts Total:	\$ 10,413.63
SPECIAL NETT			•
BODY SEALANT		1	\$ 227 80.00 X
LABOUR			
	FIT & REPAIR AFFECTED DAMAGED PA ELD & STRAIGHTEN ON THE AFFECTED	A STATE OF THE PARTY OF THE PAR	\$ Joel 1,500.00
TO CONDUCT A	LL WHEEL COMPUTERISED ALIGNMENT		\$ 100.00 /
TO RESET ENGI	NE WARNING LIGHT (ABS, SRS, ECU ME	MORY & ETC)	\$ 204 300.00 \$
TO APPLY ANTI	RUST COATING		\$ ~~ 150.00 j
TO REMOVE, RE	FIT & UPHOLSTERY TO FACILITATE RE	PAIRS	\$ 601 150.00
TO REMOVE & R	REPLACE BUMPER SENSORS		\$ 60.00 -
TO CHECK & RE	CONNECT ALL NECESSARY WIRING		\$ 201 80.00
	T ON THE AFFECTED AREAS		\$ 1,500.00
		Total:	\$ 14,333.63

LKK Auto Consultants hence notify the Repairer of the following:

- + To reservey beforecolor surray pointing
- To display damaged portful during receivery.
- Parts prices are subject to confirmation
- \* Third party survey is on a "y-most Projudice" home
- No illigal modification(s) is absent
- Supplementary larger transfer in the Company of the is subject to East appropriate from from some Company

Addressing of by Reporter

15312.83

7% GST: \$

Grand Total: \$

Mbm wheelpower pte ltd 160 SIN MING DRIVE #06-02

SIN MING AUTOCITY. t 62828888 f 64525333

1,003.35

15,336.98

Company Registration Number: 200204110W

## MBM WHEELPOWER PTE LTD

Your Ref: GY5490X Our Ref: SLJ9216R

CHINA TAIPING

To:

Date:

Danny CC Fax: 64525333 Contact: 93288668

Make / Model: MERCEDES C180

Chassis No.: WDD2040452A720249 Fax Engine No.: . 27191031355592

Year of Make: 2012

Accident Date: 30 November 2019 SUPPLEMENTARY FOR VEHICLE NO.: SLJ9216R

BOOT LID TRIM COVER RH

TRIM COVER RIVET @ \$8 EACH

TAIL LAMP PANEL RH

DESCRIPTION

615.90 REAR REINFORCEMENT

REAR BUMPER LOWER RH BRACKET

QTY			List Price		
1	\$	15	MIT	55.00	_
5	\$		14	40.00	-
1	\$		3	224.00	-
1	\$		R	680.00	-
1	\$		em	89.00	-
Total:	\$		1	,088.00	
LESS 10%	\$			(108.80)	
Parts Total:	s			979.20	

4/12/2019

From:

wheelpower

Mbm wheelpower pte ltd 160 SIN MING DRIVE

SIN MING AUTOCITY 1 62628888 1 64525333

Company Registration Number : 200204110W

## **REVISED & FINALISE**

# MBM WHEELPOWER PTE LTD

Your Ref: GY5490X Our Ref: SLJ9216R

To: CHINA TAIPING


cc

Fax

FINALISE FOR VEHICLE NO. : SLJ9216R

VEHICLE NO. : SLJ9216F

	DESCRIPTION
	BOOT LID
	BOOT LID WEATHERSTRIP
	BOOT LID INNER TRIM BOARD CLIPS
Check	BOOT LID LOCK
	BOOT LID "MERCEDES" LOGO
	BOOT LID "KOCOMPRESSOR" EMBLEM
	BOOT LID "C180: EMBLEM
	REAR BUMPER
	REAR BUMPER CENTER CHROME
	REAR BUMPER RH CHROME
	REAR BUMPER LH CHROME
Check	REAR BUMPER CENTER CARRIER
Check	REAR BUMPER RH CARRIER
Check	END PANEL
	END PANEL TOP GARNISH
	END PANEL TOP GARNISH CLIPS
	BUMPER RIVETS
	DISTANCE SENSOR @ \$250 EACH
	TAIL LAMP RH
supp.	BOOT LID TRIM COVER RH
supp.	TRIM COVER RIVET @ \$8 EACH
supp.	TAIL LAMP PANEL RH
supp.	REAR REINFORGEMENT
supp.	REAR BUMPER LOWER RH BRACKET



Date: 12/12/2019

From: Danny Fax: 64525333

Contact: 93288668 Make / Model: MERCEDES

Make / Model: MERCEDES C180

Chassis No.: WDD2040452A720249

Engine No.: 27191031355592

Year of Make: 2012

Accident Date: 30 November 2019

QTY		List Price
1	S	1,730.80
1	\$	92.50
8	\$	48.00
1	\$	318,50
1	\$	60.00
1	\$	90.00
1	\$	80.00
1	\$	1,638.00
1	5	210.00
1	\$	165.00
1	\$	165.00
1	\$	150.00
1	\$	122.00
1	\$	1,309.00
1	\$	146.40
8	\$	48.00
10	\$	60.00
1	\$	250.00
1	\$	774.00
1	\$	55.00
5	\$	40.00
of Control	\$	224.00
1	\$	680.00
1	\$	89.00
Total:	\$	8,545.20
LESS 10%	S	(854.52)
Parts Total:	\$	7,690.68

## LABOUR

	\$	8,757.61
Less 10	)%_\$	(973.07)
To	tal: \$	9,730.68
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	900.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	20.00
TO REMOVE & REPLACE BUMPER SENSORS	S	60.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	60.00
TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	\$	200.00
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	s	800.00

Lump Sum: \$

8,750.00

06 Days Repair

Company Registration Number : 200204110W

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19021344/KQF3N2

Date:

21/02/2020

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore)

Pte. Ltd.

Policy No:

DMCVSN30363019000

Claimant Vehicle No:

SLJ9216R

Insured Vehicle

GY5490X

Date of Loss:

30/11/2019

No: Nature of Claim:

TP

Claim No:

SNM19D205718C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLJ9216R

Make & Model:

MERCEDES-BENZ C180, 1.6 Kompressor (A)

Engine No:

27191031355592

Reg. Date:

12/06/2012 (Man. Year: 2012)

Chassis No:

WDD2040452A720249

Colour:

Metallic Grey

Odometer:

97757 km

Engine Capacity: Market Value/New Car Price:

1597 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

225/45R17

Rear Tyre Size:

225/45R17

Front Left Side:

Pirelli 8 mm

Rear Left Side: Rear Right Side:

Pirelli 8 mm Pirelli 8 mm

Pirelli 8 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,472.83	6,874.27	4,598.56	40.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,140.00	1,700.00	44.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,312.83	9,014.27	6,298.56	41.13
Approved Total (Overridden) (S\$		8,100.00		
(S\$)	15,312.83	8,100.00	7,212.83	47.10
+ GST 7.00/7.00% (S\$)	1,071.90	567.00	504.90	47.10
Nett Amount (S\$	16,384.73	8,667.00	7,717.73	47.10
D S				

INSPECTION

Date of Assignment:

03/12/2019

Date Inspected:

04/12/2019 Inspected At:

MBM Wheelpower Pte Ltd (HQ)

160 Sin Ming Drive #06-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair:

6.0 days

Adjuster: KENNETH KONG Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 21 Feb 2020) Part Source: MRM-SG

MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ9216R)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*BOOT LID	Bent	1,730.80 FL	*1,550.00 FL
2	1	*BOOT LID INNER TRIM BOARD	Serviceable	247.00 FL	*-FL
3	8	*BOOT LID INNER TRIM BOARD CLIPS	Necessary	48.00 FL	*48.00 FL
4	1	*BOOT LID HANDLE	Serviceable	78.00 FL	*-FL
5	1	*BOOT LID HINGE BRACKET RH	Repair	176.00 FL	*-FL
6	1	*BOOT LID HINGE BRACKET LH	Repair	176.00 FL	*-FL
7	1	*BOOT LID LOCK	Dented	318.50 FL	*285.00 FL
В	1	*BOOT LID HANDLE RELEASE	Serviceable	168.40 FL	*-FL
9	1	*BOOT LID HANDLE STRIP	Serviceable	211.60 FL	*-FL
10	1	*BOOT LID MERCEDES LOGO	Necessary	60.00 FL	*60.00 FL
11	1	*BOOT LID KOCOMPRESSOR EMBLEM	Necessary	90.00 FL	*90.00 FL
12	1	*BOOT LID C180 EMBLEM	Necessary	80.00 FL	*80.00 FL
13	1	*REAR BUMPER	Bent	1,638.00 FL	*1,460.00 FL
14	1	*REAR BUMPER TOW COVER	Serviceable	60.00 FL	*-FL
15	1	*REAR BUMPER CENTER CHROME	Necessary	210.00 FL	*185.00 FL
16	1	*REAR BUMPER RH CHROME	Necessary	165.00 FL	*110.00 FL
17	1	*REAR BUMPER LH CHROME	Necessary	165.00 FL	*110.00 FL
18	1	*REAR BUMPER RH BRACKET-TO FENDER	Serviceable	45.00 FL	*-FL
19	1	*REAR BUMPER LOWER END COVER	Serviceable	67.00 FL	*-FL
20	1	*REAR BUMPER CENTER CARRIER	Cracked	150.00 FL	*150.00 FL
21	1	*REAR BUMPER RH CARRIER	Distorted	122.00 FL	*122.00 FL
22	1	*REAR BUMPER LH CARRIER	Serviceable	122.00 FL	*-FL
23	1	*END PANEL	Bent	1,309.00 FL	*1,084.00 FL
24	1	*END PANEL TOP GARNISH	Distorted	146.40 FL	*146.40 FL
25	8	*END PANEL TOP GARNISH CLIPS	Necessary	48.00 FL	*48.00 FL
26	10	*BUMPER RIVETS	Necessary	60.00 FL	*60.00 FL
27	1	*DISTANCE SENSOR (4 Pos)	Dented (1 Pc only)	1,000.00 FL	*250.00 FL
28	3	*TAIL LAMP RH	Broken	774.00 FL	*673.00 FL
29	1	*REAR RH FENDER	Repair	1,920.00 FL	*-FL
30	1	*BOOT LID TRIM COVER RH	Missing	55.00 FL	*55.00 FL
31	5	*TRIM COVER RIVET	Necessary	40.00 FL	*40.00 FL
32	1	*TAIL LAMP PANEL RH	Bent	224.00 FL	*224.00 FL
33	1	*REAR REINFORCEMENT	Bent	680.00 FL	*615.90 FL
34	1	*REAR BUMPER LOWER RH BRACKET	Cracked	89.00 FL	*89.00 FL
35	1	*BOOT LID WEATHERSTRIP (50%)	Distorted	166.50 FS	*92.50 FS
36	1	*BODY SEALANT	Not Necessary	80.00FS	*-F\$
F=Fr	anchise part. S=Spc	Nett. L=ListitemDisc.  - List item Discount on	Sub Total (S\$) L Items 10,00/10,00% (S\$)	<b>12,720.20</b> 1,247.37	7,627.80 753.53
			51 10 an ang ang 111 - esem	CHO AMBOURT	9000 (CO) (See
			Total Parts (S\$)	11,472.83	6,874.27

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
Reconnected	Laucun

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,500.00	800.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	100.00	0.00
3	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	300.00	200.00
4	TO APPLY ANTI RUST COATING	New	150.00	0.00
5	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150,00	60.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	60.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	1,000.00
	Gross Labor	ur Cost (S\$)	3,840.00	2,140.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >