

22/03/2012

ASS. REC. BY:

REF:

28/11/19021352/lyd3sr

Special Instruction:

Excess
\$600

Summary:

MAYUS

ASSIGNMENT (Office)

From (Person):

Jennifer Chen

of

A/C

Date/Time:

3:47pm 3/12/19

Estimated Cost:

Bill to:

OD / PP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 5807M

Insured:

at Workshop m/s

Trans Euroleers

Tel:

9111 7463.

of

Subr close

Policy No:

2100479335-03

Claim No:

Sum Insured:

Excess:

TBA 600

D.O.A. 30/11/19

Make of Veh:

(Client's Record)

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:53pm 3/12/19

Person Contacted:

vian

Vehicle IN OUT

Date/Time

Action/Instruction

Johanna

SLE 5807M-X

Tel. 6603 6124

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, December 04, 2019 6:28 PM
To: vion.lim@eurokars.com.sg
Cc: 'Fong, Andy-SY'; 'Fan, Winnie-LW'; ronald.yap@eurokars.com.sg
Subject: RE: - OUR REF: SLE5807M OWN DAMAGE CLAIM

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLE5807M (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Note: According to AIG the rear end panel need to repair back.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, December 03, 2019 3:52 PM
To: 'AIG SGP, Claims-Survey' <AIGSGP_ClaimsSurvey@aig.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: 'Fong, Andy-SY' <Andy-SY.Fong@aig.com>; 'Fan, Winnie-LW' <Winnie-LW.Fan@aig.com>
Subject: RE: - OUR REF: SLE5807M OWN DAMAGE CLAIM

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Your password will expire in 9 days. [Click here to change it.](#)

- OUR REF: SLE5807M OWN DAMAGE CLAIM

From: AIG SGP, Claims-Survey

To: Admin A, assignments

Cc: Fong, Andy-SY, Fan, Winnie-LW

Sent: 12/3/2019 3:47:30 PM

Attachments:  AIG_SLE5807M.xlsx  CL.pdf  DL.pdf  INTERVIEW FORM.pdf  RPT.PDF

Hi LKK,

Kindly assist to survey.

Thanks & regards

Jennifer Chan

From: vion.lim@eurokars.com.sg [mailto:vion.lim@eurokars.com.sg]

Sent: Tuesday, 3 December, 2019 2:17 PM

To: AIG SGP, Claims-Survey

Cc: ronald.yap@eurokars.com.sg

Subject: [EXTERNAL] OUR REF: SLE5807M OWN DAMAGE CLAIM

This message is from an external sender; be cautious with links and attachments.

OUR REF: SLE5807M OWN DAMAGE CLAIM

Dear Winnie,

Please assist to register the above vehicle and arrange survey for the above vehicle today 03/12/19 in **5 UBI Close**.
Car is in the workshop.

Attached is the ACCIDENT REPORT for your perusal.

Thank you.

Best Regards.

 **EUROKARS GROUP**

Vion Lim

Insurance Claims Officer

EUROKARS SERVICES PTE LTD

5 Ubi Close, Singapore 408605

D: (65) 6395 7874 **H:** (65) 9111 7463

E: vion.lim@eurokars.com.sg

Website: www.eurokars.com.sg

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Dec 2019

Preliminary Advice

Vehicle No	: SLE5807M	Accident Date	: 30/11/2019
Make	: MAZDA 5	Policy No.	: 2100479335 - 03
Assignment Date	: 03/12/2019	Excess	: S\$0.00
Date of Inspection	: 03/12/2019	Est. Duration of Repair	: 7.00
Inspection At	: TRANS EUOKARS PTE LTD (UBI) 5 UBI CLOSE SINGAPORE 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages.rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,690.71
Revised Amount	:S\$	10,442.16
Check Items (Estimated)	:S\$	461.07
Total	:S\$	10,903.23

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	69,000.00
COE / PARF Rebate	:S\$	53,652.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,348.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2019 19:19
Date Of Accident	30/11/2019 22:00
Exact Location Of Accident	BLK 691B WOODLANDS DRIVE 73
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE5807M
Insured/Policyholder	
Name Of Registered Owner	MOHAMED RAZALI BIN ABDUL HAMED
NRIC No	S7005749B
Email Address	NOLEFTLEG70@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94240454
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100479335 - 03
Cover Note Number	

Driver

Name of Driver	MOHAMED RAZALI BIN ABDUL HAMED
NRIC No	S7005749B
Date Of Birth	26/02/1970
Occupation	INDOOR
Date Of Driving Pass	03/07/1995
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94240454
Fax Number	
Contact Number	OFFICE-NOPHONE

Address	BLK 690B WOODLANDS DRIVE 75 #13-172
Postcode	732690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans Eurokars Pte Ltd
5 Ubi Close
Singapore 408605
Tel: 6474 3003 / 6749 4333
Fax: 6746 0660

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SLF 5807M

ACCIDENT DATE: 30 Nov 2019

CONTACT NUMBER: 94240454

ACCIDENT TIME: 22:00 hrs

EMAIL: no left leg 70@gmail.com

LOCATION: Loading Bay at Block 691B, Woodlands Drive 73, near USTAR Supermarket.

I was trying to reverse the car into the carpark lot while waiting for my family to complete their purchase. I did not notice the metal pole, which is part of the shelter for the lot. It was newly built and embedded into the floor of the road, and as such, was at my blindspot when I reversed the car. My focus was on the kerb, and I did not notice the pole until my car had backed into it. The reverse sensor also did not pick up the pole until it was too late.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☒ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : MOHAMED MAZAL BIN ABDEL HAMEED
VEHICLE NUMBER : SLG 5807 M
DATE/TIME OF ACCIDENT : 30 Nov 2019 / 2200hrs
PLACE OF ACCIDENT : Blk 69/B, Woodlands Drive 73
THIRD PARTY VEHICLE (IF ANY) : _____

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

From Jooz to home at Woodlands Drive 75.
stopped by Supermart to purchase items.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

No

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Reversed into metal pole of carpark lot shelter.
No other vehicles involved

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No

Name: Mohamed Razel

I Affirmed The Above Information Is Given To My Best Knowledge.

UNDERTAKING

I, Mohamed Razali, (NRIC No. 57005749B), hereby confirm that the Singapore Accident Statement lodged by me on 02 Dec 2019 at 0930 hours pertaining to the accident involving motor car Reg. No: SUE 5807M, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature

: 

Name of Insured / Driver

: Mohamed Razali bin Abdul Hameed

Nric No.

: 57005749B

Date

: 02/12/2019

Signature

: 

Name of Policyholder

: Mohamed Razali bin Abdul Hameed

Nric No.

: 57005749B

Date

: 02/12/2019



**SINGAPORE
POLICE FORCE**
SAFEGUARDING EVERY DAY

Class 3 - 03 Jul 1995



**TRAFFIC POLICE
SINGAPORE POLICE FORCE**
10, UBI AVENUE 3
SINGAPORE 408865
Tel : 65470000
www.police.gov.sg

Private & Confidential

MOHAMED RAZALI BIN ABDUL HAMED

APT BLK 690B WOODLANDS DRIVE 75 #13-172
SINGAPORE 732690

You will receive your photocard driving licence by registered post within 10 to 14 working days from the date of application unless you made a special request to collect at Traffic Police at the time of application

You can drive while awaiting the delivery of your photocard driving licence

Please turn overleaf for important notes.

S7005749B
(3)

C001536002

\$25/-

C2/12/2019

(Please do not detach)



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Mohamed Razali Bin Abdul Hamed
Period of Insurance : 27 Jul 2019 To 26 Jul 2020
Engine No. : PE10358587
Chassis No. : JM6CW1071G0124108

Vehicle No. : SLE5807M
Policy No. : 2100479335-03
Endorsement No. :
Issued Date : 08 Jun 2019

ABOUT THE COVER

Make/Model : MAZDA 5 2.0 SKYACTIV

Engine Capacity/Tonnage : 1,998.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2016

Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Mohamed Razali Bin Abdul Hamed - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Trans Eurocars Pte Ltd. Add: 27A Tanjong Pagar Road, Singapore 060042 63310008

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

103599190

3F (AP) PTE LTD - MAZDA

MAXWELL ROAD #01-100 ANNEX B MIND COMPLEX

SINGAPORE 050111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Shenton Way #07-19 AIG Building 5079120 | T: +65 6419 3000 | www.aig.sg

J. Tanik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	749B
Vehicle Details	
Vehicle No.:	SLE5807M
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	PE10358587
Chassis No.:	JM6CW1071G0124108
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$20,747.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$21,046.00 105'23
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$15,784.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$37,868.00
Total Rebate Amount:	\$53,652.00

The information contained herein is correct as at 04 Dec 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

THE MAZDA CX-3.
NOW FROM \$89,888.
 CX-3 SP variant is featured



CLICK HERE



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

1.6L Inline 4 Cylinder Turbocharged Engine 120 Bhp



High \$29k ARFI Lowest
 Depreciation In The Market!
 Carz World Pte Ltd StarAd

**PRIME MOTOR &**

CHENG YONG CREDIT ENTERPRISES PTE LTD

With over 200 units of vehicles
 to choose from, ranging from
 all European to Japanese Makes.

Post an Ad

Advertiser Login

Ways of Selling







Browse by Category

Sort by Date Posted

11 vehicles

mazda 5

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	mazda 5		Any	Any	2016	Any	Any	Any
	Mazda 5	Mazda 5 2.0A Sunroof	\$73,800	\$9,390 /yr	31-Aug-2016	1,998 cc	57,000 km	MPV
TransEuroKars Agent Servicing Done, Warranty Just Ended. 100% Loan Approval With Low-Interest Rate! The Only 2016 STA Evaluated Mazda 5 Sunroof In Market, High Paper And Body Price Of \$63K Thereabout If Scrap. Lowest Mileage Done At 15,000KM Yearly. Road T...								
Posted: 03-Dec-2019 Tags: 2016 Mazda 5, 2016 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda 5	Mazda 5 2.0A Sunroof	\$72,800	\$8,900 /yr	28-Dec-2016	1,998 cc	61,917 km	MPV
SMQ Series! Fully Mazda Warranty And Serviced! Very Beautiful And Luxury Metallic Grey 7-Seater MPV! Best Unit With Lowest Depreciation In Market! Trade In And High Loan To Full Loan Available! Rare Premium Stock! Contact/ Whatapps Our Top Best Appointe...								
Posted: 03-Dec-2019 Tags: 2016 Mazda 5, 2016 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda 5	Mazda 5 2.0A Sunroof	\$69,800	\$9,350 /yr	10-May-2016	1,998 cc	110,000 km	MPV
Offer Bank Interest Rate From 2.28%. Serviced By Agent! Only One Owner! Reliable MPV With Low Maintenance Cost. Good Fuel Efficiency! Accident Free! 100% Loan Approval With Flexible In House Financing/Bank Loan Available. Trade In Available. Feel Free To C...								
Hua Yang Credit Pte Ltd								
Posted: 03-Dec-2019 Tags: 2016 Mazda 5, 2016 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda 5	Mazda 5 2.0A Sunroof	\$72,800	\$8,910 /yr	30-Dec-2016	1,998 cc	43,900 km	MPV
One Owner. Very Low Mileage. Immaculate Condition. Service By Agent. Accident Free. Call/SMS For More Details.								
Posted: 02-Dec-2019 Tags: 2016 Mazda 5, 2016 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	KHY Motors Pte Ltd - Specialist for Mazda Car repair, servicing & maintenance							
KHY Motors strives to provide great customer service and great prices for all our customers!								
More info about this shop								
	Mazda 5	Mazda 5 2.0A Sunroof	\$75,668	\$9,360 /yr	09-Nov-2016	1,998 cc	66,000 km	MPV
Eurokars Mazda Unit. Full Agent Maintained Since Day 1. One Owner. Most Popular MPV With Dual Sliding Doors Unit. Grey Metallic Exterior With Black Interior. Attractive Interest Rate From 2.48%. Please Call Our Sales Consultant For More Enquiries Now. Deal Not To...								
Pre-Owned								
ad: 01-Dec-2019 Tags: 2016 Mazda 5, 2016 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								

Compare



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L

78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

ATTN :

MOTOR CLAIMS

FAX :

NAME : Mr Mohamed Razali Bin Abdul Hamed

WIP : 15770

ADDRESS : Apt Blk 690b Woodlands Drive 75

EXCESS :

#13-172

DATE: 3-Dec-19

Singapore 732690

TEL : 94240454

VEH NO :

SLE5807M

DATE IN :

CONTACT PERSON :

Vion 63957877

CHASSIS NO :

JM6CW1071G0124108

MILEAGE :

TYPE OF CLAIM :

OWN DAMAGED CLAIM

MODEL :

MAZDA5

DATE REG.:

27-Jul-16

POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC513-50-221EBB	✓	\$ 961.20
2	1	MC513-50-2H1B	X	\$ 47.60
3	1	MC513-51-067A	✓	\$ 5.70
4	1	MD350-51-5M0E	✓	\$ 53.00
5	1	MC513-50-361	✓	\$ 21.60
6	1	MC235-56-B9XC	✓	\$ 155.40
7	2	MC235-50-ES1	✓	\$ 9.40
8	4	MBHN1-50-021A	✓	\$ 10.80
9	2	MGD7A-50-EA1	✓	\$ 6.40
10	2	MB45A-56-146A	✓	\$ 6.00
11	4	MBN8F-50-355	✓	\$ 22.80
12	1	MCG15-70-750B	✓	\$ 515.70
13	1	MC513-68-89XD	✓	\$ 80.40
14	1	MC513-68-894A	✓	\$ 13.70
15	1	MC261-68-850G01	✓	\$ 491.40
16	8	MGJ21-68-885B02	✓	\$ 24.00
17	2	MG043-62-864A	✓	\$ 7.00
18	1	MCGY3-62-02XF	✓	\$ 1,637.00
19	2	MGHP9-58-867	✓	\$ 24.00
20	1	MC513-68-960B	✓	\$ 432.00
21	5	MGJ21-68-885B02	✓	\$ 15.00
22	1	MC513-62-310A	✓	\$ 256.20
23	1	MD652-62-361	✓	\$ 57.90
24	3	MEG21-51-SJ3	✓	\$ 17.10
25	1	MC513-50-8E0A	✓	\$ 31.20
26	1	MC597-51-771	✓	\$ 80.00
27	1	MC513-51-3G0G	✓	\$ 388.50
28	1	MC513-51-3F0H	✓	\$ 409.40
29	1	MC513-51-150D	✓	\$ 601.70
30	1	MEA02-51-146A	✓	\$ 3.20

31	GROMMET, TAILLAMP	1	MEA01-51-146B	11 X	\$ 2.90	X
32	FASTENER, TAILLAMP	1	MGJ6A-51-14Y	11 X	\$ 15.70	X
33	GROMMET, TAILLAMP	2	MB01W-51-142B	11 X	\$ 6.40	X
34	REAR WINDSCREEN	1	MCG15-63-930B	shards	\$ 1,125.40	✓
35	REAR WINDSCREEN MOULDING	1	MC513-50-611	nee	\$ 60.50	✓
36	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	nee	\$ 7.20	✓
37	FASTENER, REAR WINDSCREEN	6	MD204-50-896A	nee	\$ 16.80	✓
38	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	nee	\$ 51.20	✓
39	FASTENER, REAR WINDSCREEN	2	MC273-50-896	nee	\$ 16.40	✓
40	SUB TRUNK, REAR FLOOR PANEL	1	MC235-68-8MXD00	11 X	\$ 359.70	X
41	SPARE WHEEL BOARD	1	MC235-68-83XC02	11 X	\$ 496.30	X
42	COVER, WIPER ARM	1	MD267-67-395A	11 X	\$ 12.60	X
43	REAR ARM, WIPER	1	MC235-67-421A	11 X	\$ 98.50	X
44	WIPER BLADE REAR	1	MC247-67-330	11 X	\$ 24.80	X
45	WEATHERSTRIP, TAILGATE	1	MC513-62-761C	11 X	\$ 177.50	X
46	TRIM INNER LHS, TAILGATE	1	MC513-68-950B	11 X	\$ 28.40	X
47	TRIM INNER RHS, TAILGATE	1	MC513-68-940B	11 X	\$ 28.40	X
48	FINSIHER, TAILGATE	1	MC513-50-810F 53	nee	\$ 447.90	✓
TOTAL PARTS					\$ 9,361.90	
LESS 10%					\$ 936.19	
TOTAL PARTS COST					\$ 8,425.71	

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	1575	\$ 3,780.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.	1500	\$ 3,000.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT ✓	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	nee	NETT ✓ \$ 120.00
5	MZ-BR-SOLARF	TO REPLACE WINDSCREEN SOLAR FILM.	sak agumf. nee	NETT ✓ \$ 280.00
6	MZ-BR-DEBRIS	TO REMOVE AND VACUMN BROKEN GLASS DEBRIS.	nee	NETT ✓ \$ 100.00
7		TO REMOVE AND INSTALL SPOILER TAILGATE.	11 X	\$ 180.00
8	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	✓	\$ 315.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	swkd. 180	NETT \$ 315.00
10	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	✓	NETT \$ 180.00

11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. <i>11X</i>	NETT	\$ 70.00
12	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	<i>330</i>	\$ 945.00
13	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	<i>80</i>	\$ 350.00
14	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>120</i>	\$ 250.00
15	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>120</i>	\$ 250.00
16	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>180</i>	\$ 350.00
17	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>11X</i>	NETT	\$ 120.00
18	MZ-BR-SUNDRI	SUNDRIES. <i>111 30</i>	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 11,265.00
TOTAL PARTS	\$ -	\$ 8,425.71
TOTAL	\$ -	\$ 19,690.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

19972-77

Authorised Signature

LKk Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

உயிர்வாழ்வு:

உயிர்வாழ்வு:

УСТАНОВИТЕ СЕ УБОДНИК

- [illegible]



TRANS EUROKARS PTE LTD



SUPPLEMENTARY ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Mohamed Razali Bin Abdul Hamed ADDRESS: Apt Blk 690b Woodlands Drive 75 #13-172 Singapore 732690 TEL: 94240454		WIP: 15770 EXCESS: DATE: 3-Dec-19	
VEH NO:	SLE5807M	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6CW1071G0124108	MILEAGE:		TYPE OF CLAIM:	OWN DAMAGED CLAIM
MODEL:	MAZDA5	DATE REG.:	27-Jul-16	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	CLIP, SPOILER	3	MC514-51-958A	all	\$ 23.10
2	CLIP, SPOILER	1	MC525-51-958A	all	\$ 8.70
3	ORNAMENT, MAZDA	1	MCGY0-51-711	all	\$ 45.30
4	ORNAMENT, 5	1	MCGY0-51-721	all	\$ 36.30
TOTAL PARTS					\$ 113.40
LESS 10%					\$ 11.34
TOTAL PARTS COST					\$ 102.06
Labour Description					
1	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		Reported	NETT \$ 180.00
TOTAL LABOUR				\$ -	\$ 180.00
TOTAL PARTS				\$ -	\$ 102.06
TOTAL				\$ -	\$ 282.06
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Mohamed Razali Bin Abdul Hamed ADDRESS : Apt Blk 690b Woodlands Drive 75 #13-172 Singapore 732690 TEL : 94240454		WIP : 15770 EXCESS : \$ 600.00 DATE: 3-Dec-19	
VEH NO :	SLE5807M	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6CW1071G0124108	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA5	DATE REG.:	27-Jul-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	\$ 961.20	\$ 961.20
2	RETAINER RHS	1	MC513-50-2H1B		\$ 47.60
3	BRACKET RHS	1	MC513-51-067A		\$ 5.70
4	REFLECTOR RHS	1	MD350-51-5M0E		\$ 53.00
5	GUARD RHS, REAR BUMPER	1	MC513-50-361		\$ 21.60
6	REAR REINFORCEMENT	1	MC235-56-B9XC		\$ 155.40
7	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ 9.40	\$ 9.40
8	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
9	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.40	\$ 6.40
10	FASTENER, REAR BUMPER	2	MB45A-56-146A	\$ 6.00	\$ 6.00
11	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 22.80	\$ 22.80
12	REAR END PANEL	1	MCG15-70-750B		\$ 515.70
13	TRIM, END PANEL	1	MC513-68-89XD		\$ 80.40
14	BEZEL, LOCK	1	MC513-68-894A		\$ 13.70
15	TIRM RHS, BOOTSIDE	1	MC261-68-850G01		\$ 491.40
16	FASTENER, TRIM	8	MGJ21-68-885B02	\$ 24.00	\$ 24.00
17	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 7.00	\$ 7.00
18	TAILGATE	1	MCGY3-62-02XF	\$ 1,637.00	\$ 1,637.00
19	VALVE ONEWAY	2	MGHP9-58-867	\$ 24.00	\$ 24.00
20	TRIM LOWER, TAILGATE	1	MC513-68-960B		\$ 432.00
21	FASTENER, TRIM	5	MGJ21-68-885B02	\$ 15.00	\$ 15.00
22	LOCK, TAILGATE	1	MC513-62-310A		\$ 256.20
23	STRIKER, LOCK	1	MD652-62-361		\$ 57.90
24	CLIP, FINISHER	3	MEG21-51-SJ3	\$ 17.10	\$ 17.10
25	GARNISH RHS, TAILLAMP	1	MC513-50-8E0A	\$ 31.20	\$ 31.20
26	ORNAMENT, SKYACTIVE	1	MC597-51-771	\$ 80.00	\$ 80.00
27	LAMP LHS, TAILGATE	1	MC513-51-3G0G		\$ 388.50
28	LAMP RHS, TAILGATE	1	MC513-51-3F0H	\$ 409.40	\$ 409.40
29	TAILLAMP RHS	1	MC513-51-150D		\$ 601.70
30	GROMMET, TAILLAMP	1	MEA02-51-146A		\$ 3.20
31	GROMMET, TAILLAMP	1	MEA01-51-146B		\$ 2.90

32	FASTENER, TAILLAMP	1	MGJ6A-51-14Y		\$ 15.70
33	GROMMET, TAILLAMP	2	MB01W-51-142B		\$ 6.40
34	REAR WINDSCREEEN	1	MCG15-63-930B	\$ 1,125.40	\$ 1,125.40
35	REAR WINDSCREEN MOULDING	1	MC513-50-611	\$ 60.50	\$ 60.50
36	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	\$ 7.20	\$ 7.20
37	FASTENER, REAR WINDSCREEN	6	MD204-50-896A	\$ 16.80	\$ 16.80
38	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	\$ 51.20	\$ 51.20
39	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 16.40	\$ 16.40
40	SUB TRUNK, REAR FLOOR PANEL	1	MC235-68-8MXD00		\$ 359.70
41	SPARE WHEEL BOARD	1	MC235-68-83XC02		\$ 496.30
42	COVER, WIPER ARM	1	MD267-67-395A		\$ 12.60
43	REAR ARM, WIPER	1	MC235-67-421A		\$ 98.50
44	WIPER BLADE REAR	1	MC247-67-330		\$ 24.80
45	WEATHERSTRIP, TAILGATE	1	MC513-62-761C		\$ 177.50
46	TRIM INNER LHS, TAILGATE	1	MC513-68-950B		\$ 28.40
47	TRIM INNER RHS, TAILGATE	1	MC513-68-940B		\$ 28.40
48	FINSIHER, TAILGATE	1	MC513-50-810F 53	\$ 447.90	\$ 447.90
SUPPLEMENTARY ITEMS					
1	CLIP, SPOILER	3	MC514-51-958A	\$ 23.10	\$ 23.10
2	CLIP, SPOILER	1	MC525-51-958A	\$ 8.70	\$ 8.70
3	ORNAMENT, MAZDA	1	MCGY0-51-711	\$ 45.30	\$ 45.30
4	ORNAMENT, S	1	MCGY0-51-721	\$ 36.30	\$ 36.30
TOTAL PARTS				\$ 5,100.10	\$ 9,475.30
LESS 10%				\$ 510.01	\$ 947.53
TOTAL PARTS COST				\$ 4,590.09	\$ 8,527.77

Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER AND TAILGATE. TO REPAIR REAR END PANEL AND AREAS AFFECTED BY THE ACCIDENT.		\$ 1,575.00	\$ 3,780.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.		\$ 1,500.00	\$ 3,000.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		\$ 560.00	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		\$ 120.00	\$ 120.00
5	MZ-BR-SOLARF	TO REPLACE WINDSCREEN SOLAR FILM.		\$ 280.00	\$ 280.00
6	MZ-BR-DEBRIS	TO REMOVE AND VACUUM BROKEN GLASS DEBRIS.		\$ 100.00	\$ 100.00
7		TO REMOVE AND INSTALL SPOILER TAILGATE.			\$ 180.00
8	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM. TO REMOVE AND INSTALL SPOILER TAILGATE.		\$ 315.00	\$ 315.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		\$ 180.00	\$ 315.00

10	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 180.00	\$ 180.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
12	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 330.00	\$ 945.00
13	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 80.00	\$ 350.00
14	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 120.00	\$ 250.00
15	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
16	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
17	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		\$ 120.00
18	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 5,670.00 \$ 11,265.00
			TOTAL PARTS	\$ 4,590.09 \$ 8,527.77
			TOTAL	\$ 10,260.09 \$ 19,792.77
			LESS EXCESS	\$ 600.00 \$ -
			TOTAL AFTER EXCESS	\$ 9,660.09
			GST 7%	\$ 676.21 \$ -
			GRAND TOTAL	\$ 10,336.30 \$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

MZ-FMS-G	SUPPLY & INSTALL M5 AUDIO NAV SET & R/CAMERA (TO 91620				.00
MZ-SF M5	SUPPLY & INSTALL SOLAR FILM 91622				.00
MZ-FVC M	INSTALL FRONT VIDEO CAMERA				.00
MZ-LS M5	SUPPLY & INSTALL M5 L/SEAT (CLASSIC) 91741				.00
11-CARPETM5	CARPET MAZDA 5 5DR.1	1.0	.00		.00
11-FOLDER12-	OWNERS M/FOLDER M12-	1.0	.00		.76
1000-L1-600	MIRROR CONTROLLER	1.0	.20		.40
11-DVR610	DVR, PHILIPS ADR610 1	1.0	.00		.00
11-KIT	DVR ADAPTOR CABLE	1.0	80		.80

Parts	239.96
Surcharge	0.00
Labour	3,017.50
Menus	0.00

Net	.46
G.S.T. 7%	.00
Total	.46
Paid	.00
Amount Due	46

2 pages

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: Mr Mohamed Razali Bin Abdul Hamed
ADDRESS: Apt Blk 690b woodlands Drive 75
#13-172
Singapore 732690

MODEL: MAZDA5 SKYACTIVE
CHASSIS NO: JM6CW1071G0124108
ENGINE NO: PE10358587
DESCRIPTION: P.D.I.

PAGE NO: 1
INVOICE NO: 29151295
DATE IN
DATE PRINTED: 15/08/2016
JOB NO: 15477
CSO/OP CODE: Joycelyn Lee
TEL NO:
REGN NO: SLE5807M
REGN DATE:
MILEAGE: 3
REQUISITION NO: 13640

MZ-PT M5	PETROL TOPPING	0.00
	Std PDI Pkg M5-SA	
MZ-PDI M	PRE DELIVERY INSPECTION & INSTALL IU	.00
	Std PDI Pkg M5-SA	
MZ-FM M5	INSTALL FOLDING MIRROR	.00
	Std PDI Pkg M5-SA	
MZ-PV M5	POLISH A UNIT OF VEHICLE	0.00
	Std PDI Pkg M5-SA	
MZ-RP M5	SUPPLY 1 SET OF REGN PLATE	0.00
	Std PDI Pkg M5-SA	
MZ-IU M5	SUPPLY 1 UNIT OF IU	0.00
	Std PDI Pkg M5-SA	
MZ-IP M5	SUPPLY & INSTALL PIANO BLACK INTERIOR PANEL	.00
	91619	
MZ-RS MZ	SUPPLY & INSTALL R/SENSOR	.00
	91620	
MZ-ET M5	SUPPLY & INSTALL 1 PC EXHAUST TIP	.50
	91620	

COPY DOCUMENT

ID:t05

INTERNAL INVOICE

CODE: I9104 I04
CUSTOMER: Mr Mohamed Razali Bin Abdul Hamed
ADDRESS: Apt Blk 690b woodlands Drive 75
#13-172
Singapore 732690
SINGAPORE
MODEL: MAZDA5 SKYACTIVE
CHASSIS NO: JM6CW1071G0124108
ENGINE NO: PE10358587
DESCRIPTION: P.D.I.

PAGE NO: 2
INVOICE NO: 29151295
DATE
DATE PRINTED: 15/08/2016
JOB NO: 15477
CSO/OP CODE: Joycelyn Lee
TEL NO:
REGN NO: SLE5807M
REGN DATE:
MILEAGE: 3
REQUISITION NO: 13640

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2019 11:11		03 Dec 2019 17:21 Edit Adj Rpt	S\$10,260.09 Edit Estimates	S\$10,260.09 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHAMED RAZALI BIN ABDUL HAMED, ID: S7005749B, Tel: +6594240454, Email: noleftleg70@gmail.com		
Vehicle Reg. No.:	SLE5807M	Date of Loss:	30/11/2019 22:00 - :59 [40 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1329246045SG	Policy/Cover Note No.:	2100479335 - 03 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban.nadaraja.nadaraja@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/12/2019]		
Driver/Custodian:	MOHAMED RAZALI BIN ABDUL HAMED (49 / Male), NRIC: S7005749B, Tel: +6594240454 Email: noleftleg70@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (04/12/2019): SLE5807M / OD / 30/11/2019 / Coverage & Excess update
- AIG_SG (04/12/2019): Alert - Adj Mandate Approved (S\$10903.23) - SLE5807M - Claim Handler: Lim, Sheng...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



























*SLE5807M (1329246045SG)

OD

Nov 30 2019 10:00PM

[MOHAMED RAZALI BIN ABDUL HAMED]

Trans Eurokars Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 12:29	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 07:33	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	04/12/19 07:33	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/12/19 07:34	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
35	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
36	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
37	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
38	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
39	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
40	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
41	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
42	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
43	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
44	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
45	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
46	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
47	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
48	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
49	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
50	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
51	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
52	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
53	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
54	04/12/19 07:34	General View	Load JPG	<input checked="" type="checkbox"/>
55	15/01/20 08:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	15/01/20 08:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	15/01/20 08:30	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 12:26	GIA	Load PDF	
2	04/12/19 12:26	INTERVIEW FORM	Load PDF	
3	04/12/19 12:27	UNDERTAKING	Load PDF	
4	04/12/19 12:27	Driver's Driving License	Load PDF	
5	04/12/19 12:28	CI	Load PDF	
6	04/12/19 12:28	ESTIMATE	Load PDF	
7	03/02/20 15:01	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View In Browser
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	1 per page	<input checked="" type="checkbox"/>
1	06/12/19 19:44	Accident Statement	Load HTM	
2	06/12/19 19:44	Accident Statement	Load HTM	
3	06/12/19 19:49	Accident Statement	Load HTM	
4	06/12/19 19:50	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	02/12/19 19:23	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	02/12/19 19:23	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	02/12/19 19:23	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	02/12/19 19:23	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=892784&extid=324784&corole=4&... 3/3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19021352/UYD3S2
Date: 03/02/2020

REFERENCE

Insured/Claimant: MOHAMED RAZALI BIN ABDUL HAMED
Date of Loss: 30/11/2019

Policy No: 2100479335 - 03
Nature of Claim: OD

Claim No: 1329246045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE5807M
Make & Model: MAZDA 5, 2.0 (A)
Reg. Date: 27/07/2016 (Man. Year: 2016)
Colour: Grey
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$69,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: PE10358587
Chassis No: JM6CW1071G0124108
Odometer: 85426 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Sumitomo 6 mm Rear Left Side: Sumitomo 6 mm
Front Right Side: Sumitomo 6 mm Rear Right Side: Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,012.77	4,800.09	4,212.68	46.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,960.00	5,460.00	5,500.00	50.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,972.77	10,260.09	9,712.68	48.63
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,372.77	9,660.09	9,712.68	50.14
+ GST 7.00/7.00% (S\$)	1,356.09	676.21	679.88	50.14
Nett Amount (S\$)	20,728.86	10,336.30	10,392.56	50.14

INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 03/12/2019

Inspected At:

Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	961.20 FL	*961.20 FL
2	1		*RETAINER RHS	Not Necessary	47.60 FL	*- FL
3	1		*BRACKET RHS	Not Necessary	5.70 FL	*- FL
4	1		*REFLECTOR RHS	Not Necessary	53.00 FL	*- FL
5	1		*GUARD RHS, REAR BUMPER	Not Necessary	21.60 FL	*- FL
6	1		*REAR REINFORCEMENT	Not Necessary	155.40 FL	*- FL
7	2		*GROMMET, REAR BUMPER	Necessary	9.40 FL	*9.40 FL
8	4		*GROMMET, REAR BUMPER	Necessary	10.80 FL	*10.80 FL
9	2		*FASTENER, REAR BUMPER	Necessary	6.40 FL	*6.40 FL
10	2		*FASTENER, REAR BUMPER	Necessary	6.00 FL	*6.00 FL
11	4		*RIVET, REAR BUMPER	Necessary	22.80 FL	*22.80 FL
12	1		*REAR END PANEL	Repair	515.70 FL	*- FL
13	1		*TRIM, END PANEL	Not Necessary	80.40 FL	*- FL
14	1		*BEZEL, LOCK	Not Necessary	13.70 FL	*- FL
15	1		*TRIM RHS, BOOTSIDE	Not Necessary	491.40 FL	*- FL
16	8		*FASTENER, TRIM	Necessary	24.00 FL	*24.00 FL
17	2		*TAPE PROTECTOR, REAR BUMPER	Necessary	7.00 FL	*7.00 FL
18	1		*TAILGATE	Badly Dented	1,637.00 FL	*1,637.00 FL
19	2		*VALVE ONEWAY	Necessary	24.00 FL	*24.00 FL
20	1		*TRIM LOWER, TAILGATE	Not Necessary	432.00 FL	*- FL
21	5		*FASTENER, TRIM	Necessary	15.00 FL	*15.00 FL
22	1		*LOCK, TAILGATE	Not Necessary	256.20 FL	*- FL
23	1		*STRIKER, LOCK	Not Necessary	57.90 FL	*- FL
24	3		*CLIP, FINISHER	Necessary	17.10 FL	*17.10 FL
25	1		*GARNISH RHS, TAILLAMP	Necessary	31.20 FL	*31.20 FL
26	1		*ORNAMENT, SKYACTIVE	Necessary	80.00 FL	*80.00 FL
27	1		*LAMP LHS, TAILGATE	Not Necessary	388.50 FL	*- FL
28	1		*LAMP RHS, TAILGATE	Cracked	409.40 FL	*409.40 FL
29	1		*TAILLAMP RHS	Not Necessary	601.70 FL	*- FL
30	1		*GROMMET, TAILLAMP	Not Necessary	3.20 FL	*- FL
31	1		*GROMMET, TAILLAMP	Not Necessary	2.90 FL	*- FL
32	1		*FASTENER, TAILLAMP	Not Necessary	15.70 FL	*- FL
33	2		*GROMMET, TAILLAMP	Not Necessary	6.40 FL	*- FL
34	1		*REAR WINDSCREEN	Shorted	1,125.40 FL	*1,125.40 FL
35	1		*REAR WINDSCREEN MOULDING	Necessary	60.50 FL	*60.50 FL
36	1		*SPACER, REAR WINDSCREEN	Necessary	7.20 FL	*7.20 FL
37	6		*FASTENER, REAR WINDSCREEN	Necessary	16.80 FL	*16.80 FL
38	4		*SPACER, REAR WINDSCREEN	Necessary	51.20 FL	*51.20 FL
39	2		*FASTENER, REAR WINDSCREEN	Necessary	16.40 FL	*16.40 FL
40	1		*SUB TANK, REAR FLOOR PANEL	Not Necessary	359.70 FL	*- FL
41	1		*SPARE WHEEL BOARD	Not Necessary	496.30 FL	*- FL
42	1		*COVER, WIPER ARM	Not Necessary	12.60 FL	*- FL
43	1		*REAR ARM, WIPER	Not Necessary	98.50 FL	*- FL
44	1		*WIPER BLADE REAR	Not Necessary	24.80 FL	*- FL
45	1		*WEATHERSTRIP, TAILGATE	Not Necessary	177.50 FL	*- FL
46	1		*TRIM INNER LHS, TAILGATE	Not Necessary	28.40 FL	*- FL
47	1		*TRIM INNER RHS, TAILGATE	Not Necessary	28.40 FL	*- FL
48	1		*FINISHER, TAILGATE	Cracked	447.90 FL	*447.90 FL
49	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS
50	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
51	1		*REVERSE SENSORS	Shorted	315.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	3		*CLIP, SPOILER	Necessary	23.10 FL	*23.10 FL
53	1		*CLIP, SPOILER	Necessary	8.70 FL	*8.70 FL
54	1		*ORNAMENT, MAZDA	Necessary	45.30 FL	*45.30 FL
55	1		*ORNAMENT, 5	Necessary	36.30 FL	*36.30 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					9,960.30	5,310.10
- List Item Discount on L Items 10.00/10.00% (S\$)					947.53	510.01
Total Parts (S\$)					9,012.77	4,800.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	New	3,780.00	1,575.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.	New	3,000.00	1,500.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	560.00	560.00
4	TO REMOVE AND VACUUM BROKEN GLASS DEBRIS.	New	100.00	100.00
5	TO REMOVE AND INSTALL SPOILER TAILGATE.	New	180.00	0.00
6	TO TRANSFER TAILGATE MECHANISM.	New	315.00	315.00
7	TO TRANSFER REVERSE CAMERA.	New	180.00	180.00
8	TO REMOVE & REFIT CARPET & TRIMS PN THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	New	945.00	330.00
9	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	New	350.00	80.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	120.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	120.00
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
13	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO WORKSHOP.	New	120.00	0.00
14	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	New	120.00	120.00
15	TO REPLACE WINDSCREEN SOLAR FILM.	New	280.00	280.00
16	TO TRANSFER REVERSE CAMERA.	New	180.00	0.00
Gross Labour Cost (S\$)			10,960.00	5,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >