

Kk

C

CO. REG. NO: 199402370D
GST NO: M2-0123250-3**K. Kim Hin** AUTO PTE LTD**金興(龔)汽車私人有限公司**160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30898

Vehicle Insured : GBA 9387 X
Accident Date : 29-Nov-2019

Date : 02-Dec-2019

Our Ref : 190721 (LONPAC) / SANDRA

PAGE : 1

YUEN CHEE MUN (MR)
Singapore*Not Notarized*
6 Long @ 2400.60
Resurvey After Paint 5 days

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY HYBRID (2494cc) (2012) SJY1600L

1 pc rear bumper	<i>olsem</i>				
2 pcs rear bumper side retainer	@ S\$ 55.00	<i>Bumper</i>	240.00	c	<i>✓</i>
10 pcs rear bumper clips	@ S\$ 1.50	<i>na</i>	110.00	c	<i>455</i>
1 pc o/s bootlid lamp		<i>na</i>	15.00	c	<i>✓</i>
1 pc bootlid logo		<i>na</i>	155.00	c	<i>✓</i>
1 pc bootlid 'hybrid' emblem		<i>na</i>	35.00	c	<i>✓</i>
1 pc bootlid 'camry' emblem		<i>na</i>	35.00	c	<i>✓</i>
1 pc o/s taillamp		<i>na</i>	40.00	c	<i>✓</i>
1 pc o/s taillamp lower bracket		<i>na</i>	155.00	c	<i>✓</i>
1 pc o/s taillamp panel		<i>na</i>	25.00	c	<i>✓</i>
1 pc o/s rear fender		<i>na</i>	95.00	c	<i>✓</i>
1 pc o/s rear fender inner air vent		<i>na</i>	365.00	c	<i>✓</i>
1 pc o/s rear fender inner shield		<i>na</i>	65.00	c	<i>✓</i>
6 pcs o/s rear fender inner shield clips	@ S\$ 1.50	<i>na</i>	80.00	c	<i>✓</i>
1 pc rear windscreen glass moulding		<i>na</i>	9.00	c	<i>✓</i>
		<i>na</i>	65.00	c	<i>✓</i>
			1,489.00		
	Add 15% :		223.35		
			1,712.35		
1 pc rear windscreen glass sealant		<i>na</i>	40.00	sn	<i>✓</i>
1 pc rear windscreen glass damping seal		<i>na</i>	20.00	sn	<i>✓</i>

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.*600h*
800.00

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBA 9387 X
Our Ref : 190721

Page : 2
No. : 30898

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

100/
180.00

To remove and refit rear windscreen
glass and conduct water leak test

120.00 X

To remove and refit reverse sensor
assy.

60.00 ✓

To apply undersealing

80.00 30 X

To putty and respray on affected
portions.

750.00 650

To focus taillamps. To check rear
wiring and lighting operation.

30.00 20

Total : S\$ 3,792.35
=====

Singapore Dollars Three Thousand Seven Hundred
and Ninety Two and Cents Thirty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

844.00
+ 15%

970.60
+ 1580.00 1430

2550.60 2400.60
