

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19021362/KPA3Q2

**Date:** 14/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKX7594A	<b>Insured Vehicle No :</b>	SHA3694C
Date of Loss: 01/12/2019	Nature of Claim: TP	Claim No: MCT19120015

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKX7594A</b>		
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Engine No:	G4FGFH601456
Reg. Date:	28/12/2015 (Man. Year: 2015)	Chassis No:	KNAFX411MF5539963
Colour:	Metallic Red	Odometer:	82703 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 4 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Continental 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,975.23	1,717.74	257.49	13.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,290.00	410.00	24.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,675.23</b>	<b>3,007.74</b>	<b>667.49</b>	<b>18.16</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,200.00</b>		
<b>(\$\$)</b>	3,675.23	2,200.00	1,475.23	40.14
<b>+ GST 7.00/7.00% (\$\$)</b>	257.27	154.00	103.27	40.14
<b>Nett Amount (\$\$)</b>	<b>3,932.50</b>	<b>2,354.00</b>	<b>1,578.50</b>	<b>40.14</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		428.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,789.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>2,700.00</b>		

### INSPECTION

Date of Assignment:	03/12/2019	
Date Inspected:	04/12/2019 Inspected At:	Cp Motors Pte Ltd 160 SIN MING DR #05-05 SIN MING AUTO CITY Singapore 575722
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2020)
<b>Parts:</b>	143	KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX7594A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT REAR DOOR	Bent	1,302.50 FL	*1,302.50 FL
2	1		*RIGHT REAR DOOR WEATHER STRIP	Serviceable	135.70 FL	*- FL
3	1		*RIGHT REAR DOOR TOP HINGE	Repair	75.20 FL	*- FL
4	1		*RIGHT REAR DOOR LOWER HINGE	Repair	75.20 FL	*- FL
5	1		*RIGHT REAR DOOR REGULATOR GEAR	Bent	455.10 FL	*455.10 FL
6	2		*RIGHT REAR DOOR STICKER	Necessary	151.00 FL	*151.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,194.70</b>	<b>1,908.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	219.47	190.86
<b>Total Parts (\$\$)</b>	<b>1,975.23</b>	<b>1,717.74</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REBUILD DOOR MECHANISM	New	60.00	60.00
2	RUST PROOF DAMAGED PARTS	New	40.00	30.00
3	TO STRAIGHTEN RIGHT FRONT DOOR ,RIGHT DOOR PILLAR RIGHT ROCKER PANEL INCLUDE REPLACEMENT OF PARTS	New	600.00	400.00
4	SPRAY PAINT ON RIGHT FRONT DOOR ,RIGHT REAR DOOR ,RIGHT DOOR CENTER PILLAR ,RIGHT ROCKER PANEL	New	1,000.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,700.00</b>	<b>1,290.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**