

ASSIGNMENT

Surveyor:

XGQ

DOE: 02/12/2019

Date / Time : 02/12/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJU 6851S

Claim No. : SNM190205693

Name of Insured : CHUA BIDA, DANIEL

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$

D.O.A : 28/11/2019 16:20

Place of Accident : UPP ALJUNIED ROAD > MACPHERSON

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHC 1094L

INSRS:
WSP: CDGE LOYANG

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SHC 1094L - CC4/III19011322/Kwb3q2; DOA:06.06.19	Non-Reporting ltr (1st):	
- CC4/III19013666/R1ga3q2; DOA: 26.7.19	Non-Reporting ltr (2nd):	
- CC4/III18023194/Deb3s2; DOA : 23.12.18	Non-Reporting ltr (Final):	
SJU 6851S - X	Notification ltr (if non-pickup):	
REQUEST FOR TP VIDEO.	Call OI:	Email, 31-03-20
	After call ltr to OI:	
REQD TP VIDEO, FORWARDED TO CHUANSHO (HAW) TRIP CO- ENCLOSURED QD TP LOAN NAME TURNING IN THE BRAND.	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA :	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
PRELIMINARY ADVICE Date/Time:	Sent By:	Post-Repair Photos: ☒
		Others: ☐
FINALIZATION Date/Time:	Confirm with:	Confirm by: XGQ
Repair Cost: 1/2 SS1,750	(4 days) Reduction: 75 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 05-03-20	Confirm with: CM	Email ☒ Call ☐
Final Liability: 100	(Agreed / Assessed) BOLA S/N No. : 16	If NO or B 28, Ass. Lia :
Repair Cost: 2/4 SS1,813.50	QD ENCLOSURED INTO TP LANE.	
Loss of Rental (LOR): SS 616.02	(6 days) x \$102.67	
Loss of Use (LOU): SS -	(5 x days)	
Loss of Income (LOI): SS 300.00	(550 x 6 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒	(Tick only one)	
GIA/LTA Search: SS1.99		
Medical: SS -		
Disbursement: SS -	(e.g. Tow/ Independent)	
Legal Cost: SS -		
Total: SS2,856.01	Global Sum SS: 2,850 -	
FINAL PAYMENT Date/Time: 05-03-20	Confirm with: CM	Email ☒ Call ☐
Payee 1: SS2,850.00	Name 1: COMPROMISED ENGINEERING PTE LTD	
Payee 2: (Strike if N.A.) SS	Name 2:	
Payee 3: (Strike if N.A.) SS	Name 3:	

COPY SENT
15/3/2020



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

31 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19021364/Gea3

Date: 12/12/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 1094L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/12/2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	6,915.08
Revised Estimate Amount	: S\$	2,176.68
"Check" Items Amount	: S\$	140.00
Total (Including Check Items)	: S\$	2,316.68

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:
The vehicle sustained damages at the
O/S Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 4 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

Asher

DATE 29/11/2019 16:36

Lee

CHINA

MODEL : HYUNDAI i40

Look Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications being allowed
- Supplementary items will be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: _____

Date: _____

563
800
x
x } nn
x }
40
x
x } nn

Our Job Ref No 305358036

Date 17.12.19

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To LKK

Fax :

Attn : Mr GUO QIANG

Vehicle Reg No. SHC1094L CTPL

28.11.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA SJU6851S

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$1,750.00

Final Lumpsum Repair cost

\$1,750.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name :

Date : 23/12/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305358036

OWNER

AS COMFORT TRANSPORTATION PTE LTD

7010045

OWNER NO 383 SIN MING DRIVE

MESS Singapore SINGAPORE 575717

65508755

(R) (C)

(P)

COUNT CARD NO.

REGN NO.

SHC1094L

MILEAGE

MAKE

HYUNDAI

FUEL

E 1/2 F

MODEL

I-40

DATE/TIME IN

28.11.2019 17:20

YR OF MANU

25.08.2016

TARGET DATE

CHASSIS CODE

RHMLB41UMGU093350

COMPLETION DATE/TIME

CHINA

JOB DESCRIPTION


Accident Date: 28.11.2019

NATURE: 3P 28.11.2019

S/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist Slip

Vehicle No. SHC1094L

LIKE

RAM

Exit Pass

Vehicle No.

SHC1094L

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Reception upon collection

To be kept by Security Guard

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

SHC1094L

Make / Model

HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Vehicle Type :

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1 :

Air-Con (Taxi)

Vehicle Scheme :

Taxi (Company)

Chassis No. :

KMHLB41UMGU093350

Propellant :

Diesel

Engine No. :

D4FDGU668610

Motor No. :

-

Engine Capacity :

1685 cc

Power Rating :

-

Maximum Power Output :

100.0 kW (134 bhp)

REPAIR ESTIMATE*

VEHICLE NO : SHC 1094L

DATE 29/11/2019 16:36

MAKE :

MODEL : HYUNDAI i40

Lee

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 553.00
	Rear Door (RH) X { Repair			\$ 2,201.10
	Front Door (RH) X { Repair			\$ 2,256.40
	Front Door Mirror Assy (RH) / Dis			\$ 670.00
	Rear Wheel Hub-Cap (RH) / Scr			\$ 107.10
	SUB TOTAL			\$ 5,787.60
	LESS 20%			\$ 1,157.52
	DISCOUNTED TOTAL			\$ 4,630.08
	Rear Bumper Rubber Mat X NN			\$ 50.00
	Rear Door Comfortdelgro & Apps Sticker (RH) / { Rec.			\$ 80.00
	Front Door Coloured Comfort Logo (RH) /			\$ 75.00
				\$ 205.00
	Labour Charge			
	Panel Beating-Repair Rear Fender (RH)			\$ 700.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 60.00
	Remove/Refix Reverse Sensor			\$ 80.00
	Transfer of Door		\$ 80.00	\$ 160.00
	Rear Wheel Alignment			\$ 80.00
	4 Days.			\$ 2,080.00
	1 Upsm Repair.			\$ 6,915.08
	After repair photos.			
	Guo Qian - 83880282			
	02/12/19.			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

563
800
X
X
?
40
X
?

Mei Kwan (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 16 December, 2019 5:01 PM
To: Mei Kwan (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: OUR REF: SNM19D205693/SJU6851S/TKL - Accident Involving SJU6851S (OI : CTI - TBA) and SHC1094L (TP : LKK REF - CC3/CTI19021364/Gea3) on 28/11/2019
Attachments: SJU6851S.PDF
Categories: HMK

Without Prejudice

Dear Mei Kwan,

We refer to your email below.

Attached is our insured's GIA report for your necessary action.

Please keep us posted on the status of the claim.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, December 16, 2019 3:55 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: OUR REF: SNM19D205693/SJU6851S/TKL - Accident Involving SJU6851S (OI : CTI - TBA) and SHC1094L (TP : LKK REF - CC3/CTI19021364/Gea3) on 28/11/2019

Dear Kah Leong,

Please revert LKK.

Note : Officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Thank You,

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Monday, 16 December, 2019 12:14 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: Direct Settlement - Accident Involving SJU6851S (OI : CTI - TBA) and SHC1094L (TP : LKK REF - CC3/CTI19021364/Gea3) on 28/11/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 1094L at M/s ComfortDelGro Engineering Pte Ltd (Loyang) on a WP basis and TP repairer proposed for a direct settlement

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler , you may contact the undersigned.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19021364/Gea3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 18-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 6851S	Veh. Inspected	SHC 1094L	
Policy No.	DMPCSN3080581900	Coverage (\$)	0.00	
Claim No.	SNM19D205693	Excess (\$)	0.00	
Assign From		Assign Date	02/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093350	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	6 mm	
L/H Front Tyre	205/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/11/2019	Inspection Date	02/12/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1094L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
1	REAR DOOR (RH)	TO REPAIR SEE LABOUR	2,201.10	-
1	FRONT DOOR (RH)	TO REPAIR SEE LABOUR	2,256.40	-
1	FRONT DOOR MIRROR ASSY (RH)	DISTORTED	670.00	670.00
1	REAR WHEEL HUP-CAP (RH)	SCRATCHED	107.10	107.10
	LESS 20% DISCOUNT		-1,157.52	-155.42
			4,630.08	621.68
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	REAR DOOR COLOURED COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
			205.00	155.00
<u>LABOUR</u>				
	PANEL BEATING-REPAIR REAR FENDER (RH).INCLUSIVE OF THE REPAIR OF REAR DOOR (RH),REAR BUMPER AND FRONT DOOR (RH).		700.00	560.00
	SPRAY PAINTING CHARGE.		900.00	800.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	40.00
	TRANSFER OF DOOR .	NOT NECESSARY	160.00	-
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			2,080.00	1,400.00
GRAND TOTAL			6,915.08	2,176.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CC3/CTI19021364/Gea3q2



Report Ref No. CC3/CTI19021364/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.