

ORTDELGRO ENGINEERING PTE LTD

ESTIMATE*

VEHICLE NO : SHC7266T
 MAKE : HYUNDAI
 MODEL : IONIQ

DATE: 2. Dec. 2019
 DOA: 1. Dec. 2019

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER / <i>ee</i>			\$459.40
1	REAR BUMPER CENTRE MOLDING ASSY / <i>ee</i>			\$451.25
1	REAR BUMPER LOER CENTRE MOLDING ASSY / <i>ee</i>			\$270.10
1	REAR BUMPER REINFORCEMENT ? <i>X NN</i>			\$294.80
1	REAR BUMPER REINFORCEMENT STAY - RH ? <i>X NN</i>			\$138.10
10	REAR BUMPER CLIPS / <i>ML</i>		\$2.20	\$22.00
1	REAR BUMPER UNDER CENTRE / <i>ee</i>			\$53.85
1	REAR BUMPER SIDE UNDER - RH <i>X</i>			\$27.50
1	REAR BUMPER REFLECTOR - RH <i>X</i>			\$31.90
1	REAR LICENSE LAMP - RH <i>X</i>		\$30.20	\$30.20
SUB TOTAL				\$1,779.10
LESS 20%				\$463.46
DISCOUNTED TOTAL				\$1,315.64
1	REVERSE SENSOR / <i>DM</i>			\$135.70
1	REAR NUMBER PLATE / <i>M's</i>			\$25.00
1	REAR NUMBER PLATE CASING / <i>M's</i>			\$30.00
1	REAR BUMPER RUBBER MAT / <i>ML</i>			\$50.00
\$240.70				
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Wiring Charge			\$50.00
1	Remove/refix reverse sensor			\$80.00
1	Computer Programming for BSD			\$250.00
TOTAL LABOUR				\$930.00
ESTIMATE TOTAL				\$2,486.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Nett
 Nett
 Nett
 Nett

320
 200
 X ML
 40
 180

Larry Ng

P/P
 before paint photos.
 Que Conf.
 03/12/19. 2 Days.

Note: BSD - Blind Spot Detection Sensor

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.