

REPAIR ESTIMATE*

DATE: 2. Dec. 2019

MODEL : i40

DOA: 1. Dec. 2019

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover / Cut?			\$1,052.20
1	Front Bumper Side Bracket - LH ?			\$24.60
1	Front Bumper Top Bracket - LH ?			\$22.40
10	Front Bunmper Clips / WCL		\$2.20	\$22.00
1	Front Bumper Grille - LH x NW			\$41.60
1	Headlamp - LH / SCR			\$1,388.00
1	Front Fender - LH / Pmc			\$566.30
SUB TOTAL				\$3,117.10
LESS 20%				\$623.42
DISCOUNTED TOTAL				\$2,493.68
Labour Charge				
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$50.00
1	Wiring Charge			\$50.00
P/P	reface paint photos			
TOTAL LABOUR				\$1,200.00
ESTIMATE TOTAL				\$3,693.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.