

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 21343**

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1419/2019/NS  
Date : 3-Dec-19

**Vehicle IN workshop. Kindly arrange for survey.**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Mr Khiu Shen Woo Joshua  
Address : 236A Serangoon Avenue 2  
#09-149  
Singapore 551236  
Telephone : HP +65 98186262  
Type of Claim : Own Damage Claims  
Policy No. : 1700076736-02  
Vehicle No : **SLU 348 U**  
Model Code : Audi A6 1.8 TFSI S -Tronic  
Model / Year : 20/11/2017  
Engine No : CYG 020784  
Chassis No : WAUZZZ4G8HN129401  
Mileage : 49384  
Date In : 1-Dec-19  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 1-Dec-19  
Place of Accident : Serangoon Rd Underpass Near Poiz Centre

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLU 348 U

| S/n                             | Nature of Jobs                                                                                                                                                                                                                             | Estimated Charges | Surveyor's Recommendations |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 1                               | To tow And recover vehicle from scene of accident.                                                                                                                                                                                         | S/N \$ 280.00     | X.                         |
| 2                               | To carry out first measurement on car o-liner                                                                                                                                                                                              | S/N \$ 800.00     | <del>✓</del> ?             |
| 3                               | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight waler assy and front parking aid.                                                                                           | S/N \$ 480.00     | ✓                          |
| 4                               | To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.                                                                      | S/N \$ 1,400.00   | ✓                          |
| 5                               | To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and cushion airbag. | S/N \$ 3,600.00   | ✓                          |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                            | <b>:</b>          | <b><u>\$ 6,560.00</u></b>  |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLU 348 U

| S/n                      | Nature of Jobs                                                                                                                             | Estimated Charges | Surveyor's Recommendations |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 6                        | To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.                                                   | S/N \$ 2,800.00   | ?                          |
| 7                        | To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary. | S/N \$ 2,400.00   | ?                          |
| 8                        | To renew front windscreen                                                                                                                  | S/N \$ 480.00     | ✓                          |
| 9                        | To install <del>front</del> <sup>Rear</sup> windscreen. solar film                                                                         | S/N \$ 400.00     | ✓                          |
| 10                       | To place vehicle on car o-liner.                                                                                                           | S/N \$ 1,800.00   | ?                          |
| SUB TOTAL LABOUR CHARGES |                                                                                                                                            | : \$ 7,880.00     |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLU 348 U

| S/n                             | Nature of Jobs                                                                                                               | Estimated Charges    | Surveyor's Recommendations |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 11                              | To remove and transfer both front doors and lhs rear door's multi-lock system and power window devices. Inspect for damages. | S/N \$ 840.00        | X                          |
| 12                              | To remove and renew lhs front seat cushion.                                                                                  | S/N \$ 480.00        | ✓                          |
| 13                              | To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.              | S/N \$ 360.00        | ✓                          |
| 14                              | To remove and reinstall exhaust system and rear suspension assembly with subframe. Renew accordingly.                        | S/N \$ 2,400.00      | ?                          |
| 15                              | To remove and reinstall fuel tank assy.                                                                                      | S/N \$ 600.00        | ✓ ?                        |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                              | <b>: \$ 4,680.00</b> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLU 348 U

| S/n | Nature of Jobs                                                                                                                                                                                                                                                                                                                                                                                                                                      | Estimated Charges | Surveyor's Recommendations                                                            |
|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|---------------------------------------------------------------------------------------|
| 16  | To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.                                                                                                                                                                                                                                                                                                                                                                            | S/N \$ 600.00 ✓   |                                                                                       |
| 17  | To install rear windscreen solar film.                                                                                                                                                                                                                                                                                                                                                                                                              | S/N \$ 400.00 ✓   |                                                                                       |
| 18  | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.                                                                                                                                                                                                                                                                                                                      | S/N \$ 1,400.00 ✓ |                                                                                       |
| 19  | To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and diengage curtain airbag etc.                                                                                                                                                                                                                                                                                          | S/N \$ 1,400.00 ✓ |                                                                                       |
| 20  | To dismantle and renew front bumper, both front fenders, bonnet, both headlights, both front doors, lhs sill panel trim, lhs rear door and rear bumper. To cut out and reweld both front fender top supports, lhs rear outer wheel housing, lhs rear outer wheel housing connecting plate and lhs rear fender. renew front lock carrier and align to position. re-organise front and rear crash management components. reinstall all parts removed. | \$ 23,200.00 ✓    | <p>Rear : 3K.</p> <p>Front : 3750.</p> <p>6750.</p> <p>Before. Fender top support</p> |

**SUB TOTAL LABOUR CHARGES**

**: \$ 27,000.00**

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLU 348 U

| S/n                         | Nature of Jobs                                                                                                                                                                                                                                                                                                                                                                                             | Estimated Charges                                                                                                            | Surveyor's Recommendations |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|----------------------------|
|                             | <p> <del>To respray front bumper, both front fenders, bonnet, hinges, both upper A-pillars, both front doors, lhs rear door, lhs panel trim, rear bumper, lhs rear fender, door entrances, roof channel, drain channel, lhs rear outer wheel housing, lhs rear outer wheel housing connecting plate, lhs sill panel and end panelling. to carry out joint sealer work and stone chip treatment.</del> </p> | <p> <del>12 x SSD = 6600</del><br/> <del>Hinges = 200</del><br/> <del>connecting plate = 275</del><br/> <del>7075</del> </p> |                            |
| 21                          | channel, drain channel, lhs rear outer wheel housing, lhs rear outer wheel housing connecting plate, lhs sill panel and end panelling. to carry out joint sealer work and stone chip treatment.                                                                                                                                                                                                            | \$ 15,600.00                                                                                                                 |                            |
| 22                          | To renew both front rims and lhs rear rim. To carry out wheel alignment.                                                                                                                                                                                                                                                                                                                                   | S/N \$ 360.00                                                                                                                | ✓                          |
| 23                          | To carry out diagnostic checks.                                                                                                                                                                                                                                                                                                                                                                            | S/N \$ 384.00                                                                                                                | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                                                                                                                                                                            | <b>: \$ 62,464.00</b>                                                                                                        |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                                        |    |    | Damaged Parts & Prices |         |
|-----------------------|----------------------------------------------------------|----|----|------------------------|---------|
|                       |                                                          |    |    | S/Nett                 | Remarks |
| 1                     | FRONT BUMPER <i>Distorted</i>                            |    | \$ | 2,787.00               | ✓       |
| 2                     | FRONT BUMPER FIXING PARTS ?                              |    | \$ | 491.00                 | ?       |
| 3                     | FRONT BUMPER TOWING EYE COVER <i>Repaired</i>            |    | \$ | 43.00                  | ✓       |
| 4                     | FRONT BUMPER GRILLE - LOWER CENTRE <i>Crushed</i>        |    | \$ | 116.00                 | ✓       |
| 5                     | LOCKING CLIP <i>re</i>                                   | 14 | \$ | 51.00                  | ✓       |
| 6                     | FRONT BUMPER ADAPTER - LH / RH <i>Damaged</i>            | 2  | \$ | 68.00                  | ✓       |
| ⑦                     | FRONT BUMPER CLOSING ELEMENT <i>Crushed</i>              |    | \$ | 199.00                 | ✓       |
| ⑧                     | FRONT BUMPER SPOILER <i>Deleted / Not in</i>             |    | \$ | 227.00                 | ✓       |
| 9                     | FRONT BUMPER COVER MOLDING <i>Repaired</i>               |    | \$ | 860.00                 | ✓       |
| 10                    | RADIATOR GRILLE <i>Crushed</i>                           |    | \$ | 1,766.00               | ✓       |
| 11                    | RADIATOR GRILLE COVER ?                                  |    | \$ | 33.00                  | ?       |
| 12                    | FRONT RADIATOR GRILLE SENSOR SUPPORT - LH / RH <i>re</i> | 2  | \$ | 122.00                 | ✓       |
| 13                    | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Missing</i>   | 2  | \$ | 904.00                 | ✓       |
| 14                    | FRONT BUMPER CHANNEL COVER - LH / RH <i>Damaged</i>      | 2  | \$ | 92.00                  | ✓       |
| 15                    | FRONT WHEEL SPOILER - LH / RH <i>Crushed</i>             | 2  | \$ | 484.00                 | ✓       |
| 16                    | HEADLIGHT WASHER COVER CAP - LH / RH <i>Pushed</i>       | 2  | \$ | 104.00                 | ✓       |
| 17                    | FRONT BUMPER FOAM FILLER PIECE <i>Crushed</i>            |    | \$ | 215.00                 | ✓       |
| 18                    | FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Bent</i>         |    | \$ | 754.00                 | ✓       |
| 19                    | FRONT BUMPER COVER MOLDING ?                             |    | \$ | 112.00                 | ?       |
| 20                    | FRONT BUMPER BRACKET HOLDER - LH / RH <i>Damaged</i>     | 2  | \$ | 474.00                 | ✓       |
| SUB TOTAL SPARE PARTS |                                                          |    | :  | <u>\$ 9,902.00</u>     |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                               | Damaged Parts & Prices |    |                 | Remarks |
|-----------------------|-------------------------------------------------|------------------------|----|-----------------|---------|
|                       |                                                 | S/Nett                 |    |                 |         |
| 21                    | FRONT BUMPER BRACE - LH / RH <i>Damaged</i>     | 2                      | \$ | 54.00           | ✓       |
| 22                    | FRONT BUMPER GUIDE PIECE - LH / RH <i>Dmgd</i>  | 2                      | \$ | 68.00           | ✓       |
| 23                    | AIRCON STICKER <i>2/11/12</i>                   | NEC                    | \$ | 18.00           | ✓       |
| 24                    | CAUTION SIGN STICKER                            | NEC                    | \$ | 13.00           | ✓       |
| 25                    | EXTERNAL TEMPERATURE SENSOR <i>Best New</i>     |                        | \$ | 57.00           | ✓       |
| 26                    | EXTERNAL TEMPERATURE SENSOR BRACKET <i>Dmgd</i> |                        | \$ | 21.00           | ✓       |
| 27                    | SIGNAL HORN - LH LOW TONE ?                     |                        | \$ | 262.00          | ?       |
| 28                    | SIGNAL HORN - RH HIGH TONE ?                    |                        | \$ | 215.00          | ?       |
| 29                    | SPRING SHACKLE - LH / RH <i>Best</i>            | 2                      | \$ | 86.00           | ✓       |
| 30                    | FRONT PARKING AID SENSOR - INNER <i>New</i>     | 2                      | \$ | 419.00          | +       |
| 31                    | FRONT PARKING AID SENSOR - OUTER <i>New</i>     | 2                      | \$ | 462.00          | +       |
| 32                    | FRONT BUMPER WIRING SET ?                       |                        | \$ | 532.00          | ?       |
| 33                    | BONNET <i>Disturbed</i>                         |                        | \$ | 4,965.00        | ✓       |
| 34                    | BONNET ATTACHMENT PARTS ?                       |                        | \$ | 161.00          | ?       |
| 35                    | BONNET LID HINGE - LH / RH <i>Best</i>          | 2                      | \$ | 292.00          | ✓       |
| 36                    | BALL STUD ?                                     | 2                      | \$ | 38.00           | ?       |
| 37                    | BONNET GAS FILLED STRUT <i>Best</i>             | 2                      | \$ | 217.00          | ✓       |
| 38                    | BONNET CATCH HOOK <i>Best</i>                   |                        | \$ | 127.00          | ✓       |
| 39                    | BONNET LOCK BAR <i>Tampered</i>                 | 2                      | \$ | 90.00           | ✓       |
| 40                    | BONNET CATCH HOOK <i>Best</i>                   |                        | \$ | 16.00           | ✓       |
| SUB TOTAL SPARE PARTS |                                                 | :                      | \$ | <u>8,113.00</u> |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                                  | Damaged Parts & Prices |             | Remarks |
|-----------------------|----------------------------------------------------|------------------------|-------------|---------|
|                       |                                                    | S/Nett                 |             |         |
| 41                    | BONNET LID LOCK <i>2 Dmgd</i>                      | 2                      | \$ 391.00   | ✓       |
| 42                    | BONNET MICRO SWITCH                                | 2                      | \$ 133.00   | ✓       |
| 43                    | BONNET BOWDEN CABLE - CENTRE ?                     |                        | \$ 53.00    | ?       |
| 44                    | BONNET LID LOCK CABLE ?                            |                        | \$ 67.00    | ?       |
| 45                    | BONNET BRACKET <i>Dmgd</i>                         |                        | \$ 35.00    | ✓       |
| 46                    | FRONT FENDER - LH <i>Disbld</i>                    |                        | \$ 1,269.00 | ✓       |
| 47                    | FRONT FENDER ATTACHMENT PARTS <i>ru</i>            |                        | \$ 92.00    | ✓       |
| 48                    | FRONT FENDER STONE GUARD FILM - LH <i>ru</i>       |                        | \$ 110.00   | ✓       |
| 49                    | FRONT FENDER - RH <i>Disbld</i>                    |                        | \$ 1,269.00 | ✓       |
| 50                    | FRONT FENDER ATTACHMENT PARTS <i>ru</i>            |                        | \$ 92.00    | ✓       |
| 51                    | FRONT FENDER STONE GUARD FILM - RH <i>ru</i>       |                        | \$ 110.00   | ✓       |
| 52                    | FRONT FENDER BRACE - LH / RH <i>Best</i>           | 2                      | \$ 150.00   | ✓       |
| 53                    | FRONT FENDER CLOSING ELEMENT - LH / RH <i>Dmgd</i> | 2                      | \$ 96.00    | ✓       |
| 54                    | WHEEL HOUSING LINER - LH / RH <i>torn</i>          | 2                      | \$ 512.00   | ✓       |
| 55                    | WHEEL HOUSING LINER ATTACHMENT PARTS <i>ru</i>     | 2                      | \$ 132.00   | ✓       |
| 56                    | FRONT STONE CHIP GUARD - LH / RH <i>ru</i>         | 2                      | \$ 132.00   | ✓       |
| 57                    | ENGINE BONNET SOUND ABSORBER ?                     |                        | \$ 289.00   | ?       |
| 58                    | WATER DEFLECTOR COVER ?                            |                        | \$ 183.00   | ?       |
| 59                    | WATER DEFLECTOR ?                                  |                        | \$ 69.00    | ?       |
| 60                    | FILLER PLATE - LH UPPER <i>Best</i>                |                        | \$ 683.00   | ✓       |
| SUB TOTAL SPARE PARTS |                                                    | :                      | \$ 5,867.00 |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                         | Damaged Parts & Prices |                     | Remarks |
|-----------------------|-------------------------------------------|------------------------|---------------------|---------|
|                       |                                           | S/Nett                 |                     |         |
| 61                    | NOISE INSULATION PLATE <i>toen</i>        | \$                     | 30.00 ✓             |         |
| 62                    | FILLER PLATE - RH UPPER <i>distal</i>     | \$                     | 683.00 ✓            |         |
| 63                    | NOISE INSULATION PLATE <i>ru</i>          | \$                     | 30.00 ✓             |         |
| 64                    | END PLATE - LH / RH UPPER <i>Best</i>     | 2 \$                   | 272.00 ✓            |         |
| 65                    | HEADLIGHT MOUNTING - LH / RH <i>could</i> | 2 \$                   | 214.00 ✓            |         |
| 66                    | LED HEADLIGHT - LH / RH <i>could</i>      | 2 \$                   | 17,214.00 ✓         |         |
| 67                    | TURN SIGNAL POWER MODULE ?                | 2 \$                   | 1,039.00 ?          |         |
| 68                    | DIPPED BEAM POWER MODULE ?                | \$                     | 508.00 ?            |         |
| 69                    | HEADLAMP FAN - LH / RH ?                  | 2 \$                   | 726.00 ?            |         |
| 70                    | HEADLIGHT AIR GUIDE - LH / RH ?           | 2 \$                   | 110.00 ?            |         |
| 71                    | HEADLIGHT PROTECTIVE CAP - LH / RH ?      | 2 \$                   | 104.00 ?            |         |
| 72                    | HEADLIGHT BRACKET <i>2x2</i>              | 2 \$                   | 52.00 ✓             |         |
| 73                    | HEADLIGHT HOSE - LH / RH ?                | 2 \$                   | 76.00 !             |         |
| 74                    | HEADLIGHT COMPENSATING PIECE ?            | 4 \$                   | 153.00 ?            |         |
| 75                    | HEADLIGHT ADJUSTMENT ELEMENT ?            | 2 \$                   | 83.00 ?             |         |
| 76                    | LIFT CYLINDER - LH / RH <i>could</i>      | 2 \$                   | 432.00 ✓            |         |
| 77                    | HEADLIGHT HOSE - LH / RH <i>ru n</i>      | \$                     | 426.00 ✗            |         |
| 78                    | WASH WATER RESERVOIR ?                    | \$                     | 174.00 ?            |         |
| 79                    | LOCK CARRIER <i>distal</i>                | \$                     | 1,140.00 ✓          |         |
| 80                    | COOLANT REGULATOR SUPPORT ?               | 2 \$                   | 67.00 ?             |         |
| SUB TOTAL SPARE PARTS |                                           | :                      | <u>\$ 23,533.00</u> |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                          | Damaged Parts & Prices |             | Remarks |
|-----------------------|--------------------------------------------|------------------------|-------------|---------|
|                       |                                            | S/Nett                 |             |         |
| • 81                  | AIRCON CONDENSER <i>Dented</i>             | \$                     | 689.00      | ✓       |
| 82                    | REFRIGERANT HOSE ?                         | \$                     | 340.00      | ?       |
| 83                    | REFRIGERANT HOSE ?                         | \$                     | 234.00      | ?       |
| 84                    | PRESSURE RELIEF VALVE ?                    | \$                     | 48.00       | ?       |
| 85                    | PRESSURE SENDER ?                          | \$                     | 175.00      | ?       |
| 86                    | REFRIGERANT PIPE ?                         | \$                     | 234.00      | ?       |
| • 87                  | RADIATOR <i>Dented</i>                     | \$                     | 775.00      | ✓       |
| 88                    | RADIATOR RUBBER BUSH - UPPER <i>Rec</i>    | 2 \$                   | 12.00       | ✓       |
| 89                    | RADIATOR RUBBER BUSH - LOWER <i>Rec</i>    | 2 \$                   | 24.00       | ✓       |
| 90                    | READY MIX COOLANT <i>1L</i>                | 4 \$                   | 84.00       | ?       |
| 91                    | CHARGE AIR COOLER ?                        | \$                     | 513.00      | ?       |
| • 92                  | PRESSURE HOSE - RH <i>embled</i>           | \$                     | 320.00      | ✓       |
| 93                    | PRESSURE HOSE - LH ?                       | \$                     | 150.00      | ?       |
| 94                    | PRESSURE PIPE - LH ?                       | \$                     | 203.00      | ?       |
| 95                    | OUTLET HOSE ?                              | \$                     | 59.00       | ?       |
| 96                    | PULSATION DAMPER ?                         | \$                     | 73.00       | ?       |
| 97                    | TWIN FAN RING ?                            | \$                     | 237.00      | ?       |
| 98                    | RADIATOR FAN ?                             | \$                     | 811.00      | ?       |
| 99                    | RADIATOR FAN ?                             | \$                     | 700.00      | ?       |
| • 100                 | RADIATOR AIR GUIDE - LH / RH <i>embled</i> | 2 \$                   | 50.00       | ✓       |
| SUB TOTAL SPARE PARTS |                                            | :                      | \$ 5,731.00 |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N | Parts Description                              | Damaged Parts & Prices |            | Remarks |
|-----|------------------------------------------------|------------------------|------------|---------|
|     |                                                | S/Nett                 |            |         |
| 101 | RADIATOR CIVER - UPPER CENTRE ?                | \$                     | 27.00 ?    |         |
| 102 | RADIATOR SEALING STRIP ?                       | \$                     | 21.00 ?    |         |
| 103 | AIR INTAKE AIR GUIDE - RH FRONT <i>omitted</i> | \$                     | 24.00 ?    |         |
| 104 | AIR INTAKE AIR DUCT - RH FRONT <i>omitted</i>  | \$                     | 79.00 ?    |         |
| 105 | AIR INTAKE AIR FILTER <i>omitted</i>           | \$                     | 266.00 ?   |         |
| 106 | AIR INTAKE HOSE                                | \$                     | 150.00 ?   |         |
| 107 | WINDOW SILL TRIM <i>not new</i>                | \$                     | 561.00 X   |         |
| 108 | ENGINE UNDERSHIELD - FRONT ?                   | \$                     | 579.00 ?   |         |
| 109 | SHOCK ABSORBER MOUNTING - LH / RH ?            | 2 \$                   | 156.00 ?   |         |
| 110 | SIDE MEMBER - LH / RH <i>not new</i>           | 2 \$                   | 2,730.00 X |         |
| 111 | FRONT WINDSCREEN <i>omitted</i>                | \$                     | 1,438.00 ✓ |         |
| 112 | MIRROR INSIDE RETAINER ?                       | \$                     | 20.00 ?    |         |
| 113 | MIRROR INSIDE RETAINER ?                       | \$                     | 20.00 ?    |         |
| 114 | RAIN SENSOR <i>new</i>                         | \$                     | 749.00 ✓   |         |
| 115 | WATER DEFLECTOR STRIP - LH / RH ?              | 2 \$                   | 122.00 ?   |         |
| 116 | FRONT DOOR - LH <i>Rep</i>                     | \$                     | 3,374.00 X |         |
| 117 | FRONT DOOR ATTACHMENT PARTS <i>new</i>         | \$                     | 173.00 +   |         |
| 118 | FRONT OUTER DOOR SEAL ?                        | NEC \$                 | 212.00 +   |         |
| 119 | BONDING AGENT <i>new</i>                       | NEC \$                 | 45.00 +    |         |
| 120 | CLEANING SOLUTION                              | NEC \$                 | 65.00 +    |         |

SUB TOTAL SPARE PARTS

: \$ 10,811.00

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

|                       |                                                  | Damaged Parts & Prices |         |
|-----------------------|--------------------------------------------------|------------------------|---------|
| S/N                   | Parts Description                                | S/Nett                 | Remarks |
| 121                   | FRONT DOOR - RH <i>Repair</i>                    | \$ 3,374.00            | X       |
| 122                   | FRONT DOOR ATTACHMENT PARTS                      | \$ 173.00              | X       |
| 123                   | FRONT DOOR OUTER SEAL                            | \$ 212.00              | X       |
| 124                   | BONDING AGENT                                    | \$ 45.00               | ✓       |
| 125                   | CLEANING SOLUTION                                | \$ 65.00               | ✓       |
| 126                   | FRONT DOOR CATCH                                 | 2 \$ 217.00            | X       |
| 127                   | WINDOW SLOT SEAL - LH / RH                       | 2 \$ 620.00            | X       |
| 128                   | TYRE PRESSURE DATA PLATE                         | \$ 35.00               | X.      |
| 129                   | REAR BUMPER <i>Rehd</i>                          | \$ 2,676.00            | ✓       |
| 130                   | REAR BUMPER FIXING PARTS <i>see n</i>            | \$ 247.00              | ✓       |
| 131                   | REAR BUMPER SPOILER <i>see n</i>                 | \$ 437.00              | ✓       |
| 132                   | REAR BUMPER SECURING STRIP <i>see n</i>          | \$ 203.00              | X       |
| 133                   | REAR BUMPER CLOSING ELEMENT - LH <i>see n</i>    | \$ 73.00               | ✓       |
| 134                   | REAR BUMPER GUIDE SECTION - LH ?                 | \$ 48.00               | ?       |
| 135                   | REAR BUMPER GUIDE PROFILE - LH / RH ?            | 2 \$ 120.00            | ?       |
| 136                   | REAR BUMPER GUIDE SECTION - LH / RH ?            | 2 \$ 60.00             | ?       |
| 137                   | REAR BUMPER CONNECTING PIECE                     | 2 \$ 22.00             | X       |
| 138                   | REAR BUMPER HOLDING STRAP - LH / RH <i>see n</i> | 2 \$ 116.00            | ✓       |
| 139                   | REAR SIDE PANEL - LH <i>Distorted</i>            | \$ 2,850.00            | ✓       |
| 140                   | REAR WHEEL HOUSING - LH OUTER <i>Repair</i>      | \$ 688.00              | X.      |
| SUB TOTAL SPARE PARTS |                                                  | : \$ 12,281.00         |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                                     | Damaged Parts & Prices |         |
|-----------------------|-------------------------------------------------------|------------------------|---------|
|                       |                                                       | S/Nett                 | Remarks |
| 141                   | REAR WHEEL HOUSING CONNECTING PLATE - LH <i>Repis</i> | \$ 89.00               | x       |
| 142                   | REAR WINDSCREEN <i>Neu</i>                            | \$ 1,069.00            | ✓       |
| 143                   | PRIMER <i>neu</i>                                     | 2 \$ 38.00             | ✓       |
| 144                   | REAR SIDE WINDOW - LH <i>Neu</i>                      | \$ 356.00              | ✓       |
| 145                   | SIDE WINDOW TRIM STRIP - LH REAR ?                    | \$ 235.00              | ?       |
| 146                   | REAR WHEEL HOUSING LINER - LH ?                       | \$ 256.00              | ?       |
| 147                   | REAR WHEEL HOUSING LINER ATTACHMENT PARTS ?           | \$ 66.00               | ?       |
| 148                   | REAR DOOR - LH <i>Repis</i>                           | \$ 3,374.00            | x       |
| 149                   | REAR DOOR ATTACHMENT PARTS                            | \$ 76.00               | x       |
| 150                   | REAR DOOR OUTER SEAL                                  | NEC \$ 212.00          | x       |
| 151                   | BONDING AGENT                                         | NEC \$ 45.00           | x       |
| 152                   | CLEANING SOLUTION                                     | NEC \$ 65.00           | x       |
| 153                   | REAR DOOR CATCH                                       | \$ 109.00              | x       |
| 154                   | SIDE MEMBER TRIM - LH <i>Repis</i>                    | \$ 783.00              | x       |
| 155                   | ATTACHMENT PARTS CLIP <i>2 neu</i>                    | \$ 81.00               | ✓       |
| 156                   | ATTACHMENT PARTS ADHESIVE TAPE                        | \$ 15.00               | ✓       |
| 157                   | LED TAIL LIGHT - LH <i>neu canled</i>                 | \$ 1,149.00            | ✓       |
| 158                   | LED TAIL LIGHT TRIM - LH <i>neu</i>                   | \$ 27.00               | ✓       |
| 159                   | LUGGAGE COMPARTMENT TRIM - LH <i>neu</i>              | \$ 704.00              | x       |
| 160                   | STEERING WHEEL AIRBAG UNIT <i>Activated</i>           | \$ 3,384.00            | ✓       |
| SUB TOTAL SPARE PARTS |                                                       | : \$ 12,133.00         |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                                  | Damaged Parts & Prices |                     | Remarks |
|-----------------------|----------------------------------------------------|------------------------|---------------------|---------|
|                       |                                                    | S/Nett                 |                     |         |
| 161                   | PASSENGER SIDE AIRBAG UNIT                         | \$                     | 4,114.00 ✓          |         |
| 162                   | FRONT SIDE AIRBAG UNIT - LH                        | \$                     | 1,481.00 ✓          |         |
| 163                   | HEAD AIRBAG UNIT - LH                              | \$                     | 1,708.00 ✓          |         |
| 164                   | HEAD AIRBAG UNIT ATTACHMENT PARTS <i>new</i>       | \$                     | 84.00 ✓             |         |
| 165                   | HEAD AIRBAG UNIT - RH <i>Activated</i>             | \$                     | 1,708.00 ✓          |         |
| 166                   | HEAD AIRBAG UNIT ATTACHMENT PARTS <i>Activated</i> | \$                     | 84.00 ✓             |         |
| 167                   | AIRBAG CONTROL UNIT <i>Activated</i>               | \$                     | 2,326.00 ✓          |         |
| 168                   | AIRBAG CRASH SENSOR - REAR                         | \$                     | 273.00 ✓            |         |
| 169                   | FRONT IMPACT SENSOR                                | 2 \$                   | 546.00 ✓            |         |
| 170                   | CENTRAL PROTECTION                                 | \$                     | 543.00 ✓            |         |
| 171                   | SEAT BELT - LH                                     | \$                     | 1,269.00 ?          |         |
| 172                   | SEAT BELT - RH                                     | \$                     | 1,005.00 ?          |         |
| 173                   | HEIGHT ADJUSTER                                    | 2 \$                   | 323.00 ?            |         |
| 174                   | STEERING WHEEL <i>at</i>                           | \$                     | 2,048.00 ✓          |         |
| 175                   | DASHBOARD WITH AIR DUCT <i>torn</i>                | \$                     | 5,420.00 ✓          |         |
| 176                   | AIR VENT <i>Not New</i>                            | \$                     | 111.00 x            |         |
| 177                   | AIR VENT TRIM <i>New</i>                           | \$                     | 113.00 x            |         |
| 178                   | MOULDED HEADLINING <i>crumpled</i>                 | \$                     | 2,417.00 ✓          |         |
| 179                   | A-PILLAR TRIM - LH / RH UPPER <i>Not New</i>       | 2 \$                   | 374.00 x            |         |
| 180                   | B-PILLAR TRIM LH / RH UPPER <i>Not New</i>         | 2 \$                   | 428.00 x            |         |
| SUB TOTAL SPARE PARTS |                                                    | :                      | <u>\$ 26,375.00</u> |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                                             | Damaged Parts & Prices |              | Remarks |
|-----------------------|---------------------------------------------------------------|------------------------|--------------|---------|
|                       |                                                               | S/Nett                 |              |         |
| 181                   | C-PILLAR TRIM - LH / RH UPPER <i>new</i>                      | 2                      | \$ 428.00    | *       |
| 182                   | FRONT FOLDING GRAB HANDLE                                     | 2                      | \$ 286.00    | *       |
| 183                   | REAR FOLDING GRAB HANDLE - LH                                 |                        | \$ 143.00    | *       |
| 184                   | REAR FOLDING GRAB HANDLE - RH                                 |                        | \$ 143.00    | *       |
| 185                   | BACKREST PADDING - LH <i>torn</i>                             |                        | TBC          | ✓       |
| 186                   | BACKREST COVER - LH <i>torn</i>                               | \$                     | 3,078.00     | ✓       |
| 187                   | SEAT COVER - LH <i>new</i>                                    | \$                     | 2,560.00     | *       |
| 188                   | SEAT PADDING - LH                                             | \$                     | 532.00       | ✓       |
| 189                   | ALUMINIUM RIM <i>lt</i>                                       | 3                      | \$ 2,198.00  | ✓       |
| 190                   | ALUMINIUM RIM RUBBER VALVE <i>new</i>                         | 4                      | \$ 13.00     | *       |
| 191                   | SUPPORT FRAME ?                                               | \$                     | 3,550.00     | ?       |
| 192                   | ASSEMBLY CARRIER STRUT BRACE ?                                | \$                     | 177.00       | ?       |
| 193                   | FRONT WISHBONE LINK - LH / RH FRONT <i>Best</i>               | 2                      | \$ 982.00    | ✓       |
| 194                   | FRONT SUSPENSION GUIDE - LH <i>Best</i>                       | \$                     | 889.00       | ✓       |
| 195                   | FRONT SUSPENSION GUIDE - RH <i>Best</i>                       | \$                     | 889.00       | ✓       |
| 196                   | FRONT UPPER CONTROL ARM - LH / RH UPPER <i>Best</i>           | 2                      | \$ 982.00    | ✓       |
| 197                   | <del>FRONT</del> REAR CONTROL ARM - LH / RH UPPER <i>Best</i> | 2                      | \$ 982.00    | ✓       |
| 198                   | WHEEL BEARING HOUSING - LH <i>RA</i>                          | \$                     | 1,035.00     | ✓       |
| 199                   | WHEEL BEARING HOUSING - RH <i>RA</i>                          | \$                     | 1,035.00     | ✓       |
| 200                   | SWIVEL JOINT <i>Best</i>                                      | 2                      | \$ 350.00    | ✓       |
| SUB TOTAL SPARE PARTS |                                                               | :                      | \$ 20,252.00 |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N                   | Parts Description                 | Damaged Parts & Prices |                     | Remarks |
|-----------------------|-----------------------------------|------------------------|---------------------|---------|
|                       |                                   |                        | S/Nett              |         |
| 201                   | WHEEL HUB <i>Best</i>             | 2                      | \$ 855.00           | ✓       |
| 202                   | WHEEL BEARING <i>Best</i>         | 2                      | \$ 1,057.00         | ✓       |
| 203                   | SUSPENSION FORKS - LH <i>Best</i> |                        | \$ 215.00           | ✓       |
| 204                   | SUSPENSION FORKS - RH <i>Best</i> |                        | \$ 215.00           | ✓       |
| 205                   | COUPLING ROD <i>Best</i>          | 2                      | \$ 245.00           | ✓       |
| 206                   | GAS SHOCK ABSORBER ?              | 2                      | \$ 1,042.00         | ?       |
| 207                   | UNDERLAY ?                        | 2                      | \$ 56.00            | ?       |
| 208                   | SPRING DISC ?                     | 2                      | \$ 64.00            | ?       |
| 209                   | DRIVE SHAFT ? - LH. <i>Best</i>   | 2                      | \$ 5,240.00         | 2620-   |
| 210                   | STEERING GEAR ?                   |                        | \$ 6,261.00         | ?       |
| 211                   | TRACK ROD <i>Best</i>             | 2                      | \$ 180.00           | ✓       |
| 212                   | TIE ROD END - LH / RH <i>Best</i> | 2                      | \$ 324.00           | ✓       |
| 213                   | REAR SUPPORT FRAME ?              |                        | \$ 3,046.00         | ?       |
| 214                   | LEFT AXLE GUIDE ?                 |                        | \$ 826.00           | ?       |
| 215                   | WISHBONE - LH UPPER ?             |                        | \$ 541.00           | ?       |
| 216                   | TRACK ROD ?                       |                        | \$ 105.00           | ?       |
| 217                   | WHEEL BEARING HOUSING - LH ?      |                        | \$ 906.00           | ?       |
| 218                   | WHEEL BEARING ?                   |                        | \$ 404.00           | ?       |
| 219                   | SPACER PIPE ?                     |                        | \$ 20.00            | ?       |
| 220                   | GAS SHOCK ABSORBER ?              |                        | \$ 467.00           | ?       |
| SUB TOTAL SPARE PARTS |                                   | :                      | <u>\$ 22,069.00</u> |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 348 U

| S/N | Parts Description                    | Damaged Parts & Prices |               | Remarks |
|-----|--------------------------------------|------------------------|---------------|---------|
|     |                                      | S/Nett                 |               |         |
| 221 | STONE CHIP GUARD <i>me</i>           | 2                      | \$ 16.00 ✓    |         |
| 222 | REAR LEVEL SENSOR ?                  |                        | \$ 298.00 ?   |         |
| 223 | RADIATOR RUBBER BUSH - CENTRE ?      | 2                      | \$ 18.00 ✓    |         |
| 224 | ACRYLIC SEALANT ?                    | S/N                    | \$ 360.00 ✓   |         |
| 225 | CAVITY WAX <i>me</i>                 | S/N                    | \$ 280.00 ✓   |         |
| 226 | STONE CHIP                           | S/N                    | \$ 360.00 ✓   |         |
| 227 | METAL FILLER POWDER <i>me</i>        | S/N                    | \$ 280.00 ✓   |         |
| 228 | FRONT NO PLATE <i>me</i>             | S/N                    | \$ 40.00 ✓    |         |
| 229 | FRONT WINDSCREEN SEALANT ? <i>me</i> | S/N                    | \$ 200.00 ✓   |         |
| 230 | REAR WINDSCREEN SEALANT              | S/N                    | \$ 200.00 ✓   |         |
| 231 | 1/4 GLASS SEALANT <i>me</i>          | S/N                    | \$ 200.00 ✓   |         |
| 232 | SUNDRIES ?                           |                        | \$ 1,000.00 ? |         |

**TOTAL SPARE PARTS**  
**TOTAL LABOUR CHARGES**  
**GRAND TOTAL**

: \$ 160,319.00  
: \$ 62,464.00  
: \$ 222,783.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King  
: 03/12/19.

: Not Authorized, 40 days.

Inclusive of  
undercarriage.

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: