

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21343

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1419/2019/NS
Date : 3-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Khiu Shen Woo Joshua
Address : 236A Serangoon Avenue 2
#09-149
Singapore 551236
Telephone : HP +65 98186262
Type of Claim : Own Damage Claims
Policy No. : 1700076736-02
Vehicle No : **SLU 348 U**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 20/11/2017
Engine No : CYG 020784
Chassis No : WAUZZZ4G8HN129401
Mileage : 49384
Date In : 1-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Dec-19
Place of Accident : Serangoon Rd Underpass Near Poiz Centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 348 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To tow And recover vehicle from scene of accident.	S/N \$	280.00	X-
2	To carry out first measurement on car o-liner	S/N \$	800.00	280.00 ?
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight waher assy and front parking aid.	S/N \$	480.00	✓
4	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00	✓
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and cushion airbag.	S/N \$	3,600.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 6,560.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 348 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N \$	2,800.00	?
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N \$	2,400.00	?
8	To renew front windscreen	S/N \$	480.00	✓
9	To install front ^{Rear} windscreen. solar Film	S/N \$	400.00	✓
10	To place vehicle on car o-liner.	S/N \$	1,800.00	?
SUB TOTAL LABOUR CHARGES		:	<u>\$ 7,880.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 348 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
11	To remove and transfer both front doors and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	840.00	X
12	To remove and renew lhs front seat cushion.	S/N \$	480.00	✓
13	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	✓
14	To remove and reinstall exhaust system and rear suspension assembly with subframe. Renew accordingly.	S/N \$	2,400.00	?
15	To remove and reinstall fuel tank assy.	S/N \$	600.00	✓ ?
SUB TOTAL LABOUR CHARGES		:	\$ 4,680.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 348 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
16	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00 ✓	
17	To install rear windscreen solar film.	S/N \$ 400.00 ✓	
18	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	
19	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and diengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
20	To dismantle and renew front bumper, both front fenders, bonnet, both headlights, both front doors, lhs sill panel trim, lhs rear door and rear bumper. To cut out and reweld both front fender top supports, lhs rear outer wheel housing, lhs rear outer wheel housing connecting plate and lhs rear fender. renew front lock carrier and align to position. re-organise front and rear crash management components. reinstall all parts removed.	\$ 23,200.00	Rear : 3K . Front : 3750 . 6750 . Bedone . Fender top support .

SUB TOTAL LABOUR CHARGES

: \$ 27,000.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 348 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
	To respray front bumper, both front fenders, bonnet, hinges, both upper A-pillars, both front doors, lhs rear door, lhs panel trim, rear bumper, lhs rear fender, door entrances, roof channel, drain channel, lhs rear outer wheel housing, lhs rear outer wheel housing connecting plate, lhs sill panel and end panelling. to carry out joint sealer work and stone chip treatment.	\$ 15,600.00	12 x 550 = 6600 Hinges = 200 connecting plate = 275 7075
22	To renew both front rims and lhs rear rim. To carry out wheel alignment.	S/N \$ 360.00	✓
23	To carry out diagnostic checks.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 62,464.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
1	FRONT BUMPER <i>Distorted</i>		\$	2,787.00	✓
2	FRONT BUMPER FIXING PARTS ?		\$	491.00	?
3	FRONT BUMPER TOWING EYE COVER <i>Re-banded</i>		\$	43.00	✓
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>crushed</i>		\$	116.00	✓
5	LOCKING CLIP <i>re</i>	14	\$	51.00	✓
6	FRONT BUMPER ADAPTER - LH / RH <i>Painted</i>	2	\$	68.00	✓
7	FRONT BUMPER CLOSING ELEMENT ?		\$	199.00	?
8	FRONT BUMPER SPOILER <i>Re-banded</i>		\$	227.00	✓
9	FRONT BUMPER COVER MOLDING ?		\$	860.00	?
10	RADIATOR GRILLE <i>crushed</i>		\$	1,766.00	✓
11	RADIATOR GRILLE COVER ?		\$	33.00	?
12	FRONT RADIATOR GRILLE SENSOR SUPPORT - LH / RH ?	2	\$	122.00	?
13	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Missing</i>	2	\$	904.00	✓
14	FRONT BUMPER CHANNEL COVER - LH / RH ?	2	\$	92.00	?
15	FRONT WHEEL SPOILER - LH / RH <i>crushed</i>	2	\$	484.00	✓
16	HEADLIGHT WASHER COVER CAP - LH / RH <i>Fished</i>	2	\$	104.00	✓
17	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>		\$	215.00	✓
18	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Bent</i>		\$	754.00	✓
19	FRONT BUMPER COVER MOLDING ?		\$	112.00	?
20	FRONT BUMPER BRACKET HOLDER - LH / RH ?	2	\$	474.00	?
SUB TOTAL SPARE PARTS			:	<u>\$ 9,902.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	FRONT BUMPER BRACE - LH / RH ?	2	\$ 54.00 ?	
22	FRONT BUMPER GUIDE PIECE - LH / RH <i>eng d</i>	2	\$ 68.00 ✓	
23	AIRCON STICKER <i>2</i>	NEC	\$ 18.00 ✓	
24	CAUTION SIGN STICKER <i>1</i>	NEC	\$ 13.00 ✓	
25	EXTERNAL TEMPERATURE SENSOR ?		\$ 57.00 ?	
26	EXTERNAL TEMPERATURE SENSOR BRACKET ?		\$ 21.00 ?	
27	SIGNAL HORN - LH LOW TONE ?		\$ 262.00 ?	
28	SIGNAL HORN - RH HIGH TONE ?		\$ 215.00 ?	
29	SPRING SHACKLE - LH / RH ?	2	\$ 86.00 ?	
30	FRONT PARKING AID SENSOR - INNER <i>2</i>	2	\$ 419.00 +	
31	FRONT PARKING AID SENSOR - OUTER <i>2</i>	2	\$ 462.00 +	
32	FRONT BUMPER WIRING SET ?		\$ 532.00 ?	
33	BONNET <i>Disturbed</i>		\$ 4,965.00 ✓	
34	BONNET ATTACHMENT PARTS ?		\$ 161.00 ?	
35	BONNET LID HINGE - LH / RH <i>Bent</i>	2	\$ 292.00 ✓	
36	BALL STUD ?	2	\$ 38.00 ?	
37	BONNET GAS FILLED STRUT <i>Bent</i>	2	\$ 217.00 ✓	
38	BONNET CATCH HOOK <i>Bent</i>		\$ 127.00 ✓	
39	BONNET LOCK BAR <i>Tampered</i>	2	\$ 90.00 ✓	
40	BONNET CATCH HOOK <i>Bent</i>		\$ 16.00 ✓	
SUB TOTAL SPARE PARTS		:	<u>\$ 8,113.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices			Remarks
			S/Nett		
41	BONNET LID LOCK <i>2 Paid</i>	2	\$	391.00	✓
42	BONNET MICRO SWITCH <i>1 Paid</i>	2	\$	133.00	✓
43	BONNET BOWDEN CABLE - CENTRE ?		\$	53.00	?
44	BONNET LID LOCK CABLE ?		\$	67.00	?
45	BONNET BRACKET <i>Paid</i>		\$	35.00	✓
46	FRONT FENDER - LH <i>Disbld</i>		\$	1,269.00	✓
47	FRONT FENDER ATTACHMENT PARTS <i>ru</i>		\$	92.00	✓
48	FRONT FENDER STONE GUARD FILM - LH <i>ru</i>		\$	110.00	✓
49	FRONT FENDER - RH <i>Disbld</i>		\$	1,269.00	✓
50	FRONT FENDER ATTACHMENT PARTS <i>ru</i>		\$	92.00	✓
51	FRONT FENDER STONE GUARD FILM - RH <i>ru</i>		\$	110.00	✓
52	FRONT FENDER BRACE - LH / RH <i>Best</i>	2	\$	150.00	✓
53	FRONT FENDER CLOSING ELEMENT - LH / RH <i>Paid</i>	2	\$	96.00	✓
54	WHEEL HOUSING LINER - LH / RH <i>tom</i>	2	\$	512.00	✓
55	WHEEL HOUSING LINER ATTACHMENT PARTS <i>ru</i>	2	\$	132.00	✓
56	FRONT STONE CHIP GUARD - LH / RH <i>ru</i>	2	\$	132.00	✓
57	ENGINE BONNET SOUND ABSORBER ?		\$	289.00	?
58	WATER DEFLECTOR COVER ?		\$	183.00	?
59	WATER DEFLECTOR ?		\$	69.00	?
60	FILLER PLATE - LH UPPER ?		\$	683.00	?
SUB TOTAL SPARE PARTS		:	\$	<u>5,867.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
61	NOISE INSULATION PLATE ?		\$ 30.00 ?	
62	FILLER PLATE - RH UPPER ?		\$ 683.00 ?	
63	NOISE INSULATION PLATE ?		\$ 30.00 ?	
64	END PLATE - LH / RH UPPER ?	2	\$ 272.00 ?	
65	HEADLIGHT MOUNTING - LH / RH <i>could</i>	2	\$ 214.00 ✓	
66	LED HEADLIGHT - LH / RH <i>could</i>	2	\$ 17,214.00 ✓	
67	TURN SIGNAL POWER MODULE ?	2	\$ 1,039.00 ?	
68	DIPPED BEAM POWER MODULE ?		\$ 508.00 ?	
69	HEADLAMP FAN - LH / RH ?	2	\$ 726.00 ?	
70	HEADLIGHT AIR GUIDE - LH / RH ?	2	\$ 110.00 ?	
71	HEADLIGHT PROTECTIVE CAP - LH / RH ?	2	\$ 104.00 ?	
72	HEADLIGHT BRACKET <i>2x</i>	2	\$ 52.00 ✓	
73	HEADLIGHT HOSE - LH / RH ?	2	\$ 76.00 ?	
74	HEADLIGHT COMPENSATING PIECE ?	4	\$ 153.00 ?	
75	HEADLIGHT ADJUSTMENT ELEMENT ?	2	\$ 83.00 ?	
76	LIFT CYLINDER - LH / RH <i>could</i>	2	\$ 432.00 ✓	
77	HEADLIGHT HOSE - LH / RH <i>new</i>		\$ 426.00 X	
78	WASH WATER RESERVOIR ?		\$ 174.00 ?	
79	LOCK CARRIER <i>distorted</i>		\$ 1,140.00 ✓	
80	COOLANT REGULATOR SUPPORT ?	2	\$ 67.00 ?	
SUB TOTAL SPARE PARTS		:	<u>\$ 23,533.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
81	AIRCON CONDENSER ?		\$ 689.00 ?	
82	REFRIGERANT HOSE ?		\$ 340.00 ?	
83	REFRIGERANT HOSE ?		\$ 234.00 ?	
84	PRESSURE RELIEF VALVE ?		\$ 48.00 ?	
85	PRESSURE SENDER ?		\$ 175.00 ?	
86	REFRIGERANT PIPE ?		\$ 234.00 ?	
87	RADIATOR ?		\$ 775.00 ?	
88	RADIATOR RUBBER BUSH - UPPER ?	2	\$ 12.00 ?	
89	RADIATOR RUBBER BUSH - LOWER ?	2	\$ 24.00 ?	
90	READY MIX COOLANT <i>Alu</i>	4	\$ 84.00 ✓	
91	CHARGE AIR COOLER ?		\$ 513.00 ?	
92	PRESSURE HOSE - RH ?		\$ 320.00 ?	
93	PRESSURE HOSE - LH ?		\$ 150.00 ?	
94	PRESSURE PIPE - LH ?		\$ 203.00 ?	
95	OUTLET HOSE ?		\$ 59.00 ?	
96	PULSATION DAMPER ?		\$ 73.00 ?	
97	TWIN FAN RING ?		\$ 237.00 ?	
98	RADIATOR FAN ?		\$ 811.00 ?	
99	RADIATOR FAN ?		\$ 700.00 ?	
100	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 50.00 ?	
SUB TOTAL SPARE PARTS		:	\$ 5,731.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
101	RADIATOR CIVER - UPPER CENTRE ?	\$ 27.00	?
102	RADIATOR SEALING STRIP ?	\$ 21.00	?
103	AIR INTAKE AIR GUIDE - RH FRONT ?	\$ 24.00	?
104	AIR INTAKE AIR DUCT - RH FRONT ?	\$ 79.00	?
105	AIR INTAKE AIR FILTER ?	\$ 266.00	?
106	AIR INTAKE HOSE ?	\$ 150.00	?
107	WINDOW SILL TRIM <i>not in</i>	\$ 561.00	X
108	ENGINE UNDERSHIELD - FRONT ?	\$ 579.00	?
109	SHOCK ABSORBER MOUNTING - LH / RH ?	2 \$ 156.00	?
110	SIDE MEMBER - LH / RH <i>not in</i>	2 \$ 2,730.00	X
111	FRONT WINDSCREEN <i>cracked</i>	\$ 1,438.00	✓
112	MIRROR INSIDE RETAINER ?	\$ 20.00	?
113	MIRROR INSIDE RETAINER ?	\$ 20.00	?
114	RAIN SENSOR <i>in</i>	\$ 749.00	✓
115	WATER DEFLECTOR STRIP - LH / RH ?	2 \$ 122.00	?
116	FRONT DOOR - LH <i>Rep5</i>	\$ 3,374.00	X
117	FRONT DOOR ATTACHMENT PARTS <i>in</i>	\$ 173.00	X
118	FRONT OUTER DOOR SEAL ?	NEC \$ 212.00	X
119	BONDING AGENT <i>in</i>	NEC \$ 45.00	X
120	CLEANING SOLUTION	NEC \$ 65.00	X
SUB TOTAL SPARE PARTS		: \$ 10,811.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
121	FRONT DOOR - RH <i>Repair</i>	\$ 3,374.00	X
122	FRONT DOOR ATTACHMENT PARTS } <i>MP</i>	\$ 173.00	f
123	FRONT DOOR OUTER SEAL	\$ 212.00	f
124	BONDING AGENT	\$ 45.00	✓
125	CLEANING SOLUTION	\$ 65.00	✓
126	FRONT DOOR CATCH	2 \$ 217.00	f
127	WINDOW SLOT SEAL - LH / RH	2 \$ 620.00	f
128	TYRE PRESSURE DATA PLATE	\$ 35.00	X.
129	REAR BUMPER <i>Rehd</i>	\$ 2,676.00	✓
130	REAR BUMPER FIXING PARTS <i>new</i>	\$ 247.00	f
131	REAR BUMPER SPOILER <i>new</i>	\$ 437.00	f
132	REAR BUMPER SECURING STRIP <i>new</i>	\$ 203.00	X
133	REAR BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 73.00	f
134	REAR BUMPER GUIDE SECTION - LH ?	\$ 48.00	?
135	REAR BUMPER GUIDE PROFILE - LH / RH ?	2 \$ 120.00	?
136	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$ 60.00	?
137	REAR BUMPER CONNECTING PIECE <i>new</i>	2 \$ 22.00	X
138	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 116.00	✓
139	REAR SIDE PANEL - LH <i>Distorted</i>	\$ 2,850.00	✓
140	REAR WHEEL HOUSING - LH OUTER <i>Repair</i>	\$ 688.00	X.
SUB TOTAL SPARE PARTS		: \$ 12,281.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
141	REAR WHEEL HOUSING CONNECTING PLATE - LH <i>Reps</i>	\$ 89.00	<i>x</i>
142	REAR WINDSCREEN <i>Neu</i>	\$ 1,069.00	<i>✓</i>
143	PRIMER <i>neu</i> 2	\$ 38.00	<i>✓</i>
144	REAR SIDE WINDOW - LH <i>neu</i>	\$ 356.00	<i>✓</i>
145	SIDE WINDOW TRIM STRIP - LH REAR ?	\$ 235.00	<i>?</i>
146	REAR WHEEL HOUSING LINER - LH ?	\$ 256.00	<i>?</i>
147	REAR WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 66.00	<i>?</i>
148	REAR DOOR - LH <i>Reps</i>	\$ 3,374.00	<i>x</i>
149	REAR DOOR ATTACHMENT PARTS	\$ 76.00	<i>+</i>
150	REAR DOOR OUTER SEAL	NEC \$ 212.00	<i>+</i>
151	BONDING AGENT	NEC \$ 45.00	<i>+</i>
152	CLEANING SOLUTION	NEC \$ 65.00	<i>+</i>
153	REAR DOOR CATCH	\$ 109.00	<i>+</i>
154	SIDE MEMBER TRIM - LH <i>Reps</i>	\$ 783.00	<i>x</i>
155	ATTACHMENT PARTS CLIP <i>3 neu</i>	\$ 81.00	<i>✓</i>
156	ATTACHMENT PARTS ADHESIVE TAPE	\$ 15.00	<i>✓</i>
157	LED TAIL LIGHT - LH <i>neu</i>	\$ 1,149.00	<i>✓</i>
158	LED TAIL LIGHT TRIM - LH <i>neu</i>	\$ 27.00	<i>✓</i>
159	LUGGAGE COMPARTMENT TRIM - LH <i>neu</i>	\$ 704.00	<i>x</i>
160	STEERING WHEEL AIRBAG UNIT <i>Activated</i>	\$ 3,384.00	<i>✓</i>
SUB TOTAL SPARE PARTS		: \$ 12,133.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
161	PASSENGER SIDE AIRBAG UNIT	\$ 4,114.00	✓
162	FRONT SIDE AIRBAG UNIT - LH	\$ 1,481.00	✓
163	HEAD AIRBAG UNIT - LH	\$ 1,708.00	✓
164	HEAD AIRBAG UNIT ATTACHMENT PARTS	\$ 84.00	✓
165	HEAD AIRBAG UNIT - RH	\$ 1,708.00	✓
166	HEAD AIRBAG UNIT ATTACHMENT PARTS	\$ 84.00	✓
167	AIRBAG CONTROL UNIT	\$ 2,326.00	✓
168	AIRBAG CRASH SENSOR - REAR	\$ 273.00	✓
169	FRONT IMPACT SENSOR	2 \$ 546.00	✓
170	CENTRAL PROTECTION	\$ 543.00	✓
171	SEAT BELT - LH	\$ 1,269.00	?
172	SEAT BELT - RH	\$ 1,005.00	?
173	HEIGHT ADJUSTER	2 \$ 323.00	?
174	STEERING WHEEL	\$ 2,048.00	✓
175	DASHBOARD WITH AIR DUCT	\$ 5,420.00	✓
176	AIR VENT	\$ 111.00	x
177	AIR VENT TRIM	\$ 113.00	x
178	MOULDED HEADLINING	\$ 2,417.00	✓
179	A-PILLAR TRIM - LH / RH UPPER	2 \$ 374.00	x
180	B-PILLAR TRIM LH / RH UPPER	2 \$ 428.00	x
SUB TOTAL SPARE PARTS		: \$ 26,375.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
181	C-PILLAR TRIM - LH / RH UPPER <i>new</i>	2	\$ 428.00	x
182	FRONT FOLDING GRAB HANDLE	2	\$ 286.00	x
183	REAR FOLDING GRAB HANDLE - LH <i>new</i>		\$ 143.00	x
184	REAR FOLDING GRAB HANDLE - RH		\$ 143.00	x
185	BACKREST PADDING - LH <i>torn</i>		TBC	✓
186	BACKREST COVER - LH <i>torn</i>	\$	3,078.00	✓
187	SEAT COVER - LH <i>new</i>	\$	2,560.00	x
188	SEAT PADDING - LH	\$	532.00	x
189	ALUMINIUM RIM <i>ht</i>	3	\$ 2,198.00	✓
190	ALUMINIUM RIM RUBBER VALVE <i>new</i>	4	\$ 13.00	x
191	SUPPORT FRAME ?	\$	3,550.00	?
192	ASSEMBLY CARRIER STRUT BRACE ?	\$	177.00	?
193	FRONT WISHBONE LINK - LH / RH FRONT ?	2	\$ 982.00	?
194	FRONT SUSPENSION GUIDE - LH ?	\$	889.00	?
195	FRONT SUSPENSION GUIDE - RH ?	\$	889.00	?
196	FRONT UPPER CONTROL ARM - LH / RH UPPER ?	2	\$ 982.00	?
197	REAR CONTROL ARM - LH / RH UPPER ?	2	\$ 982.00	?
198	WHEEL BEARING HOUSING - LH ?	\$	1,035.00	?
199	WHEEL BEARING HOUSING - RH ?	\$	1,035.00	?
200	SWIVEL JOINT ?	2	\$ 350.00	?
SUB TOTAL SPARE PARTS		:	\$ 20,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
201	WHEEL HUB ?	2	\$ 855.00 ?	
202	WHEEL BEARING ?	2	\$ 1,057.00 ?	
203	SUSPENSION FORKS - LH ?		\$ 215.00 ?	
204	SUSPENSION FORKS - RH ?		\$ 215.00 ?	
205	COUPLING ROD ?	2	\$ 245.00 ?	
206	GAS SHOCK ABSORBER ?	2	\$ 1,042.00 ?	
207	UNDERLAY ?	2	\$ 56.00 ?	
208	SPRING DISC ?	2	\$ 64.00 ?	
209	DRIVE SHAFT ?	2	\$ 5,240.00 ?	
210	STEERING GEAR ?		\$ 6,261.00 ?	
211	TRACK ROD ?	2	\$ 180.00 ?	
212	TIE ROD END - LH / RH ?	2	\$ 324.00 ?	
213	REAR SUPPORT FRAME ?		\$ 3,046.00 ?	
214	LEFT AXLE GUIDE ?		\$ 826.00 ?	
215	WISHBONE - LH UPPER ?		\$ 541.00 ?	
216	TRACK ROD ?		\$ 105.00 ?	
217	WHEEL BEARING HOUSING - LH ?		\$ 906.00 ?	
218	WHEEL BEARING ?		\$ 404.00 ?	
219	SPACER PIPE ?		\$ 20.00 ?	
220	GAS SHOCK ABSORBER ?		\$ 467.00 ?	
SUB TOTAL SPARE PARTS		:	\$ 22,069.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 348 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
221	STONE CHIP GUARD <i>mc</i>	2	\$ 16.00	✓
222	REAR LEVEL SENSOR ?		\$ 298.00	?
223	RADIATOR RUBBER BUSH - CENTRE ?	2	\$ 18.00	7
224	ACRYLIC SEALANT ?	S/N	\$ 360.00	✓
225	CAVITY WAX <i>mc</i>	S/N	\$ 280.00	✓
226	STONE CHIP	S/N	\$ 360.00	✓
227	METAL FILLER POWDER <i>mc</i>	S/N	\$ 280.00	✓
228	FRONT NO PLATE <i>mc</i>	S/N	\$ 40.00	✓
229	FRONT WINDSCREEN SEALANT ? <i>mc</i>	S/N	\$ 200.00	✓
230	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	✓
231	1/4 GLASS SEALANT <i>mc</i>	S/N	\$ 200.00	✓
232	SUNDRIES ?		\$ 1,000.00	?

TOTAL SPARE PARTS : \$ 160,319.00

TOTAL LABOUR CHARGES : \$ 62,464.00

GRAND TOTAL : \$ 222,783.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *03/12/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorized, 40 days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant