

12/20/00

ASS. REC. BY:

REP: 08/MSG1902/386/Egd3n2

Special Instruction:

Invoyr: Steve

ASSIGNMENT (Office)

From (Person): Crystal Lee

of MS1G

Date/Time: 3/12/19 @ 4:58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SDF 8962S

Insured:

SMC 7662Z

at Workshop n/s

Auburn Auto

Tel:

97875558

of

3 AMK St. 62 link #01-45

Policy No:

29119902

Claim No:

613375

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time:

9:35am 3/12/19

Person Contacted:

Sam

Vehicle: IN / OUT

Date/Time

Action/Instruction Estimated /

SDF 8962S - x

parts discount?

SMC 7662Z - x

05/12/19 @ 10:12am revised to Irene Tan via Meimien.

ASSIGNMENT

From: _____ Date: 4/12/19
 Estimated Cost: _____
 (TP) WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SDF 8962S
 at Workshop no: Auburn Auto
 of: 3 Amk st. 62 link @ # 01-45
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) 478 7977
 Make of Veh: Scam @ 97875558


Veh No: SDF 8962S Yr Regn: 8/10/10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Jazz C.C. 1339
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp Reading: 257862 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHM GE 68599 5235293
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/50R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front 5 mm R/Bal. 5 mm
 Rear 5 mm
 L/Bal. 5 mm U/Bal. 5 mm
 D.O.A. 30/11/19 D.O.I. 4/12/19
 Survey held at Auburn Auto
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV- 18,000 13/12/19 Finalize conf \$ 1850, 4 days. (Sam) (Red to 7948.61, 81% -)
	PV - 12189
	NV - 5811
	
	16/12/2019

RECEIVED 7 DEC 2019

Date/Time, File Pass to? : Prel. Report
 16/12/2019 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: 4
 Resurvey No. of Trip: 2
 Survey Fee: _____
 Transport: 150

 TOTAL: 161

Arbit Fee: Site Insp (€) _____
 Interview (€) _____
 Tech. Insp (€) _____
 Wheel end (€) _____

Report Format: MER-TP
 Lump Sum / Mile: 1850

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 05 Dec 2019

Preliminary Advice

Insured Vehicle No	: SMC7662Z	Accident Date	: 30/11/2019
TP Vehicle No	: SDF8962S	Assignment Date	: 05/12/2019
Make	: HONDA FIT	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/12/2019		
Inspection At	: AUBURN AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,535.40
Revised Amount	:S\$	1,835.20
Check Items (Estimated)	:S\$	846.00
Total	:S\$	2,681.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY AMEND THE MAKE & MODEL OF SDF 8962S TO HONDA JAZZ (1339cc) INSTEAD OF HONDA FIT IN MERIMEN SYSTEM.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 3 December 2019 4:58 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

ACCIDENT INVOLVING SDF8962S & SMC7662Z (MSIG) ON 30 Nov 2019 AT 16:30

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Tuesday, 3 December, 2019 4:02 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: RE:ACCIDENT INVOLVING SDF8962S & SMC7662Z (MSIG) ON 30 Nov 2019 AT 16:30

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Helene Phua
Sent: Tuesday, 3 December 2019 4:02 PM
To: 'Sam Ng' <samuel.auburnauto@gmail.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: RE:ACCIDENT INVOLVING SDF8962S & SMC7662Z (MSIG) ON 30 Nov 2019 AT 16:30

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua
Admin Assistant, Claims Services
D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG



A Member of **MS&AD** INSURANCE GROUP

From: Sam Ng <samuel.auburnauto@gmail.com>
Sent: Tuesday, 3 December 2019 3:29 PM
To: Helene Phua <helene_phua@sg.msig-asia.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: Re: RE:ACCIDENT INVOLVING SDF8962S & SMC7662Z (MSIG) ON 30 Nov 2019 AT 16:30

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi All,

The company decided to use

1) LKK Auto Consultants Pte Ltd

with regards

Sam
Auburn Auto Pte Ltd
+65 9787 5558

On Tue, 3 Dec 2019 at 15:14, Helene Phua <helene_phua@sg.msig-asia.com> wrote:

Hi,

We refer to your email dated 03/12/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong
2. Kenneth Kong	7) Siew Meng Hui
3. Marcus Chua	8) Daniel Chan
4. Ng You Han	9) Victor Png

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. ***Fast lane settlement is not applicable for cases that liability is in dispute***
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sam Ng [mailto:samuel.auburnauto@gmail.com]
Sent: Tuesday, 3 December 2019 1:28 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Auburn Auto Claims <auburnauto.claim@gmail.com>
Subject: RE:ACCIDENT INVOLVING SDF8962S & SMC7662Z ON 30 Nov 2019 AT 16:30

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Officer-In-Charge,

We refer to the above.

We are handling the claims for our client's car:

[SDF8962S]

The car is currently at:

3 Ang Mo Kio Street 62

Link@amk 01-45

S(569139).

The other party [SMC7662Z] is under [MSIG INSURANCE] Insurance.

We would like to amicably settle this directly with you.

In this regard, we would appreciate it if you could list your independent surveyors list for us to choose to inspect car before our pre repair protocol.

Thank you.

Kindly call Samuel -97875558(hp) to make an Appointment

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Steve Chen (LKK Auto)

From: Sam Ng <samuel.auburnauto@gmail.com>
Sent: Thursday, December 12, 2019 1:05 PM
To: Steve Chen (LKK Auto)
Subject: Re: SDF8962S Finalize

Hi Steve,

The company decided to accept the offer. Kindly revert to the relevant personal.

with regards
Sam
Auburn Auto Pte Ltd
+65 9787 5558

On Thu, 12 Dec 2019 at 09:52, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sam,

Please confirm the above vehicle \$1850 (L/S, before GST). 4 repair days.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	050H
Vehicle Details	
Vehicle No.:	SDF8962S
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA JAZZ 1.3L A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	L13Z11035319
Chassis No.:	JHMGE68509S235293
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,331.00
Original Registration Date:	08 Oct 2010
First Registration Date:	08 Oct 2010
Transfer Count:	2
Actual ARF Paid:	\$19,331.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2020
PARF Rebate Amount:	\$9,665.00
Intended COE Rebate Details	
COE Expiry Date:	07 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$30,001.00
COE Rebate Amount:	\$2,524.00
Total Rebate Amount:	\$12,189.00

The information contained herein is correct as at 04 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2019 14:05
Date Of Accident	30/11/2019 16:30
Exact Location Of Accident	HAVELOCK RD INTERCHANGE TWDS UPPER PICKERING RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDF8962S
Insured/Policyholder	
Name Of Registered Owner	ALPHA MOTORS PTE. LTD.
Co Reg No	201922050H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90102031
Alternative Phone No	OFFICE-90102031

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5111428824-000021 (TP)
Cover Note Number	

Driver

Name of Driver	LIM KOK PIOW
NRIC No	S2662003A
Date Of Birth	07/05/1967
Occupation	OUTDOOR
Date Of Driving Pass	07/12/1990
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90102031
Fax Number	
Contact Number	OTHERS-90102031
EMail Address	NOEMAIL

Address	BLK 453B FERVALE ROAD #13-517
Postcode	792453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20191202/2169 ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC7662Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM KOK PIOW
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SDF8962S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

03 DEC 2019
03 DEC 2019

Sketch Plan #2 Pg. 1

A-SDF 89626
B-SMC 76627

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/11/2019 at about 4.45pm, I was in car A driving towards Havelock Roads in the direction of upper Pickering Road, I was at the second lane from the left and wanted to filter to the right lane - car B which was travelling at the third lane hit onto the front right side of my car. We came down exchange contact as I was not feeling well, I was given me as I went to see a doctor.


03 DEC 2019

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: 
Date & Time:

QIARMC SketchPlan.com v3

Driver's Signature (if driver is not the policyholder): 
Date & Time:

Reporting Centre Personnel's Signature Name:
NRIC/PIH No.:

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SDF8962S

Model: Honda Jazz

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille X NAI	\$ 180.00
1	Front bonnet lock X NAI	\$ 380.00
1	Front bonnet inner rubber X NAI	\$ 68.20
1	Front bonnet outer rubber X NAI	\$ 86.20
1	Front bumper inner sponge X NAI	\$ 135.90
1	Front bumper side retainers / DR	\$ 145.20
1	Front headlamp lower bracket ? / CRA	\$ 186.00 SS
1	Front grille chrome moulding X NAI	\$ 285.90
1	Front grille logo X NAI	\$ 188.80
1	Front grille X NAI	\$ 628.60
1	Front bumper reinforcement X NAI	\$ 680.60
1	R/H Mud Flap X NAI	\$ 160.00
1	R/H Headlight ? / DR	\$ 660.00
1	Bonnet X NN	\$ 950.00
1	Front bumper / DR	\$ 880.00 572
1	Car Plate and Carplate Holder X NAI	\$ 190.00
1	Front support panel X NAI	\$ 1,670.00

Supp
 front RH for door / OO \$391.51 / S 7,475.40

1823.71
 - 20%
 1458.96

c/f: \$ 9,616.90

S/N. Labour Charges

1	To establish mirror motor & reset wiring focussing	\$	210.00	X
2	To check wiring and reset headlamps focussing.	\$	320.00	30
3	To apply tuff kote.	\$	330.00	30
4	Panel beating.	\$	400.00	✓
5	To sand-down, patch-work, re-spray paint.	\$	800.00	400
		\$	<u>2,060.00</u>	

Total Repair Cost: \$ 9,535.40 860

P- 1458-96
 L- 860
 2318-96
 L/S- 1855-17
 = 1850

Survey: 1st / 2nd / 3rd *[Signature]* (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
 (Contact) 8322 8873
 (Email) _____
 (Signature) *[Signature]*
 (Date/Time) 4/12/19, 3-30pm

4 days
 with panel
 L/S
 Ry AL SMJ

4926.91

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19021386/EQD3N2
Date: 24/12/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29119902
Claimant Vehicle No :	SDF8962S	Insured Vehicle No :	SMC7662Z
Date of Loss:	30/11/2019	Nature of Claim:	TP
		Claim No:	613375

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDF8962S	Engine No:	L13Z11035319
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGE68509S235293
Reg. Date:	08/10/2010 (Man. Year: 2009)	Odometer:	257862 km
Colour:	Silver		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,866.91	1,458.97	6,407.94	81.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	860.00	1,200.00	58.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,926.91	2,318.97	7,607.94	76.64
Approved Total (Overridden) (S\$)		1,850.00		
Nett Amount (S\$)	9,926.91	1,850.00	8,076.91	81.36

INSPECTION

Date of Assignment:	05/12/2019	3 AMK St.62 Link# 01-45
Date Inspected:	04/12/2019 Inspected At:	Repairer: Auburn Auto Pte Ltd
		176 SIN MING DRIVE, #04-18 SIN MING
		AUTOCARE
		Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2019)
Parts: 144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDF8962S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	180.00 F	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	380.00 F	*- FL
3	1		*FRONT BONNET INNER RUBBER	Not Necessary	68.20 F	*- FL
4	1		*FRONT BONNET OUTER RUBBER	Not Necessary	86.20 F	*- FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	135.90 F	*- FL
6	1		*FRONT BUMPER SIDE RETAINERS	Broken	145.20 F	*145.20 FL
7	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	186.00 F	*55.00 FL
8	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	285.90 F	*- FL
9	1		*FRONT GRILLE LOGO	Not Necessary	188.80 F	*- FL
10	1		*FRONT GRILLE	Not Necessary	628.60 F	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	680.60 F	*- FL
12	1		*R/H MUD FLAP	Not Necessary	160.00 F	*- FL
13	1		*R/H HEADLIGHT	Broken	660.00 F	*660.00 FL
14	1		*BONNET	Not Necessary	950.00 F	*- FL
15	1		*FRONT BUMPER	Broken	880.00 F	*572.00 FL
16	1		*CAR PLATE AND CARPLATE HOLDER	Not Necessary	190.00 F	*- FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	1,670.00 F	*- FL
18	1		*FRONT RH FENDER	Dented	391.51 F	*391.51 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,866.91	1,823.71
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	364.74
Total Parts (S\$)	7,866.91	1,458.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO ESTABLISH MIRROR MOTOR & RESET WIRING FOCUSING	New	210.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	320.00	30.00
3	TO APPLY TUFF KOTE	New	330.00	30.00
4	PANEL BEATING	New	400.00	400.00
5	TO SAND-DOWN,PATCH-WORK,RE-SPRAY PAINT	New	800.00	400.00
Gross Labour Cost (S\$)			2,060.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >