



Not Authorized
the pho be hie raly.
4/12/19
Sdy.

TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS



AIG ASIA PACIFIC INSURANCE P/L		NAME : Ms Wong Siew Peng		WIP : 15888	
78 SHENTON WAY		ADDRESS : Blk 330 Serangoon Avenue 3		EXCESS :	
#07-16 CHARTIS BUILDING		#07-363		DATE: 3-Dec-19	
SINGAPORE 079120		Singapore 550330			
ATTN. : MOTOR CLAIMS		TEL : 96288154Mr			
FAX :					
VEH NO :	SLM1085M	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6CW1071H0125416	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA5	DATE REG.:	21-Mar-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MC513-50-221EBB	Dis ✓	\$ 961.20
2	REAR REINFORCEMENT	1	MC235-56-B9XC	See X	\$ 155.40
3	GROMMET, REAR BUMPER	4	MBHN1-50-021A	see ✓	\$ 10.80
4	GROMMET	2	MC235-50-ES1	see ✓	\$ 9.40
5	FASTENER, REAR BUMPER	2	MB45A-56-146A	see ✓	\$ 6.00
6	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	see ✓	\$ 6.40
7	RIVET, REAR BUMPER	4	MBN8F-50-355	see ✓	\$ 22.80
8	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	see ✓	\$ 7.00
9	TAILGATE	1	MCGY3-62-02XF	see X	\$ 1,637.00
10	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	see X	\$ 24.00
11	FASTENER, TRIM	5	MGJ21-68-885B02	see ✓	\$ 15.00
12	LOCK, TAILGATE	1	MC513-62-310A	see X	\$ 256.20
13	STRIKER, LOCK	1	MD652-62-361	see X	\$ 57.90
14	CLIP, FINISHER	3	MEG21-51-SJ3	see ✓	\$ 17.10
15	ORNAMENT, MAZDA	1	MCGY0-51-711	see ✓	\$ 45.30
16	ORNAMENT, 5	1	MCGY0-51-721	see ✓	\$ 36.30
17	ORNAMENT, SKYACTIVE	1	MC597-51-771	see ✓	\$ 80.00
18	REAR WINDSCREEN MOULDING	1	MC513-50-611	see X	\$ 60.50
19	FASTENER, REAR WINDSCREEN	6	MD204-50-896A	see X	\$ 16.80
20	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	see X	\$ 7.20
21	FASTENER, REAR WINDSCREEN	2	MC273-50-896	see X	\$ 16.40
22	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	see X	\$ 51.20
23	PIN STUD, REAR WINDSCREEN	2	MC236-63-938	see X	\$ 29.40
24	PROTECTOR, SPOILER	2	MC514-51-979B	see X	\$ 11.00
25	PROTECTOR, SPOILER	2	MC514-51-972B	see X	\$ 28.20
26	PROTECTOR, SPOILER	2	MC514-51-982B	see X	\$ 24.00
27	CLIP, SPOILER	3	MC514-51-958A	see X	\$ 23.10
28	CLIP, SPOILER	1	MC525-51-958A	see X	\$ 8.70
29	GASKET LHS, TAILGATE	1	MC513-51-318	see ✓	\$ 95.40
30	GASKET RHS, TAILGATE	1	MC513-51-318	see ✓	\$ 95.40

		TOTAL PARTS	\$	3,815.10
		LESS 10%	\$	381.51
		TOTAL PARTS COST	\$	3,433.59
<u>Labour Description</u>				
1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT. <i>Repair 630</i>	1260	\$ 1,890.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. <i>600</i>	1200	\$ 2,400.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	11 X NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	11 X NETT	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	11 X	\$ 315.00
6		TO REMOVE AND INSTALL SPOILER TAILGATE.	11 X	\$ 180.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	<i>should 180</i> NETT	\$ 315.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	11 X NETT	\$ 180.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	<i>scr</i> NETT	\$ 70.00
10	MZ-BR-LTAREG	TO BREAK AND RESEAL VEHICLE WEEKEND NUMBER PLATE LTA REGISTRATION FEE.	✓ NETT	\$ 150.00
11	MZ-BR-INSCEN	TO SEND THE CAR TO INSPECTION CENTRE FOR THE INSTALLATION OF THE WEEKEND NUMBER PLATE.	✓ NETT	\$ 120.00
12	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	11 X	\$ 945.00
13	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	11 X	\$ 350.00
14	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11 X	\$ 250.00
15	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
16	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
17	MZ-BR-SUNDRI	SUNDRIES.	<i>Net 20</i> NETT	\$ 100.00
			TOTAL LABOUR	\$ - \$ 8,545.00
			TOTAL PARTS	\$ - \$ 3,433.59

TOTAL	\$ -	\$ 11,978.59
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No life modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: