

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan, Yoke Shi

Date: 04 Dec 2019

## **Preliminary Advice**

Vehicle No	: SLM1085M	Accident Date	: 02/12/2019
Make	: MAZDA MAZDA5	Policy No.	: 2100504536
Assignment Date	: 04/12/2019	Excess	: S\$0.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 5 days
Inspection At	: Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,978.59
Revised Amount	:S\$	4,567.29
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,567.29
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	40,906.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,094.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :