



not allowed
 4th
 excess 8
 5/12/18
 take photo before

TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L		NAME : Mr Teo Beng Chai		WIP : 15790	
78 SHENTON WAY		ADDRESS : 88 Sea Breeze Avenue		EXCESS :	
#07-16 CHARTIS BUILDING		Singapore 487587		DATE: 3-Dec-19	
SINGAPORE 079120		TEL : 90063399			
ATTN : MOTOR CLAIMS		FAX :			
VEH NO :	SLA8808L	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6GL1071J0133072	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA6	DATE REG.:	31-Jan-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	2	MB45A-56-146A	11 X	\$ 6.00	
2	6	MC274-50-133	11 X	\$ 22.20	
3	6	MGD7A-50-EA1	11 X	\$ 19.20	
4	6	MGHP9-50-355	11 X	\$ 29.40	
5	8	MS51S-51-833	11 X	\$ 32.00	
6	1	MGHP9-52-111A	11 X	\$ 383.70	
7	1	MGHZ9-52-1R0A	11 X	\$ 48.30	
8	1	MGHP9-56-130K	11 X	\$ 114.30	
9	15	MB45A-56-146A	11 X	\$ 45.00	
10	1	MGHY0-58-02XJ	11 X	\$ 975.20	
11	1	MGHP9-58-762A	11 X	\$ 3.20	
12	1	MBF67-51-261	11 X	\$ 2.40	
13	9	MGJ6A-58-975	11 X	\$ 27.00	
14	1	M9991-00-503	11 X	\$ 3.80	
15	1	MGS1D-58-315A	11 X	\$ 2.40	
16	1	MGD7A-50-EA1	11 X	\$ 3.20	
17	1	MKD53-58-210A	11 X	\$ 37.40	
18	1	MD461-59-210B	11 X	\$ 37.80	
19	1	MGHP9-58-270	11 X	\$ 65.70	
20	7	MGJ6A-58-975	11 X	\$ 21.00	
21	1	MGHP9-56-391A	11 X	\$ 82.70	
22	1	M9965-18-7570	11 X	\$ 1,196.80	
TOTAL PARTS				\$ 3,158.70	
LESS 10%				\$ 315.87	
TOTAL PARTS COST				\$ 2,842.83	
Labour Description					

1		TO REPLACE FRONT FENDER RH AND FRONT DOOR RH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	630	\$ 1,260.00
2		TO RESPRAY FRONT FENDER RH AND FRONT DOOR RH.		\$ 1,200.00 ✓
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	NETT	\$ 315.00 ✓
4		TO SUPPLY 1 PC TIRE.	11 X	\$ 480.00
5	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	11 X NETT	\$ 120.00
6	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	11 X NETT	\$ 560.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11 X	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
10	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,885.00
TOTAL PARTS	\$ -	\$ 2,842.83
TOTAL	\$ -	\$ 7,727.83
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

L&S Auto Consultants hence notify the Repairer of the following:

- To respray before/after spray painting
- To respray damaged part(s) during/after repair
- Parts prices are subject to confirmation
- This quotation is on a "Without Prejudice" basis
- Confirmation is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature

Acknowledged by Repairer

Signature:

Date: