

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21401

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1424/2019/NS
Date : 3-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Shetty Rajendra Kumar
Address : BLK 217 YISHUN ST 21
#07-337
Singapore 760217
Telephone : 98389904
Type of Claim : Own Damage Claims
Policy No. : 2100471809-03
Vehicle No : **SLD 6542 A**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : 24/6/2016
Engine No : CNC 168546
Chassis No : WAUZZZ8R6GA139958
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Dec-19
Place of Accident : Yishun Ring Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 6542 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1250 ✓
3	To respray front bumper, front bumper spoiler and rhs front fender.	\$ 3,000.00	1650 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 6,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 6542 A

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
1	FRONT BUMPER <i>Repld</i>	5	2,353.00	✓	1882.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	5	249.00	+	
3	FRONT BUMPER BUMPER FRONT SPOILER <i>Ry 5</i>	5	569.00	+	
4	FRONT BUMPER CLOSING ELEMENT	5	191.00	+	
5	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	5	103.00	+	
6	FRONT BUMPER PULL STRAP	4	187.00	+	
7	FRONT BUMPER SECURING STRIP- RH	5	34.00	+	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	5	319.00	+	
9	FRONT BUMPER GUIDE SECTION - RH <i>Not Nec</i>	5	34.00	?	X
10	FRONT FENDER - RH <i>Repld</i>	5	913.00	✓	730
11	FRONT FENDER ATTACHMENT PARTS <i>Not Nec</i>	5	61.00	?	X
12	FRONT FENDER BRACKET - RH FRONT <i>Ry 2</i>	5	49.00	✓	38.56
13	FRONT FENDER BRACKET - CENTRE <i>Not Nec</i>	5	45.00	?	X
14	FRONT FENDER BRACKET - REAR <i>Not Nec</i>	5	45.00	?	X
15	FRONT FENDER BRACE - RH <i>Not Nec</i>	5	79.00	?	X
16	FRONT WHEEL HOUSING LINER - RH <i>new</i>	5	246.00	+	
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	5	94.00	+	
18	FRONT WHEEL SPOILER - RH <i>new</i>	5	60.00	+	
19	HEADLIGHT MOUNTING - RH <i>new</i>	5	107.00	+	
20	HEADLIGHT RETAINING PLATE - RH <i>new</i>	5	71.00	+	
21	HEADLIGHT - RH <i>ht</i>	5	2,501.00	✓	2000.80
22	LIFT CYLINDER - RH <i>Not Nec</i>	5	181.00	+	
23	SUNDRIES <i>Nec</i>	5	300.00	?	14.40 ✓

TOTAL SPARE PARTS : \$ 8,791.00

TOTAL LABOUR CHARGES : \$ 6,472.00

GRAND TOTAL \$ 15,263.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Adrian Ling
04/12/19

Not Authorised, 05 p.p.s

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No deposit on repair and parts is allowed
- Supplementary work must be resurveyed and it subject to final approval from insurance Company

Authorised by: [Signature]

Signature

Date

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant