

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21401

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1424/2019/NS
Date : 3-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Shetty Rajendra Kumar
Address : BLK 217 YISHUN ST 21
#07-337
Singapore 760217
Telephone : 98389904
Type of Claim : Own Damage Claims
Policy No. : 2100471809-03
Vehicle No : **SLD 6542 A**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : 24/6/2016
Engine No : CNC 168546
Chassis No : WAUZZZ8R6GA139958
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Dec-19
Place of Accident : Yishun Ring Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 6542 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1250 ✓
3	To respray front bumper, front bumper spoiler and rhs front fender.	\$ 3,000.00	1650 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 6,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLD 6542 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Rehd</i>	\$ 2,353.00 ✓	1882.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 249.00 ✕	
3	FRONT BUMPER BUMPER FRONT SPOILER <i>Regis</i>	\$ 569.00 ✕	
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 191.00 ✕	
5	FRONT BUMPER FOAM FILLER PIECE	\$ 103.00 ✕	
6	FRONT BUMPER PULL STRAP 4	\$ 187.00 ✕	
7	FRONT BUMPER SECURING STRIP- RH <i>new</i>	\$ 34.00 ✕	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 319.00 ✕	
9	FRONT BUMPER GUIDE SECTION - RH ? NN	\$ 34.00 ?	✕
10	FRONT FENDER - RH <i>Rehd</i>	\$ 913.00 ✓	730
11	FRONT FENDER ATTACHMENT PARTS ? NN	\$ 61.00 ?	✕
12	FRONT FENDER BRACKET - RH FRONT <i>Regis</i>	\$ 49.00 ✓	38.56
13	FRONT FENDER BRACKET - CENTRE ? NN	\$ 45.00 ?	✕
14	FRONT FENDER BRACKET - REAR ? NN	\$ 45.00 ?	✕
15	FRONT FENDER BRACE - RH ? NN	\$ 79.00 ?	✕
16	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 246.00 ✕	
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 94.00 ✕	
18	FRONT WHEEL SPOILER - RH <i>new</i>	\$ 60.00 ✕	
19	HEADLIGHT MOUNTING - RH <i>new</i>	\$ 107.00 ✕	
20	HEADLIGHT RETAINING PLATE - RH <i>new</i>	\$ 71.00 ✕	
21	HEADLIGHT - RH <i>lit</i>	\$ 2,501.00 ✓	2000.80
22	LIFT CYLINDER - RH <i>new</i>	\$ 181.00 ✕	
23	SUNDRIES ? NEC	\$ 300.00 ?	14.40 ✓

TOTAL SPARE PARTS : \$ 8,791.00

TOTAL LABOUR CHARGES : \$ 6,472.00

GRAND TOTAL \$ 15,263.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 04/12/19
Authorised Date :
Excess Cost :
Liability :
Remarks : 168 Authorised, 05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant