

ASS. REC. BY:

REF:

08/FCI19021400/Ky d3

n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

5:47pm 3/12/19

Estimated Cost:

Bill to:

OD ☒ TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 5964U

Insured:

8HB 6686B

at Workshop m/s

K. Kim Hin

Tel:

64527018

of

160 Sin Ming Drive # 02-20

Policy No:

Claim No:

D19007642 MFSA

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:14am 4/12/19

Person Contacted:

Sandra

Vehicle IN ☒ OUT

Date/Time	Action/Instruction
	1-3/11/19 ✓
	SLN 5964U-X
	8HB 6686B - CC4/1A0A/16001407/H1kg 3.2
	D.O.A. 1/15/2016

ASS. REC. BY:

REF: FC21

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLN 5964Uat Workshop m/s IC KITA

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £70k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 5964UYr Regn: 05, 17Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Altisc.c. 1598Colour: M. Red

A/C: Insured / Std / NI / NA

Sp. Reading: 26184

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH164563122Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 30/11/19D.O.I. 17/12/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to18/12/19 Sent PIP by email13/2/20 PIP \$3020-25 (Red \$2101-22, 41%)

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

F. P. S.

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

PIP \$3020-25

TOTAL

255

140
50
50
15
255



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007642MFSH

Date: 18 Dec 2019

Our Ref: CS/FCI19021400/Kyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN5964U.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/12/2019 at the premises of M/s K.KIM HIN AUTO PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,121.47</u>
Revised Estimate Amount	: S\$ <u>3,020.25</u>
"Check" Items Amount	: S\$ <u>570.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear o/s.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, December 18, 2019 3:41 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007642MFSH/1
Attachments: SLN5964U DOA 30112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLN5964U
Date of survey : 17/12/2019
Number of days : 5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, December 04, 2019 12:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007642MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

MOTOR SURVEY ASSIGNMENT

Date	03-12-2019	Our Ref No. D19007642MFSH
Accident Date	30-11-2019	Claim Type. Third Party
Insured Vehicle	SHB6686B	Third Party Vehicle. SLN5964U
Survey Location	160 SIN MING DRIVE #02-20SIN MING AUTOCITY	
Contact Person.	SANDRA	
Contact No.	64527018/ 96222116	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 170A

Vehicle Details

Vehicle No.: SLN5964U
Vehicle to be Exported: No
Intended Deregistration Date: 02 Dec 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: 1ZRY348797
Chassis No.: MR053REH104563122
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,995.00
Original Registration Date: 11 May 2017
First Registration Date: 11 May 2017
Transfer Count: 0
Actual ARF Paid: \$19,995.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 May 2027
PARF Rebate Amount: \$14,996.00

Intended COE Rebate Details

COE Expiry Date: 10 May 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,000.00
COE Rebate Amount: \$38,678.00
Total Rebate Amount: \$53,674.00

The information contained herein is correct as at 02 Dec 2019

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30901

Vehicle Insured : SHB 6686 B
Accident Date : 30-Nov-2019

Date : 03-Dec-2019

Our Ref : 190724 (FIRST) / SANDRA

PAGE : 1

LOH CHEE TONG (MR)
Singapore

*Not Authorized
Running Blue paint 5 days*

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 CVT (2017) SLN5964U

1 pc o/s rear fender
1 pc o/s rear door
1 pc o/s rear door weatherstrip
1 pc o/s rear door lock
1 pc o/s rear door regulator
1 pc o/s rear door regulator motor
1 pc o/s rear door black sticker(1)
1 pc o/s rear door black sticker(2)

R 986.00 ✓
R 1,079.00 ✓
R 175.00 X
R 333.30 X
175.00 ?
585.00 ?
R 61.00 —
R 61.00 —

3,455.30

Less 25% : -863.83

2,591.47

1 pc o/s rear rim 17"
1 pc o/s rear tyre

R 450.00 sn X
R 240.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 *700*

To remove door's fittings

80.00 *60*

To putty and respray on affected
portions.

800.00 *500*

To apply undersealing

80.00 *60*

To conduct front wheel alignment
test.

80.00 *60*

Total : S\$ 5,121.47

Singapore Dollars Five Thousand One Hundred and
Twenty One and Cents Forty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

* TP: 1st *
CAP

1/2/20



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHB 6686 B
Accident Date : 30-Nov-2019

No. : 30901
Date : 03-Dec-2019

Our Ref : 190724 (FIRST) / SANDRA

PAGE : 1

LOH CHEE TONG (MR)
Singapore

Not within
Penny B4 paint 5 days

811
3020.25

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 CVT (2017) SLN5964U

- 1 pc o/s rear fender
- 1 pc o/s rear door
- 1 pc o/s rear door weatherstrip
- 1 pc o/s rear door lock
- 1 pc o/s rear door regulator
- 1 pc o/s rear door regulator motor
- 1 pc o/s rear door black sticker(1)
- 1 pc o/s rear door black sticker(2)

R1	986.00	✓
R1	1,079.00	✓
R	175.00	X
R	333.30	X
SL	175.00	X
R	585.00	X
R	61.00	✓
R	61.00	✓

3,455.30
Less 25% : -863.83
2,591.47

- 1 pc o/s rear rim 17"
- 1 pc o/s rear tyre

R	450.00	sn X
R	240.00	sn X

2187.00
-25%

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

To remove door's fittings

To putty and respray on affected
portions.

To apply undersealing

To conduct front wheel alignment
test.

1640.25 s/Parts
+ 1380.00 Labour
3045.00

800.00	700
80.00	60
800.00	500
80.00	60
80.00	60

Total : S\$ 5,121.47

Singapore Dollars Five Thousand One Hundred and
Twenty One and Cents Forty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19021400/Kyd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-02-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6686B	Veh. Inspected	SLN 5964U
Policy No.		Coverage (\$)	0.00
Claim No.	D19007642MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	03/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104563122	Colour	METALLIC RED
Odometer	26184	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	7 mm
L/H Front Tyre	215/45 R17	MICHELIN	7 mm
R/H Rear Tyre	215/45 R17	MICHELIN	7 mm
L/H Rear Tyre	215/45 R17	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/11/2019	Inspection Date	17/12/2019
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 5964U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S REAR FENDER	BENT	986.00	986.00
1	O/S REAR DOOR	BENT	1,079.00	1,079.00
1	O/S REAR DOOR WEATHERSTRIP	SERVICEABLE	175.00	-
1	O/S REAR DOOR LOCK	TO REPAIR SEE LABOUR	333.30	-
1	O/S REAR DOOR REGULATOR	SERVICEABLE	175.00	-
1	O/S REAR DOOR REGULATOR MOTOR	SERVICEABLE	585.00	-
1	O/S REAR DOOR BLACK STICKER (1)	NECESSARY	61.00	61.00
1	O/S REAR DOOR BLACK STICKER (2)	NECESSARY	61.00	61.00
	LESS 25% DISCOUNT		-863.83	-546.75
			2,591.47	1,640.25
SPECIAL NETT ITEMS				
1	O/S REAR RIM 17" (SN)	TO REPAIR SEE LABOUR	450.00	-
1	O/S REAR TYRE (SN)	SERVICEABLE	240.00	-
			690.00	-
LABOUR				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S REAR DOOR LOCK AND O/S REAR RIM 17".		800.00	700.00
	TO REMOVE DOOR'S FITTINGS.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		800.00	500.00
	TO APPLY UNDERSEALING.		80.00	60.00
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		80.00	60.00
	-		-	-
	-		-	-
	-		-	-
			1,840.00	1,380.00
GRAND TOTAL			5,121.47	3,020.25
RECOMMENDED COST OF REPAIRS				3,020.25

Report Ref No. CS/FCI19021400/Kyd3n2



Report Ref No. CS/FCI19021400/Kyd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.