

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 05 Dec 2019

Preliminary Advice

Vehicle No	: GBG7993C	Accident Date	: 29/11/2019
Make	: TOYOTA DYNA 150	Policy No.	: 29099690
Assignment Date	: 04/12/2019	Excess	: S\$500.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way Singapore 758059		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,430.00
Revised Amount	:S\$	8,580.00
Check Items (Estimated)	:S\$	850.00
Total	:S\$	9,430.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	27,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,196.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.