

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9629Y**AAD1911-237**

Not Authorised
Resurvey B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 9629Y

JTDKB3FU303082481

TOYOTA

PRIUS

29.11.19

AIG

1/8/2019

03 DEC 2019

		PART	LIST		
1	1	REAR BUMPER	\$ Bu	442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ GNC	332.70	TX
3	1	REAR BUMPER TOWING COVER	\$ SL	15.40	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ Rd/CW	576.30	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$ SL	116.50	} X
6	1	REAR BUMPER SIDE RETAINER RH	\$ SL	117.70	
7	1	REAR TAILGATE	\$ R	1,147.80	
8	1	REAR TAILGATE OUTER GARNISH	\$ SL	925.60	
9	1	COVER, REAR COMBINATION LAMP, RH	\$ SL	64.50	
10	1	COVER, REAR COMBINATION LAMP, LH	\$ SL	64.50	
11	1	GARNISH, BACK DOOR SIDE, LH	\$ SL	95.60	
12	1	GARNISH, BACK DOOR SIDE, RH	\$ SL	95.60	
13	1	BOARD ASSY, BACK DOOR TRIM	\$ SL	259.20	
14	1	REAR TAILGATE WEATHERSTRIP	\$ SL	372.30	
15	1	PANEL SUB-ASSY, BODY LOWER BACK	\$ SL	650.30	
16	1	TAILLAMP LOWER RH	\$ SL	502.00	
17	1	TAILLAMP UPPER RH	\$ SL	451.80	
18	1	REAR BUMPER SIDE RH	\$ SL	123.70	
19	1	REAR BUMPER SIDE LH	\$ SL	123.70	
20	1	TAILLAMP LOWER LH	\$ SL	502.00	
21	1	TAILLAMP UPPER LH	\$ SL	443.30	
22	1	BOARD, BACK DOOR TRIM	\$ SL	225.20	} \$1,018.90 less 25%
23	1	COVER, DECK TRIM, REAR	\$ SL	126.70	
24	1	COVER, FLOOR UNDER, NO 1	\$ SL	175.10	
25	1	COVER, FLOOR UNDER, NO 2	\$ SL	241.90	
26	1	COVER, REAR FLOOR	\$ SL	229.90	
TOTAL \$				8,421.90	\$764.19

Trans-cab Auto Services Pte Ltd**AAD1911-237**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9629Y

25%	\$	2,105.48
	\$	6,316.43

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	Sn	66.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	} X 66
4	1	WINDSCREEN MOULDING	\$	nn	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00	
12	1	REAR WHEEL RIM	\$	Sn	1,570.55	
13	1	REAR TYRE 195/65/15	\$	Sn	350.00	}
14	1	REAR WHEEL RIM COVER	\$	Sn	175.80	
15	1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
16	1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	
TOTAL			\$		3,605.75	

TOTAL PARTS	\$	9,922.18
--------------------	----	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9629Y**AAD1911-237**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	2201
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

	\$	4,500.00	2001
TOTAL	\$	11,340.00	
Over All Total	\$	21,262.18	470

(PART-BY-PART) Repair Days

15 Days P/P & 1,300.18
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: