

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7781C

AAD1911-215

*Not Authorized
Recovery B4 paint
& 300p*

Vehicle No.:		SHB 7781C
Chassis No.:		JTDKB3FU403081582
Vehicle Make:		TOYOTA
Vehicle Model:		PRIUS
Date of Accident :		26.11.19
Third Party Insurer :		NTUC Income <u>IV</u>
Date of Registration :		27/6/2019

03 DEC 2019

PART		LIST	
1	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$ <i>sn</i> 594.80
2	1	REAR FENDER RH	\$ <i>n</i> 854.80
3	1	REAR FENDER LINER	\$ <i>sn</i> 139.80
4	1	REAR BUMPER	\$ <i>sn</i> 442.60
5	1	REAR BUMPER RE-INFORCEMENT	\$ <i>n</i> 332.70
6	1	REAR BUMPER TOWING COVER	\$ <i>sn</i> 15.40
7	1	REAR BUMPER UNDER COVER (BLACK)	\$ <i>sn</i> 576.30
8	1	REAR BUMPER SIDE RETAINER RH	\$ <i>sn</i> 117.70
9	1	TAILLAMP LOWER RH	\$ <i>sn</i> 502.00
10	1	TAILLAMP UPPER RH	\$ <i>sn</i> 451.80
11	1	REAR BUMPER SIDE RH	\$ <i>sn</i> 123.70
12	1	REAR TAILGATE	\$ <i>sn</i> 1,147.80
13	1	PANEL SUB-ASSY, REAR DOOR, RH	\$ <i>sn</i> 1,281.70
TOTAL		\$	6,581.10
25%		\$	1,645.28
		\$	4,935.83

X

Special Nett

1	1	REAR DOOR STICKER '6555-3333'	\$ <i>nn</i> 80.00
2	1	REAR RIGHT WHEEL RIM	\$ <i>sn</i> 1,570.55
3	1	REAR RIGHT WHEEL RIM COVER	\$ <i>sn</i> 175.80
4	1	SET PARKING AID	\$ <i>sn</i> 700.00
5	1	SET REAR BUMPER CLIP	\$ <i>nn</i> 66.00
6	1	REAR BUMPER PROTECTOR	\$ <i>nn</i> 100.00
7	2	REAR WINDSCREEN SEALANT	\$ <i>nn</i> 80.00
8	1	WINDSCREEN MOULDING	\$ <i>nn</i> 100.00

X

Trans-cab Auto Services Pte Ltd

AAD1911-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7781C

9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	}
10	1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i> 47.00	
11	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i> 52.90	
12	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i> 53.50	
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i> 80.00	
14	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i> 80.00	
15	1SET	REAR RH FENDER LINER CLIP	\$	<i>na</i> 25.00	
TOTAL			\$	3,310.75	

TOTAL PARTS	\$	8,246.58
--------------------	-----------	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>801</i>
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1911-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7781C

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>un</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>7</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>4</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>5</i> 170.00	X
TOTAL	\$	11,340.00	
Over All Total	\$	19,586.58	

(PART-BY-PART) Repair Days

~~15~~ DAYS
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: