

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 84582722

TP111
Xiao Tony

ESTIMATE

Repair Code : CLM15826

Date in : 02/12/2019

Vehicle Num. : SLR1815Y

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31223574/LEB5923588

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1080.50	✓ 1,080.50
FRONT RH DOOR BLACK TAPE <i>me</i>	1	39.20	✓ 39.20
FRONT RH DOOR HINGE LOWER <i>me</i>	1	55.00	+ 55.00
FRONT RH DOOR WEATHER STRIP (LOWER) <i>me</i>	1	89.00	+ 89.00
Subtotal before discount			1,263.70
Percentage discount 20%			252.74
Sub-total 1			1,010.96
Parts-total			1,263.70

LABOUR

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

✓ 80.00

680 400 500.00

200 300.00

+ 60.00

940.00

2,203.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices *is subject to confirmation*
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 1

Adrian Lj
L/S 04/12/19

03 Days

total: 1575.76

L/S: 12K ✓