

ASSIGNMENT

From: 4/12/19
 Date: 4/12/19
 Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: EY 800 S
 at Workshop o/s: premium
 of: 281 Alexander Road
 Insured:
 Policy No:
 Claims No:
 Sum Insured: \$11001-
 Excess: TBA
 (Client's Record)
 Make of Veh: 2pm
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Est. or Market Value: 86k
 IDAC Accident Rpt. Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: days Res.: Yes or No
 Lim Sum: % 3 Val.: Yes or No
 CA / REV REP. / 24 HRS
 Date: Person Contacted: Vehicle: IN / OUT

Veh No: EY 800 S Reg: 2017 SEP
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A3 SEDAN 1.0 TFSI TRAIL 999
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 21451 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WAAZ228V7J1012155
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 25/11/19 D.O.L. 04/12/19
 Survey held at PREMIUM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction
4/12 - revert via menmen
5/12 @ 12:06 approval by Lim Kok Chong
5/12 @ 1:51am email to per premium anthony repair
Part by Part #7894.72 (Red. 6306.28: 44%)

RECEIVED 11 MAR 2020

Date/Time: File Pass to: ☐ Prel. Report ☒ Final Report
 n 11/3 Typist
 Date/Time: File Return to:
 Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Insp. (\$)
☐ Wash. Insp. (\$)
 Report Format: OD
 Lump Sum / Fee: 7894.72
 Days Of Repair: 3
 Resurvey No. of Trip: 1
 Survey Fee: 200
 Transport: 11
 3 + 10 = 11
 211

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 04 Dec 2019

Preliminary Advice

Vehicle No	: EY800S	Accident Date	: 25/11/2019
Make	: AUDI A3	Policy No.	: 1900152327
Assignment Date	: 04/12/2019	Excess	: S\$0.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,201.00
Revised Amount	:S\$	8,711.00
Check Items (Estimated)	:S\$	2,195.00
Total	:S\$	10,906.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	40,245.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,755.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 2 December 2019 10:03 AM
To: 'SUR'; 'assignments'
Subject: OD CLAIMS FOR EY 800 S
Attachments: SDY 800 S 25112019 GIA.PDF

Dear all,

Please register OD claims for the above mentioned vehicle.

Attached is the GIA report for your reference.

Kindly arrange the survey on 4/11/2019@2pm, owner waiting.

Address : 281 Alexandra Road Singapore 159938

Thank you.

Best Regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6366 2323, option 1

e. Claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***EY800S (2110548319SG)**

OD

Nov 25 2019 12:30PM

[YEOH LAI ANN @YANG LAI ANN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/12/2019 12:06 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10906.00) - EY800S - Claim Handler: Chan, Yoke Shi

Approved:10906.00:Please resurvey for checked / hidden and supplementary items if require and upload in Merimen.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 5 December 2019 1:57 PM
To: 'Claims'; SUR; assignments
Subject: RE: OD CLAIMS FOR EY 800 S

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle EY 800S (Excess \$1,100/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 5 December 2019 9:32 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: OD CLAIMS FOR EY 800 S

Dear Denise,

Above is a soft copy of clearest DL (front and back) for your reference.

Thank you.

Best Regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
281 Alexandra Road Singapore 159938
p. +65 6366 2323, option 1
e. Claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom 281 Alexandra Road Singapore 159938 p. +65 68362223

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	842Z
Vehicle Details	
Vehicle No.:	EY8005
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CHZ529742
Chassis No.:	WAUZZZ8V7J1012155
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,472.00
Original Registration Date:	20 Sep 2017
First Registration Date:	20 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$16,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2027
PARF Rebate Amount:	\$12,195.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$28,050.00
Total Rebate Amount:	\$40,245.00

The information contained herein is correct as at 04 Dec 2019.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2019 19:17
Date Of Accident	25/11/2019 12:30
Exact Location Of Accident	PIXEL BUILDING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EY800S
Insured/Policyholder	
Name Of Registered Owner	YEOH LAI ANN @YANG LAI ANN
NRIC No	S0072842Z
Email Address	YANGSIA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96345800
Alternative Phone No	OFFICE-64634966

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900152327
Cover Note Number	

Driver

Name of Driver	YANG JIE SHENG, ERNEST
NRIC No	S9146201Z
Date Of Birth	12/12/1991
Occupation	INDOOR
Date Of Driving Pass	15/03/2011
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	+65-96345800
Fax Number	
Contact Number	OFFICE-64634966
Email Address	EYHS3WO@GMAIL.COM

Address	150B CORONATION RD WEST
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I SCRAPPED THE FRONT RIGHT OF THE CAR AGAINST TICKET GANTRY. I WAS BEHIND FOR ANOTHER MEETING AND MISJUDGES THE WIDENESS OF THE TURN. THERE WAS NO CONCRETE PLATFORM UNDER THE GANTRY TO PREVENT THIS. I NOTICED A FEW SCRATCHES ON MY FRONT CAR BUMPER. THE NEXT MORNING, I REALIZED THAT THE WATER HAD SEEPED INTO MY HEADLIGHT VIA A SCRATCH THERE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature:
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: SEENY KUMAR SENESEKERA
NRIC/NIH No: 62487490

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I scraped the front end of the car against the grating. I was holding for another meeting and misjudged the width of the turn. As there was no concrete platform under the grating to prevent this. I noticed a few scratches on my front car bumper. The next morning, I realised that the water had seeped into my headlight via a scratch there.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Walteri Edmond Sene, Mary
NRIC/IN No: 62539 1438

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20918

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1414/2019/NS
Date : 29-Nov-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yeoh Lain Ann @ Yang Lai Ann
Address : 150B Coronation Road West
Singapore 269367
Telephone : HP +65 96345800
Type of Claim : Own Damage Claims
Policy No. : 1900152327
Vehicle No : **EY 800 S**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 529742
Chassis No : WAUZZZ8V7J1012155
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Nov-19
Place of Accident : Pixel Building

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 800 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 750	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 2,852.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 800 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>de/</i>	\$ 1,830.00	<i>1464</i>
2	FRONT BUMPER FIXING PARTS <i>X SVC</i>	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH <i>X SVC</i>	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X SVC</i>	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH <i>X SVC</i>	\$ 270.00	
6	FRONT BUMPER COVER TRIM - RH <i>X SVC</i>	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - RH <i>X SVC</i>	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>X SVC</i>	\$ 171.00	
9	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>X SVC</i>	\$ 660.00	
10	FRONT BUMPER FOAM FILLER PIECE <i>X SVC</i>	\$ 172.00	
11	REINFORCEMENT BEAM COVER <i>X SVC</i>	\$ 111.00	
12	LED HEADLIGHT - RH <i>ca/</i>	\$ 5,029.00	<i>4023.4020</i>
13	LED UNIT - RH <i>? SVC</i>	\$ 666.00	
14	HEADLIGHT HOSE - RH <i>X SVC</i>	\$ 36.00	
15	LIGHT CONTROL SYSTEM CONTROL UNIT <i>? x SVC</i>	\$ 508.00	
16	MAIN LIGHT ELECTRONICS POWER MODULE <i>? x short</i>	\$ 693.00	<i>554</i>
17	LIFT CYLINDER <i>? x SVC</i>	\$ 128.00	
18	SUNDRIES <i>? new</i>	\$ 200.00	<i>1.92</i>
TOTAL SPARE PARTS		: \$ 11,349.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	
GRAND TOTAL		: \$ 14,201.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Handwritten signature
5/12/19

Name

: Rasuk - Hp 90010068

Surveyed Date

: 3 days

Authorised Date

: 04/12/19 @ 1400hrs

Excess Cost

: EXCESS: TBA

Liability

: REVERT

Remarks

Rasung before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants (Singapore) Pte Ltd
(the Repainer of the Estimate)
• To resurvey before the work commences
• To display damaged parts and accessories
• Parts prices are subject to change
• Third party survey is one of the conditions of the estimate
• No illegal modification of the vehicle
• Supplementary work is subject to final approval of the Repainer

Acknowledged by Repainer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Dante

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20918

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1414/2019/NS
Date : 29-Nov-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yeoh Lain Ann @ Yang Lai Ann
Address : 150B Coronation Road West
Singapore 269367
Telephone : HP +65 96345800
Type of Claim : Own Damage Claims
Policy No. : 1900152327
Vehicle No : **EY 800 S**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 529742
Chassis No : WAUZZZ8V7J1012155
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Nov-19
Place of Accident : Pixel Building

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 800 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	750 ✓
3	To respray front bumper.	\$ 900.00	550 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 800 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>de</i>	\$ 1,830.00	1464
2	FRONT BUMPER FIXING PARTS <i>X sue</i>	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH <i>X sue</i>	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X sue</i>	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH <i>X sue</i>	\$ 270.00	
6	FRONT BUMPER COVER TRIM - RH <i>X sue</i>	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - RH <i>X sue</i>	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>X sue</i>	\$ 171.00	
9	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>X sue</i>	\$ 660.00	
10	FRONT BUMPER FOAM FILLER PIECE <i>X sue</i>	\$ 172.00	
11	REINFORCEMENT BEAM COVER <i>X sue</i>	\$ 111.00	
12	LED HEADLIGHT - RH <i>can</i>	\$ 5,029.00	4 023.20
13	LED UNIT - RH <i>? X sue</i>	\$ 666.00	
14	HEADLIGHT HOSE - RH <i>X sue</i>	\$ 36.00	
15	LIGHT CONTROL SYSTEM CONTROL UNIT <i>? X sue</i>	\$ 508.00	
16	MAIN LIGHT ELECTRONICS POWER MODULE <i>? short</i>	\$ 693.00	554.00
17	LIFT CYLINDER <i>? X sue</i>	\$ 128.00	
18	SUNDRIES <i>? new</i>	\$ 200.00	1.52
TOTAL SPARE PARTS		: \$ 11,349.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	
GRAND TOTAL		: \$ 14,201.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved; Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasuk - Hp 90010068

Surveyed Date

: 3 days

Authorised Date

: 04/12/15 @ 1400hrs

Excess Cost

: EXCESS: TBA

Liability

: EXCESS: TBA

Remarks

: REPAIR
Resurvey before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20918

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1414/2019/NS
Date : 29-Nov-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Rasul,

3 days - ok - Jy - 12 Feb 2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yeoh Lain Ann @ Yang Lai Ann
Address : 150B Coronation Road West
Singapore 269367
Telephone : HP +65 96345800
Type of Claim : Own Damage Claims
Policy No. : 1900152327
Vehicle No : **EY 800 S**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 529742
Chassis No : WAUZZZ8V7J1012155
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Nov-19
Place of Accident : Pixel Building

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 800 S

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00 ✓
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 1,400.00	\$	750.00 ✓
3	To respray front bumper.		\$ 900.00	\$	550.00 ✓
4	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00 ✓
TOTAL LABOUR CHARGES		:	\$ 2,852.00	\$	1,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 800 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	\$ 270.00	
6	FRONT BUMPER COVER TRIM - RH	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - RH	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 171.00	
9	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 660.00	
10	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
11	REINFORCEMENT BEAM COVER	\$ 111.00	
12	LED HEADLIGHT - RH	\$ 5,029.00	\$ 4,023.20
13	LED UNIT - RH	\$ 666.00	
14	HEADLIGHT HOSE - RH	\$ 36.00	
15	LIGHT CONTROL SYSTEM CONTROL UNIT	\$ 508.00	
16	MAIN LIGHT ELECTRONICS POWER MODULE	\$ 693.00	\$ 554.00
17	LIFT CYLINDER	\$ 128.00	
18	SUNDRIES	\$ 200.00	\$ 1.52
TOTAL SPARE PARTS		: \$ 11,349.00	\$ 6,042.72
TOTAL LABOUR CHARGES		: \$ 2,852.00	\$ 1,852.00
GRAND TOTAL		: \$ 14,201.00	\$ 7,894.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 800 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	750
3	To respray front bumper.	\$ 900.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

Telefax

Material List for Accident Vehicle Regn No. EY 800 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>de</i>	\$ 1,830.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH <i>X</i>	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X</i>	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH <i>X</i>	\$ 270.00	
6	FRONT BUMPER COVER TRIM - RH <i>X</i>	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - RH <i>X</i>	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>X</i>	\$ 171.00	
9	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>X</i>	\$ 660.00	
10	FRONT BUMPER FOAM FILLER PIECE <i>X</i>	\$ 172.00	
11	REINFORCEMENT BEAM COVER <i>X</i>	\$ 111.00	
12	LED HEADLIGHT - RH <i>cal</i>	\$ 5,029.00	
13	LED UNIT - RH <i>?</i>	\$ 666.00	
14	HEADLIGHT HOSE - RH <i>X</i>	\$ 36.00	
15	LIGHT CONTROL SYSTEM CONTROL UNIT <i>?</i>	\$ 508.00	
16	MAIN LIGHT ELECTRONICS POWER MODULE <i>?</i>	\$ 693.00	
17	LIFT CYLINDER <i>?</i>	\$ 128.00	
18	SUNDRIES <i>?</i>	\$ 200.00	

TOTAL SPARE PARTS

: \$ 11,349.00

TOTAL LABOUR CHARGES

: \$ 2,852.00

GRAND TOTAL

: \$ 14,201.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Rasuk - 4p 90010068

Surveyed Date

: 3 days

Authorised Date

: 04/12/15 @ 1400hrs

Excess Cost

: EXCESS: TBA

Liability

: REVERT

Remarks

Resurvey before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after survey printing
- To display damaged parts to owner/insurer
- Parts prices are subject to market price
- Third party survey is not a substitute for our own
- No illegal modifications are allowed
- Supplementary items, must be approved by us
- is subject to final approval from the insurer

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: EY 800 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1414/2019/NH

9th March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR EY 800 S, Audi A3 SEDAN 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **EY 800 S**, claimant, **Mr. Yeoh Lain Ann**, please find the related document per attached.

1. A copy of the Original invoice no. 85014957 – S\$ 7,270.35.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – EY 800 S

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6896 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2223
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:03

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014957 Date : 05/03/2020 Order : EY0800S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: EY0800S (V 35180)	Regn Date: 20/09/2017	Mileage: 21585	WIP No.: 20918
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7J1012155	Engine: CHZ 529742	Dept: U
You have been assisted by :- UB-Tony Poong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8886 Insurance Excess/Liability	-1100.00	1.00	-1,100.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5807065R GRU	COVER(LAST)	1.00	1830.00	1,464.00
X	A8V0941774D	HEADLIGHT	1.00	5029.00	4,029.20
X	A7PP941572AC	POWER MOD AP	1.00	692.50	554.00
X	AN 10261507	FLAT FUSE	1.00	1.90	1.52

Parts 6,042.72
Labour 0.00
Sublet 1,852.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,794.72

7% GST 475.63

Grand Total 7,270.35



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: EY 800 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1414/2019/TG
13 Dec 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V7J1012155
Vehicle Regn No. : EY 800 S
Vehicle Mileage : 21585 KM
Vehicle Owner : Mr. Yeoh Lain Ann @ Yang Lai Ann
Certificate No : 1900152327
Own Damage Excess : S 1177.00 (Inclusive GST)
Accident Date : 25/11/2019
Place : Pixel Building
Repair Cost : S\$ 7370.35
WIP No. : 20918
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019		04 Dec 2019 15:13 Edit Adj Rpt	S\$7,894.72 Edit Estimates	S\$7,894.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: YEON LAI ANN @YANG LAI ANN , ID: S00728422, Tel: +6596345800									
Vehicle Reg. No.: EY800S		Date of Loss: 25/11/2019 12:00 - :59 [26 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 2110548319SG		Policy/Cover Note No.: 1900152327 (Comprehensive)							
		Excess: S\$1,100.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/12/2019]									
Driver/Custodian: YANG JIE SHENG, ERNEST (27 / Male) , NRIC: S9146201Z, Tel: +6596345800 Email: EYHS3WO@GMAIL.COM									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- AIG_SG (05/12/2019): Alert - Adj Mandate Approved (S\$10906.00) - EY800S - Claim Handler: Chan, Yoke S... - AIG_SG (05/12/2019): EY800S / OD / 25/11/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***EY800S (2110548319SG)**
OD
Nov 25 2019 12:30PM
[YEOH LAI ANN @YANG LAI ANN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	04/12/19 16:17	Adjuster Immediate Advice																Load HTM		
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	05/12/19 09:49	General View																Load JPG		
2	05/12/19 09:49	General View																Load JPG		
3	05/12/19 09:49	General View																Load JPG		
4	05/12/19 09:49	General View																Load JPG		
5	05/12/19 09:49	General View																Load JPG		
6	05/12/19 09:49	General View																Load JPG		
7	05/12/19 09:49	General View																Load JPG		
8	05/12/19 09:49	General View																Load JPG		
9	05/12/19 09:49	General View																Load JPG		
10	05/12/19 09:49	General View																Load JPG		
11	05/12/19 09:49	General View																Load JPG		
12	05/12/19 09:49	General View																Load JPG		
13	05/12/19 09:49	General View																Load JPG		
14	05/12/19 09:49	General View																Load JPG		
15	05/12/19 09:49	General View																Load JPG		
16	05/12/19 09:49	General View																Load JPG		
17	05/12/19 09:49	General View																Load JPG		
18	05/12/19 09:49	General View																Load JPG		
19	05/12/19 09:49	General View																Load JPG		
20	05/12/19 09:49	General View																Load JPG		
21	05/12/19 09:49	General View																Load JPG		
22	05/12/19 09:49	General View																Load JPG		
23	05/12/19 09:49	General View																Load JPG		
24	11/03/20 15:47	Reinspection Photo																Load JPG		
25	11/03/20 15:47	Reinspection Photo																Load JPG		
26	11/03/20 15:47	Reinspection Photo																Load JPG		
27	11/03/20 15:47	Reinspection Photo																Load JPG		
28	11/03/20 15:47	Reinspection Photo																Load JPG		
29	11/03/20 15:47	Reinspection Photo																Load JPG		
30	11/03/20 15:47	Reinspection Photo																Load JPG		
Documentation															1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	04/12/19 16:26	ESTIMATE																Load PDF		
2	04/12/19 16:37	GIA REPORT																Load PDF		
3	04/12/19 17:23	CI, UNDERTAKING LETTER, INTERVIEW FORM, DL																Load PDF		
4	05/12/19 09:47	Driver's Driving License																Load JPG		
5	13/03/20 09:09	WORKSHOP INVOICE																Load PDF		
6	13/03/20 09:10	DISCHARGE VOUCHER																Load PDF		

Linked Accident Report Documents

			View View in Browser ▼	
Assessment Reports			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/12/19 10:00	Addendum Sheet	Load JPG	
2	06/12/19 19:37	Accident Statement	Load HTM	
3	06/12/19 19:39	Accident Statement	Load HTM	
4	06/12/19 19:42	Accident Statement	Load HTM	
5	06/12/19 19:43	Accident Statement	Load HTM	
6	06/12/19 19:44	Accident Statement	Load HTM	
7	06/12/19 19:44	Accident Statement	Load HTM	
8	06/12/19 19:45	Accident Statement	Load HTM	
9	06/12/19 19:45	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/12/19 09:48	Accident Photo	Load JPG	
2	02/12/19 09:48	Accident Photo	Load JPG	
3	02/12/19 09:48	Accident Photo	Load JPG	
4	02/12/19 09:48	Accident Photo	Load JPG	
5	02/12/19 09:48	Accident Photo	Load JPG	
6	02/12/19 09:48	Accident Photo	Load JPG	
7	02/12/19 09:48	Accident Photo	Load JPG	
Documentation			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/11/19 19:31	Sketch Plan	Load JPG	
2	26/11/19 19:31	Sketch Plan #2	Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19021428/R1TF3N2

Date: 13/03/2020

REFERENCE

Insured/Claimant: YEOH LAI ANN @YANG LAI ANN

Policy No: 1900152327

Date of Loss: 25/11/2019

Nature of Claim: OD

Claim No: 2110548319SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EY800S

Make & Model: AUDI A3, 999cc SEDAN TFSI (A)

Engine No: CHZ529742

Reg. Date: 20/09/2017 (Man. Year: 2017)

Chassis No: WAUZZZ8V7J1012155

Colour: Blue

Odometer: 21451 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$86,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,349.00	6,042.72	5,306.28	46.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,852.00	1,000.00	35.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,201.00	7,894.72	6,306.28	44.41
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	13,101.00	6,794.72	6,306.28	48.14
+ GST 7.00/7.00% (S\$)	917.07	475.63	441.44	48.14
Nett Amount (S\$)	14,018.07	7,270.35	6,747.72	48.14

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At:

281 Alexandra Road

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-RH	Serviceable	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Serviceable	488.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-RH	Serviceable	270.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM-RH	Serviceable	148.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ADAPTER-RH	Serviceable	34.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Serviceable	171.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Serviceable	660.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	172.00 FS	*- FS
11	1		*REINFORCEMENT BEAM COVER	Serviceable	111.00 FS	*- FS
12	1		*LED HEADLIGHT-RH	Cracked	5,029.00 FS	*4,023.20 FS
13	1		*LED UNIT-RH	Serviceable	666.00 FS	*- FS
14	1		*HEADLIGHT HOSE-RH	Serviceable	36.00 FS	*- FS
15	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Serviceable	508.00 FS	*- FS
16	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Shorted	693.00 FS	*554.00 FS
17	1		*LIFT CYLINDER	Serviceable	128.00 FS	*- FS
18	1		*SUNDRIES	Necessary	200.00 FS	*1.52 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,349.00	6,042.72
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHTS.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,852.00	1,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >