

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21329

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1421/2019/NS
Date : 3-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6221 2111

Owner's Name : Mr Teo Yat Seng
Address : 3 Hume Avenue
#07-04
Singapore 598719
Telephone : HP +65 98370772
Type of Claim : Own Damage Claim
Policy No. : 2100403929-04
Vehicle No : **SKR 6678 E**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Feb-15
Engine No : CZC 209813
Chassis No : WAUZZZ8V6F1042870
Mileage : 96345
Date In : 2-Dec-19
Estimated By : Allan Wu
Accident Date : 30-Nov-19
Place of Accident : Along PIE Before Bedok North Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00 /	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00 /	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays electrical and audio equipment.	S/N	\$ 480.00 /	
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panel and spare wheel housing. Re-organise crash management components. Reinstall all parts removed.		\$ 7,700.00	3000
SUB TOTAL LABOUR CHARGES			:	\$ 8,740.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To rep-spray rear bumper, rear lid, end panel and spare wheel housing. To carry out joint sealer works and stone chip treatment.		\$ 3,900.00	2800
6	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N	\$ 780.00	/
7	To remove and renew lhs rear exhaust silencer. To align to position.	S/N	\$ 480.00	? photo
8	to carry out diagnostic check.	S/N	\$ 192.00	/
TOTAL LABOUR CHARGES		:	\$ 14,092.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / <i>DD</i>	\$ 1,708.00	
2	REAR BUMPER FIXING PARTS ?	\$ 175.00	
3	REAR BUMPER GUIDE SECTION - LH / RH / <i>DR</i>	2 \$ 30.00	
4	REAR BUMPER LOCKING MECHANISM ?	\$ 53.00	
5	REAR BUMPER SPOILER - LH (1m) / <i>CRH</i>	\$ 216.00	
6	REAR LIGHT REFLECTOR - (LH) / RH / <i>CRA</i>	2 \$ 76.00	38
7	REAR BUMPER SIDE REINFORCEMENT BEAM ? / <i>M</i>	\$ 522.00	
8	REAR BUMPER BRACKET - LH / RH / <i>DR</i>	2 \$ 24.00	
9	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$ 120.00	
10	REAR PARKING AID SENSOR - INNER / OUTER	4 <i>2</i> \$ / <i>SL</i> 924.00	462
11	REAR PARKING AID SEAL RING / <i>M</i>	4 \$ 12.00	
12	REAR BUMPER WIRING SET ?	\$ 472.00	
13	REAR LID / <i>DD</i>	\$ 2,417.00	
14	REAR LID ATTACHMENT PARTS ? X	\$ 267.00	
15	REAR LID HINGE - LH / TH ?	2 \$ 466.00	
16	FLAP GASKET ?	\$ 185.00	
17	BONNET LOCK STRIKER / <i>BT</i>	\$ 45.00	
18	REAR LID LOCK / <i>BT</i>	\$ 178.00	
19	REAR LOCK COVER / <i>CRH</i>	\$ 7.00	
20	LIC LOCK PUSH BUTTON X	\$ 167.00	
SUB TOTAL SPARE PARTS		: \$ 8,064.00	

4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	PROTECT CAP ?	4	\$	14.00
22	PACKING ADHESIVE / MC		\$	18.00
23	AUDI EMBLEM / MC		\$	113.00
24	A3 INSCRIPTION / MC		\$	87.00
25	TFSI INSCRIPTION / MC		\$	87.00
26	LED TAIL LIGHT - LH / RH OUTER / CUT 21	\$	1,600.00	800
27	LED TAIL LIGHT TRIM - LH / RH OUTER / MC 2	\$	54.00	
28	LED TAIL LIGHT - LH / RH INNER / CUT 21	\$	1,600.00	800
29	LED TAIL LIGHT TRIM - LH / RH INNER X 2	\$	54.00	
30	REAR CROSS PANEL / DD		\$	329.00
31	REAR CROSS PANEL REINFORCEMENT / DD		\$	669.00
32	REAR FLOOR PAN (Spec type PM) / DD		\$	622.00
33	REAR LID TRIM PANEL / CRU		\$	284.00
34	REAR CROSS PANEL TRIM / CRU		\$	141.00
35	LUGGAGE COMPARTMENT FLOOR COVER / DR		\$	495.00
36	LED LICENSE PLATE LIGHT X 2	\$	105.00	
37	ACRYLIC SEALANT / MC	S/N	\$	180.00
38	CAVITY WAX / MC	S/N	\$	140.00
39	STONE CHIP / MC	S/N	\$	180.00
40	REAR NO PLATE X	S/N	\$	40.00
41	SUNDRIES ?		\$	400.00

TOTAL SPARE PARTS	:	\$ 15,276.00
TOTAL LABOUR CHARGES	:	\$ 14,092.00
GRAND TOTAL	:	\$ 29,368.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

4/12/19, 1-3pm
Steve (LKK) OO - Not Author
EXCESS - ?
10 days
P/P
Ry DEL SPY

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant