

Police Report



**SINGAPORE
POLICE FORCE**



T20191130/2161

2 of 4

Report No. T20191130/2161

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470628
Tel No: 1800-4439999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKR6678E	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100403929-04	27/02/2019	26/02/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	MOHAMED DANIAL BIN MOHAMED SALEM		ID No.	S9735966G
Related Vehicle	SJD9785U (Car)		Contact No.	98718554
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	TEO YAT SENG		ID No.	S2550822Z
Related Vehicle	SKR6678E (Car)		Contact No.	96370772
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 30/11/19 at about 2015hrs, I was driving my car(SKR6678E) along PIE towards Changi Airport before Bedok North exit, the vehicles in front of me came to stop as such I also stop my vehicle. About few seconds later, suddenly the second car(SJD9785U) collided onto the rear of my car. Both of us got down from our car to take a look on the accident. When I came out from my car, I saw there was a third car(SJG5364L) behind the second car which had collided onto my vehicle. I assume that that was a chain accident involving another 2 vehicles. I asked if anyone was injured, the driver of the 2nd car said he was calling the ambulance as his passenger was carrying a baby during the accident. The 2nd car driver also called for police assistance while waiting for the ambulance.

On the arrival of traffic police, the officer took our particulars and also ask for the story of the accident. Upon the arrival of the ambulance, the paramedics made a check on the 2nd car driver passenger and also the passenger of my car as the female passenger that was in my car felt pain on the her neck due to the accident. As such the paramedics called for another ambulance down. After the paramedics made a check both my female passenger and the 2nd car passenger was conveyed by ambulance to hospital, I

Police Report



**SINGAPORE
POLICE FORCE**



T/2019/1302161

3 of 4

Report No. T/2019/1302161

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

was then asked by the traffic police to lodge a traffic accident report.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470829
Tel No: 1800-4439999



T/2019/1130/2161

4 of 4

Report No. T/2019/1130/2161

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Staff Sgt SOONG PEI XING

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / GIT /
Sr Staff Sgt MOHAMMED FEROUZ BIN HUSSEIN
Contact No.: 65476206

Authentication Stamp
NF168

Signature Of Informant:

Date/Time:
30/11/2019 22:09

Classification Of Case:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
E-Kolliya Quay #10-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0010
Operating Hours: Monday to Friday, 09:00 - 17:00
LIN 3643580250 / GST Reg. No. M609017225

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA119158712 Vehicle Registration No: SKR6678E
Name (as shown in NRIC) : TEO YAT SENG NRIC/FIN/Passport No : S2550822Z
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 3 HUME AVENUE, #07-04 Singapore 598779
Contact (Tel) : --- Mobile No : 98370772
Email Address : YS_TEO_SG@YAHOO.COM.SG
Date of Accident : 30/11/2019 Time of Accident : 20.15
Place of Accident : ALONG PIE BEFORE BEDOK NORTH EXIT
Insurance Company : AIG ASIA PACIFIC INSURANCE PTE. LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

CONVERT CLAIM TO OD CLAIM

Policyholder / Driver's Signature

Date: 4th DEC 2019



Reporting Centre Personnel's Signature

Name: Toy Foo
NRIC/FIN No: C230801471
Date: 4/12/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21329

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1421/2019/NS
Date	:	3-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6221 2111

Owner's Name	:	Mr Teo Yat Seng
Address	:	3 Hume Avenue #07-04 Singapore 598719
Telephone	:	HP +65 98370772
Type of Claim	:	Own Damage Claim
Policy No.	:	2100403929-04
Vehicle No	:	SKR 6678 E
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	Feb-15
Engine No	:	CZC 209813
Chassis No	:	WAUZZZ8V6F1042870
Mileage	:	96345
Date In	:	2-Dec-19
Estimated By	:	Allan Wu
Accident Date	:	30-Nov-19
Place of Accident	:	Along PIE Before Bedok North Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00 ✓	✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays electrical and audio equipment.	S/N	\$ 480.00 ✓	✓
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panel and spare wheel housing. Re-organise crash management components. Reinstall all parts removed. <i>500 x 6</i>		\$ 7,700.00 <i>3000</i> ✓	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 8,740.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To rep-spray rear bumper, rear lid, end panel and spare wheel housing. To carry out joint sealer works and stone chip treatment. <i>SSR</i>	\$	3,900.00 <i>2800</i>	✓
6	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N	\$ 780.00 ✓	✓
7	To remove and renew lhs rear exhaust silencer. To align to position.	S/N	\$ 480.00 ? <i>photo</i>	✗
8	to carry out diagnostic check.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 14,092.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / DD	\$ 1,708.00	1366.40
2	REAR BUMPER FIXING PARTS ?	\$ 175.00	X NN
3	REAR BUMPER GUIDE SECTION - LH / RH / DR	2 \$ 30.00	22.88
4	REAR BUMPER LOCKING MECHANISM ? X NN	\$ 53.00	X
5	REAR BUMPER SPOILER - LH (1m) / CRU	\$ 216.00	172.80
6	REAR LIGHT REFLECTOR - LH / RH / CRA	2 \$ 76.00	38 29.68
7	REAR BUMPER SIDE REINFORCEMENT BEAM ? / M	\$ 522.00	417.60
8	REAR BUMPER BRACKET - LH / RH / DR	2 \$ 24.00	17.92
9	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$ 120.00	X NN
10	REAR PARKING AID SENSOR - INNER / OUTER	4 2 \$ 924.00	462 369.60
11	REAR PARKING AID SEAL RING / M	4 \$ 12.00	10.24
12	REAR BUMPER WIRING SET ?	\$ 472.00	X NN
13	REAR LID / DD	\$ 2,417.00	1933.60
14	REAR LID ATTACHMENT PARTS ? X NN	\$ 267.00	
15	REAR LID HINGE - LH / TH ?	2 \$ 466.00	X NN
16	FLAP GASKET ? / CRU	\$ 185.00	147.60
17	BONNET LOCK STRIKER / BT	\$ 45.00	36
18	REAR LID LOCK / CRU BT	\$ 178.00	142.40
19	REAR LOCK COVER / CRU	\$ 7.00	5.00
20	LIC LOCK PUSH BUTTON X NN	\$ 167.00	
SUB TOTAL SPARE PARTS		: \$ 8,064.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description		S/NETT	Damage Parts & Prices	
				S/NETT	REMARKS
21	PROTECT CAP ?	4	\$	14.00	X NN
22	PACKING ADHESIVE / MC		\$	18.00	13.92
23	AUDI EMBLEM / MC		\$	113.00	90
24	A3 INSCRIPTION / MC		\$	87.00	69.38
25	TFSI INSCRIPTION / MC		\$	87.00	69.38
26	LED TAIL LIGHT - LH / RH OUTER / CUT	2/1	\$	1,600.00	800 640
27	LED TAIL LIGHT TRIM - LH / RH OUTER / MC	2	\$	54.00	21.52
28	LED TAIL LIGHT - LH / RH INNER / CUT	2/1	\$	1,600.00	800 640
29	LED TAIL LIGHT TRIM - LH / RH INNER X NN	2	\$	54.00	
30	REAR CROSS PANEL / DD		\$	329.00	262.80
31	REAR CROSS PANEL REINFORCEMENT / DD		\$	669.00	535.20
32	REAR FLOOR PAN (Spec type M) X DD R		\$	622.00	X
33	REAR LID TRIM PANEL / CRU		\$	284.00	227.20
34	REAR CROSS PANEL TRIM / CRU		\$	141.00	112.40
35	LUGGAGE COMPARTMENT FLOOR COVER / DR		\$	495.00	396
36	LED LICENSE PLATE LIGHT X NN	2	\$	105.00	
37	ACRYLIC SEALANT / MC	S/N	\$	180.00	180
38	CAVITY WAX / MC	S/N	\$	140.00	140
39	STONE CHIP / MC	S/N	\$	180.00	180
40	REAR NO PLATE X	S/N	\$	40.00	X NN
41	SUNDRIES ? / MC		\$	400.00	7.20

TOTAL SPARE PARTS : \$ 15,276.00
TOTAL LABOUR CHARGES : \$ 14,092.00
GRAND TOTAL : \$ 29,368.00

29,779

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

[Handwritten signature]
5/12/19

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Steve (LKK)

*00 - Not Authorised
EXCESS - ?*

10 days

P/P

Ry Del sy

4/12/19, 1-3pm

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 21329

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No.	:	6841 1183
Reference	:	PA/OD/1421/2019/NS
Date	:	3-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6221 2111

Owner's Name	:	Mr Teo Yat Seng
Address	:	3 Hume Avenue #07-04 Singapore 598719
Telephone	:	HP +65 98370772
Type of Claim	:	Own Damage Claim
Policy No.	:	2100403929-04
Vehicle No	:	SKR 6678 E
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	Feb-15
Engine No	:	CZC 209813
Chassis No	:	WAUZZZ8V6F1042870
Mileage	:	96345
Date In	:	2-Dec-19
Estimated By	:	Allan Wu
Accident Date	:	30-Nov-19
Place of Accident	:	Along PIE Before Bedok North Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays electrical and audio equipment.	S/N \$ 480.00 ✓	
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panel and spare wheel housing. Re-organise crash management components. Reinstall all parts removed. <i>500 x 6</i>	\$ 7,700.00 <i>3000</i>	
SUB TOTAL LABOUR CHARGES		: <u>\$ 8,740.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 6678 E

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To rep-spray rear bumper, rear lid, end panel and spare wheel housing. To carry out joint sealer works and stone chip treatment.		\$ 3,900.00	2200
6	To carry out stone chip primer work on rear panelling and spare wheel housing.	S/N	\$ 780.00	/
7	To remove and renew the rear exhaust silencer. To align to position.	S/N	\$ 480.00	? photo
8	to carry out diagnostic check.	S/N	\$ 192.00	/
TOTAL LABOUR CHARGES		:	<u>\$ 14,092.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	gloss/welder	6/12/19	Damage Parts & Prices	
				S/NETT	REMARKS
✓ 1	REAR BUMPER / DD			\$ 1,708.00	
2	REAR BUMPER FIXING PARTS ?			\$ 175.00	
✓ 3	REAR BUMPER GUIDE SECTION - LH / RH / DR		2	\$ 30.00	
4	REAR BUMPER LOCKING MECHANISM ?			\$ 53.00	
✓ 5	REAR BUMPER SPOILER - LH (100) / CRA			\$ 216.00	
✓ 6	REAR LIGHT REFLECTOR - LH / RH / CRA		2	\$ 76.00	
✓ 7	REAR BUMPER SIDE REINFORCEMENT BEAM ? / DD			\$ 522.00	
✓ 8	REAR BUMPER BRACKET - LH / RH / DR		2	\$ 24.00	
9	REAR BUMPER GUIDE SECTION - LH / RH ?		2	\$ 120.00	
✓ 10	REAR PARKING AID SENSOR - INNER / OUTER		4	\$ 924.00	
✓ 11	REAR PARKING AID SEAL RING / DR		4	\$ 12.00	
12	REAR BUMPER WIRING SET ?			\$ 472.00	
✓ 13	REAR LID / DD			\$ 2,417.00	
14	REAR LID ATTACHMENT PARTS ? X			\$ 267.00	
15	REAR LID HINGE - LH / TH ?		2	\$ 466.00	
16	FLAP GASKET ?			\$ 185.00	✓
✓ 17	BONNET LOCK STRIKER / BT			\$ 45.00	
✓ 18	REAR LID LOCK / CR BT			\$ 178.00	
✓ 19	REAR LOCK COVER / CR			\$ 7.00	
20	LIC LOCK PUSH BUTTON X			\$ 167.00	
SUB TOTAL SPARE PARTS				\$ 8,064.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	PROTECT CAP ?	4 \$	14.00
22	PACKING ADHESIVE / NK	\$	18.00
23	AUDI EMBLEM / NK	\$	113.00
24	A3 INSCRIPTION / NK	\$	87.00
25	TFSI INSCRIPTION / NK	\$	87.00
26	LED TAIL LIGHT - LH / RH OUTER / CH	21 \$	1,600.00
27	LED TAIL LIGHT TRIM - LH / RH OUTER / NK	2 \$	54.00
28	LED TAIL LIGHT - LH / RH INNER / CH	21 \$	1,600.00
29	LED TAIL LIGHT TRIM - LH / RH INNER X	2 \$	54.00
30	REAR CROSS PANEL / NK	\$	329.00
31	REAR CROSS PANEL REINFORCEMENT / NK	\$	669.00
32	REAR FLOOR PAN (Specialty pad) / NK	\$	622.00
33	REAR LID TRIM PANEL / CH	\$	284.00
34	REAR CROSS PANEL TRIM / CH	\$	141.00
35	LUGGAGE COMPARTMENT FLOOR COVER / NK	\$	495.00
36	LED LICENSE PLATE LIGHT X	2 \$	105.00
37	ACRYLIC SEALANT / NK	S/N \$	180.00
38	CAVITY WAX / NK	S/N \$	140.00
39	STONE CHIP / NK	S/N \$	180.00
40	REAR NO PLATE X	S/N \$	40.00
41	SUNDRIES ?	\$	400.00

SK-air
9/12
G66-v
9/12
SK-air
9/12
G66-v
9/12

TOTAL SPARE PARTS	:	\$ 15,276.00
TOTAL LABOUR CHARGES	:	\$ 14,092.00
GRAND TOTAL	:	\$ 29,368.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Steve (LKK)	OD - Not Author
Surveyed Date	:		EXCIS - ?
Authorised Date	:		10 days
Excess Cost	:		P/P
Liability	:		
Remarks	:		Ry BPL say

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Audi

ETKA - Order Form

Order Form:

SKR6678E-WIP21329

16:43

06.12.2019

Editor:

JERRY

Rg by LTKM

Item Description	Remark	Model	Qty	SGD	D
8V5 813 331 TB VIN: WAUZZZ8V6F1042870 Reinforcement for cross panel D - 30.09.2013>> Location : 1G06-B Stock : +1.00	(31)		1	669,00	
8V5 813 307 VIN: WAUZZZ8V6F1042870 Rear cross panel Location : 1G07-B-2 Stock : +2.00			1	328,50	
8V5 807 329 VIN: WAUZZZ8V6F1042870 Bracket Location : AA01-B-5 Stock : +8.00	left	PR-K8S	1	11,20	
8V5 807 330 VIN: WAUZZZ8V6F1042870 Bracket Location : AA01-B-6 Stock : +9.00	right	PR-K8S	1	11,20	
8V5 012 109 K VIN: WAUZZZ8V6F1042870 Stowage compartment Stock : 0	- S-PP		1	53,00	
8V0 863 503 B 4PK VIN: WAUZZZ8V6F1042870 Lashing eye soul (black) Stock : 0	- S-PP		1	20,90	
8V5 945 105 A VIN: WAUZZZ8V6F1042870 Rear light reflector Location : GG01-B-4 Stock : +8.00	left	PR-2JB	1	37,10	
4G5 827 797 VIN: WAUZZZ8V6F1042870 Stop Location : CC11-C-3 Stock : +2.00	outer - sundries		2	9,00	



Audi

ETKA - Order Form

Order Form:

SKR6678E-WIP21329

16:43

06.12.2019

Item Description	Remark	Model	Qty	SGD	D
4H0 827 520 VIN: WAUZZZ8V6F1042870 cover lock Location: BB01-B-1 Stock: +9,00			1	6,30	
4H0 827 505 A VIN: WAUZZZ8V6F1042870 Lid lock Location: BB01-B-3 Stock: +4,00			1	178,00	
8V5 867 975 G CA9 VIN: WAUZZZ8V6F1042870 Rear lid trim panel Black Location: 1D07-D10 Stock: 0	- supp.		1	284,00	
8V5 945 095 A VIN: WAUZZZ8V6F1042870 LED tail light Location: 1B02-E Stock: +2,00	left	PR-AV0,AV1+ BSK	1	800,00	
8V5 807 571 VIN: WAUZZZ8V6F1042870 Guide section Location: AA01-E-5 Stock: +10,00	left		1	14,30	
8V5 807 975 VIN: WAUZZZ8V6F1042870 Locking mechanism Location: AA03-B-2 Stock: +14,00	(side guide pin) - supp.		2	53,00	
8V5 863 463 G CA9 VIN: WAUZZZ8V6F1042870 luggage comp. floor covering Black Location: 1A08-B-2 Stock: 0	✓ (35) supp		1	495,00	
8V5 807 300 VIN: WAUZZZ8V6F1042870 side reinforcement Location: 1G06-C Stock: +10,00		PR-KBS+ID0, JMS	1	522,00	
8V5 807 521 B VIN: WAUZZZ8V6F1042870 Spoiler Location: 2B16-B Stock: +4,00	(Double pipe) left	PR-2JB+T37, TA8,TF5,TE8, TH1,T21	1	216,00	



Audi

ETKA - Order Form

Order Form:

SKR6678E-WIP21329

16:43

06.12.2019

Item Description	Remark	Model	Qty	SGD	D
SV5-807-067-A GRU VIN: WAUZZZ8V6F1042870 Bumper-cover primed Location: 2B05-D Stock: +6.00		PR-2JB-7X1, 7X2-	1	1708,00	
SV5 827 705 E VIN: WAUZZZ8V6F1042870 gasket for flap Location: 1D05-D-7 Stock: +3.00	- ? (16)		1	184,50	
				5601,20 392,08 5993,28 =====	SGD
			+ 7.0% VAT		

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6678 E

S/N	Parts Description	Qty	Unit	Damage Parts & Prices	
				S/NETT	REMARKS
✓	REAR BUMPER / DP			\$ 1,708.00	
2	REAR BUMPER FIXING PARTS ?			\$ 175.00	
✓	REAR BUMPER GUIDE SECTION - LH / RH / DR	2	\$	30.00	
4	REAR BUMPER LOCKING MECHANISM ?		\$	53.00	
✓	REAR BUMPER SPOILER - LH (100) / CRU		\$	216.00	
✓	REAR LIGHT REFLECTOR - LH / RH / CRA	2	\$	76.00	
✓	REAR BUMPER SIDE REINFORCEMENT BEAM ? / DP		\$	522.00	
✓	REAR BUMPER BRACKET - LH / RH / DR	2	\$	24.00	
9	REAR BUMPER GUIDE SECTION - LH / RH ?	2	\$	120.00	
✓	REAR PARKING AID SENSOR - INNER / OUTER	4	\$	924.00	
✓	REAR PARKING AID SEAL RING / R	4	\$	12.00	
12	REAR BUMPER WIRING SET ?		\$	472.00	
✓	REAR LID / DP		\$	2,417.00	
14	REAR LID ATTACHMENT PARTS ? X		\$	267.00	
15	REAR LID HINGE - LH / TH ?	2	\$	466.00	
16	FLAP GASKET ? / CRU		\$	185.00	
✓	BONNET LOCK STRIKER / BT		\$	45.00	
✓	REAR LID LOCK / CRU BT		\$	178.00	
✓	REAR LOCK COVER / CRU		\$	7.00	
20	LIC LOCK PUSH BUTTON X		\$	167.00	
SUB TOTAL SPARE PARTS				: \$ 8,064.00	