



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/12/2019
User ID : angbangklien

Section A - Accident Details	
Registration Number	SHD6481P
Case Reference Number	TAX/11/19/2141
Registration Date	29/12/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NEO CHIN BEE
Type of Accident	Head to Rear
Accident Date and Time	30/11/2019 12:58 PM
Accident Reported Date and Time	2/12/2019 11:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104651
Special Instruction to ARC, if any	DROVE IN/ LONPAC
Prepared Date and Time	3/12/2019 4:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$1,116.00	\$560.00
Total Spare Part Cost	\$4,445.01	\$3,108.85
Total Other Cost	\$480.00	\$120.00
TOTAL COST	\$6,548.01	\$4,188.85
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Ang Bang Klien	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	05/12/2019 2:47 PM	04/12/2019 4:09 PM
Signature		
Remarks		P/P repair, Take before spray photo.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/12/2019

User ID : angbangklien

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$400.00
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$80.00
TO RESPRAY REAR PANEL	\$180.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$560.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace / PD
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace / NEC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace / NEC
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.27	Replace	Replace / BT
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace / BT
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace / BT
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X SVC
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace / Short
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace / BR
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace / BR
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check X SVC
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check X SVC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check X SVC
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check X SVC
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace / CR4
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check X SVC
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Check X SVC
		58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace / PD
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace / NEC
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.92	Replace	Replace / PD

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/12/2019

User ID : angbangklien

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace / NPC
		75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace / NPC
			SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace / NPC
		69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace / Tumul
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace / NPC
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given X SVC
Total					\$5,481.40		\$3,108.85		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: